Susana Martinez Governor

Ken McQueen Cabinet Secretary

Matthias Sayer Deputy Cabinet Secretary

February 17, 2017

Merrion Oil & Gas Corp Attn: Philana P Thompson 610 Reilly Avenue Farmington, NM 87401-7401 David R. Catanach, Division Director Oil Conservation Division



Ms. Thompson:

On February 1, 2016, a memorandum was sent to your office at the above address requiring bradenhead tests for the year 2016, Area C. The reports were required to be submitted no later than November 1, 2016. Our well files indicate the required reports have not been submitted.

These reports are out of compliance with the Bradenhead Test Memorandum dated February 1, 2016. All wells have been pulled from the 3-year test cycle and put on a yearly test cycle. To place these wells back into their regular area test rotation Merrion Oil & Gas Corp. must retest the wells in compliance with the 2017 Bradenhead Test Memorandum.

Be advised, any additional wells showing non-compliance with the Bradenhead Test Memorandum may also be pulled from the three-year cycle and put into a one year test cycle.

If your wells do not have a bradenhead, a wellbore schematic is required to be submitted on all non-plugged wells without a bradenhead explaining reason for lack of bradenhead.

If you have any questions, you can reach me at 505-334-6178, ext. 123. Sincerely,

oure Kuchling

Monica Kuehling Deputy Oil & Gas Inspector District III, Aztec

CC: Well File BLM