Susana Martinez Governor

Ken McQueen Cabinet Secretary

Matthias Sayer Deputy Cabinet Secretary Heather Riley, Division Director Oil Conservation Division



New Mexico Oil Conservation Division approval and conditions listed below are made in accordance with OCD Rule 19.15.7.11 and are in addition to the actions approved by BLM on the following <u>3160-4 or 3160-5</u> form.

Operator Signature Date: 5/31/18 Well information:

			frmWellFilte	erSu	b								
API WELL #	Well Name	Well #	Operator Name	Туре	Stat	County	Surf_Owner	UL	Sec	Twp	N/S	Rng	W/E
	NORTHEAST BLANCO UNIT		BP AMERICA PRODUCTION COMPANY	G		San Juan	F	J	22	31	N	7	W

Application Type:

P&A	Drilling/Casing Change	Location Change
		Location onange

Recomplete/DHC (For hydraulic fracturing operations review EPA Underground injection control Guidance #84; Submit Gas Capture Plan form prior to spudding or initiating recompletion operations)

Other:

Conditions of Approval:

- Notify NMOCD 24hrs prior to beginning operations.
- Pump cement under the retainer on the first plug down to 2980' vertical depth plus 100% excess to ensure the Fruitland top at 2930' is properly isolated.

Seand the

NMOCD Approved by Signature

<u>8/17/18</u> Date

-	· · · ·						
	OR. NT	L	FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018				
SUNDRY		5. Lease Serial No. NMSF079003					
Do not use the abandoned we		6. If Indian, Allottee or Tribe Name					
SUBMIT IN		 7. If Unit or CA/Agreement, Name and/or No. 892000929B 8. Well Name and No. NEBU 406A 					
1. Type of Well Oil Well Gas Well Other							
2. Name of Operator BP AMERICA PRODUCTION		9. API Well No. 30-045-32412-00-S1					
 3a. Address 380 AIRPORT RD DURANGO, CO 81303 	3b. Ph Ph: 2	none No. (include area code) 281.892.5369		10. Field and Pool or Exploratory Area BASIN FRUITLAND COAL			
4. Location of Well (Footage, Sec., 7	., R., M., or Survey Description)			11. County or Parish,	State		
Sec 22 T31N R7W NWSE 13	75FSL 1375FEL		1	SAN JUAN CO	UNTY, NM		
12. CHECK THE AI	PPROPRIATE BOX(ES) TO IN	DICATE NATURE O	F NOTICE, F	REPORT, OR OT	HER DATA		
TYPE OF SUBMISSION		TYPE OF	FACTION				
Notice of Intent		Deepen		on (Start/Resume)	□ Water Shut-Off		
Subsequent Report		Hydraulic Fracturing	Reclamat		Well Integrity		
☐ Final Abandonment Notice		New Construction Plug and Abandon	Recomple	rily Abandon	□ Other		
Tinai Abandonment Notice		Plug Back	Water Di				
testing has been completed. Final Al determined that the site is ready for f	ect well. Please see the attached	after all requirements, includ	ing reclamation,	have been completed	and the operator has		
In accordance with NMOCD F operations.	Pit Rule 19.15.17.9 NMAC, BP wi	and the second se	0	prior to	IOCD 24 hrs beginning ations		
		AU	G 0 2 201	8			
		DIST	RICT I	11			
14. I hereby certify that the foregoing is	s true and correct. Electronic Submission #422088 For BP AMERICA PRODUCT mmitted to AFMSS for processing	TION COMPANY, sent to	o the Farming	ton			
Name (Printed/Typed) TOYA CC							
Signature (Electronic		Date 05/31/2		1			
	THIS SPACE FOR FE	DERAL OR STATE	OFFICE US	E			
Approved By_JACK SAVAGE	rant or						
ertify that the applicant holds legal or eq which would entitle the applicant to cond		Office Farming	ton				
itle 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S.C. Section 1212, make it a crime for statements or representations as to any n			ke to any department of	r agency of the United		
(Instructions on page 2)	ISED ** BLM REVISED ** BI			** BLM REVISE	:D **		

NMOCDA

Ŧ


PLUG AND ABANDONMENT PROCEDURE

May 28, 2018

NEBU #406A

Basin Fruitland Coal 1375' FSL & 1375' FEL, Section 22, T-31-N, R-7-W San Juan County, New Mexico / API 30-045-32412

- Note: All cement volumes use 100% excess outside pipe and 50' excess inside. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be Class G, mixed at 15.8 ppg with a 1.15 cf/sx yield.
 - Install and test location rig anchors. Comply with all NMOCD, BLM, and Operator safety regulations. MOL and RU daylight pulling unit. Conduct safety meeting for all personnel on location. Record casing, tubing and bradenhead pressures. NU relief line and blow down well. Kill well with water as necessary and at least pump tubing capacity of water down the tubing. ND wellhead and NU BOP. Function test BOP.
 - Rods: Yes , No X, Unknown.
 Tubing: Yes X, No , Unknown, Size 23/8", Length 3386'.
 Packer: Yes , No X, Unknown, Type .
 - 3. NOTE: BLM requires a CBL log to be run on all wells where the cement did not circulate to surface or a CBL log was not previously run. This procedure is prepared with the understanding that it may be modified based on the TOC from the CBL.
 - Plug #1 (5 ½" liner top, 2525' 2425'): Round trip 7" casing scraper or gauge ring to 2525' or deep as possible. RIH and set 7" CR at 2525'. Pressure test tubing to 1000#. Mix 29 sxs Class G cement inside casing to isolate 5 ½" liner top. PUH
 - Plug #2 (Kirtland and Ojo Alamo tops, 2353' 2125): Mix 54 sxs Class G cement inside casing from 2353' to 2125' to cover the Kirtland and Ojo Alamo tops. PUH.
 - Plug #3 (Nacimiento top, 775' 675'): Mix 29 sxs Class G cement inside casing from 775' to 675' to cover the Nacimiento top. PUH.
 - 7. Plug #4 (9-5/8" casing shoe, and surface, 344' 0'): Attempt to pressure test the bradenhead annulus to 300 PSI; note the volume to load. If the BH annulus holds pressure, then establish circulation out casing valve with water. Mix approximately 67 sxs Class G cement and spot a balanced plug from 344' to surface, circulate good cement out casing valve. TOH and LD tubing. If the I3H annulus does not test, then perforate at the appropriate depth and attempt to circulate cement to surface.
 - ND cementing valves and cut off wellhead. Fill annuli with cement as necessary. Install P&A marker to comply with regulations. Record GPS coordinate for P&A marker on tower report. Photograph P&A marker in place. RD, MOL and cut off anchors. Restore location per BLM stipulations



5-1/2" 15.5# liner set @ 3400'.

6.25" hole

TD 3422'



FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intention to Abandon:

. .

Re: Permanent Abandonment Well: NEBU 406A

CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."

2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.

- 3. The following modifications to your plugging program are to be made:
 - a) Combine plugs 1 and 2 (2525 2312) ft. to cover the Kirtland and Ojo Alamo tops. BLM picks top of Kirtland at 2493 ft. BLM picks top of Ojo Alamo at 2362 ft.
 - b) Set Plug 3 (914 814) ft. to cover the Nacimiento top. BLM picks top of Nacimiento at 864 ft.

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.