

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENTFORM APPROVED  
OMB NO. 1004-0137  
Expires: January 31, 2018**SUNDRY NOTICES AND REPORTS ON WELLS**  
*Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.*

NMOCD

JAN 03 2019

DISTRICT III

**SUBMIT IN TRIPLICATE - Other instructions on page 2**

1. Type of Well <input type="checkbox"/> Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other		5. Lease Serial No. NMSF077648
2. Name of Operator HILCORP ENERGY COMPANY Contact: PRISCILLA SHORTY E-Mail: pshorty@hilcorp.com		6. If Indian, Allottee or Tribe Name
3a. Address 1111 TRAVIS STREET HOUSTON, TX 77002	3b. Phone No. (include area code) Ph: 505.324.5188	7. If Unit or CA/Agreement, Name and/or No.
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Sec 11 T31N R12W NWNW 0990FNL 0790FWL 36.917587 N Lat, 108.070480 W Lon		8. Well Name and No. DAVIS 7
		9. API Well No. 30-045-10957-00-S1
		10. Field and Pool or Exploratory Area BASIN DAKOTA
		11. County or Parish, State SAN JUAN COUNTY, NM

**12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA**

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Hydraulic Fracturing	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input checked="" type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleate horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleation in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

Hilcorp Energy Company requests permission to recompleate the subject well in the Mesaverde and downhole commingle with the existing Dakota with the Mesaverde. Attached is the procedure, wellbore diagram and plat. A DHC application will be filed and approved prior to commingling. A closed loop system will be used.

**Notify NMOCD 24 hrs  
prior to beginning  
operations**

14. I hereby certify that the foregoing is true and correct. <b>Electronic Submission #444997 verified by the BLM Well Information System For HILCORP ENERGY COMPANY, sent to the Farmington Committed to AFMSS for processing by JACK SAVAGE on 12/18/2018 (19JWS0051SE)</b>	
Name (Printed/Typed) PRISCILLA SHORTY	Title OPERATIONS REGULATORY TECH
Signature (Electronic Submission)	Date 11/26/2018

**THIS SPACE FOR FEDERAL OR STATE OFFICE USE**

Approved By <u>JACK SAVAGE</u>	Title <u>PETROLEUM ENGINEER</u>	Date <u>12/18/2018</u>
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		Office <u>Farmington</u>

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

**\*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\***

NMOCD

**District I**

1625 N. French Dr., Hobbs, NM 88240  
Phone:(575) 393-6161 Fax:(575) 393-0720

**District II**

811 S. First St., Artesia, NM 88210  
Phone:(575) 748-1283 Fax:(575) 748-9720

**District III**

1000 Rio Brazos Rd., Aztec, NM 87410  
Phone:(505) 334-6178 Fax:(505) 334-6170

**District IV**

1220 S. St Francis Dr., Santa Fe, NM 87505  
Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico**  
**Energy, Minerals and Natural**  
**Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

Form C-102  
August 1, 2011

Permit 259843

**WELL LOCATION AND ACREAGE DEDICATION PLAT**

1. API Number 30-045-10957	2. Pool Code 72319	3. Pool Name BLANCO-MESAVERDE (PRORATED GAS)
4. Property Code 318488	5. Property Name DAVIS	6. Well No. 007
7. OGRID No. 372171	8. Operator Name HILCORP ENERGY COMPANY	9. Elevation 6211


**10. Surface Location**

UL - Lot D	Section 11	Township 31N	Range 12W	Lot Idn 4	Feet From 990	N/S Line N	Feet From 790	E/W Line W	County SAN JUAN
---------------	---------------	-----------------	--------------	--------------	------------------	---------------	------------------	---------------	--------------------

**11. Bottom Hole Location If Different From Surface**

UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County
12. Dedicated Acres 304.39	13. Joint or Infill			14. Consolidation Code			15. Order No.		

**NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION**

	<p align="center"><b>OPERATOR CERTIFICATION</b></p> <p><i>I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief, and that this organization either owns a working interest or unleased mineral interest in the land including the proposed bottom hole location(s) or has a right to drill this well at this location pursuant to a contract with an owner of such a mineral or working interest, or to a voluntary pooling agreement or a compulsory pooling order heretofore entered by the division.</i></p> <p>E-Signed By: <i>Priscilla Shorty</i> Title: Operations Regulatory Technician - Sr. Date: 11/19/2018</p>
	<p align="center"><b>SURVEYOR CERTIFICATION</b></p> <p><i>I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my belief.</i></p> <p>Surveyed By: Joe Salmon Date of Survey: 12/11/1961 Certificate Number: 578</p>



HILCORP ENERGY COMPANY  
DAVIS 7  
MESA VERDE RECOMPLETION SUNDRY

API #:

3004510957

JOB PROCEDURES

1. MIRU workover rig and associated equipment; NU and test BOP.
2. TOOH with 2 3/8" tubing set at 7,302'.
3. Set a 4-1/2" cast iron bridge plug at +/- 7175' to isolate the Dakota.
4. Load hole with fluid and run a CBL on the 4-1/2" casing. Verify cement bond within the Mesa Verde and confirm TOC. Review CBL results with BLM and NMOC. PT csq to 650 psi
5. Set a 4-1/2" cast iron bridge plug at +/- 5450' to provide a base for the frac
6. Perforate the Mesa Verde. (Top perforation @ 4321', Bottom perforation @ 5330')
7. RIH w/ frac string and packer with ceramic disc sub. Set pkr and land tbq.
8. N/D BOP, NU frac stack and test frac stack to frac pressure. Open well and PT tbq to 9000#
9. RU slickline. RIH and break ceramic disc. RD slickline
10. Frac the Mesa Verde in 1 stage.
11. RU flowback eqmt. Flowback well until tubing pressure drops to working level and sand subsides or well loads up. RD flowback eqmt.
12. MIRU workover rig. Nipple down frac stack, nipple up BOP and test.
13. Release pkr and POOH LD workstring
14. TIH with a mill and clean out to the top of the DK isolation plug at 7,175'. Take Mesa Verde gas samples and analyze
15. Drill out Dakota isolation plug and cleanout to PBTD of 7,353'. TOOH.
16. TIH and land production tubing. Get a commingled Dakota/Mesa Verde flow rate.





HILCORP ENERGY COMPANY  
DAVIS 7  
MESA VERDE RECOMPLETION SUNDRY

DAVIS 7 - CURRENT WELLBORE SCHEMATIC

