
Submit I Copy To Appropriate District State of New Mexico Form C-103 Office Energy, Minerals and Natural Resources Revised July 18, 2013 District 1 - (575) 393-6161 WELL API NO. 1625 N. French Dr., Hobbs, NM 88240 District 11 - (575) 748-1283 30-045-26256 OIL CONSERVATION DIVISION 811 S. First St., Artesia, NM 88210 5. Indicate Type of Lease District III - (505) 334-6178 1220 South St. Francis Dr. STATE 🛛 FEE 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe. NM 87505 District IV - (505) 476-3460 6. State Oil & Gas Lease No. 1220 S. St. Francis Dr., Santa Fe, NM LG-3045-1 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH 8. Well Number I. Type of Well: Oil Well Gas Well Other 2. Name of Operator 9. OGRID Number 006515 Dugan Production Corp. 10. Pool name or Wildcat 3. Address of Operator PO Box 420, Farmington, NM 87499-0420 Twin Mounds Fruitland Sand PC (88620) 4. Well Location Unit Letter H: 1850 feet from the North line and 940 feet from the East line Section 32 Township 30N Range 14W San Juan County 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 5479' GL 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK □ PLUG AND ABANDON  $\boxtimes$ REMEDIAL WORK ALTERING CASING P AND A TEMPORARILY ABANDON  $\Box$ **CHANGE PLANS** П COMMENCE DRILLING OPNS.□ П MULTIPLE COMPL CASING/CEMENT JOB **PULL OR ALTER CASING** DOWNHOLE COMMINGLE **CLOSED-LOOP SYSTEM** OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. Dugan Production Corp. plans to plug and abandon well as per the following procedure: 1) RIH w/2-7/8" plug. Set plug @ 893'. Load casing. Pressure test casing to 600 psi. 2 bbl cement circulated to surface during primary cement job. 2) Spot Plug I w/tubing from 893' to surface w/28 sks Class G cement w/2% CaCl2 (32.2 cu ft, 15.6#/gal, 1.15 cu ft/sk). Plug I 0-893', surface-Kirtland-Fruitland-PC. Notify NMOCD 24 hrs 3) Cut wellhead off. Tag TOC @ surface. prior to beginning 4) Install dry hole marker. Clean location. operations DISTRICT Rig Release Date: Spud Date: I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Engineering Supervisor DATE 4/17/19 Type or print name Aliph Reena E-mail address: aliph.reena@duganproduction.com PHONE: 505-325-1821 For State Use Only SUPERVISORATE 7/25/19 APPROVED BY: TITLE DIAKICA Conditions of Approval (if any):

## Planned P & A Schematic

Bi-Knobs # 1 30-045-26256 S32 T30N R14W 1850' FNL & 940' FEL Lat: 36.77286, Long: -108.32682



Spot Plug I from 893' to surface w/ 28 sks (32.2 Cu.ft) Class G cement. Plug I, Kirtland-Fruitland-Pictured Cliffs


2-7/8" 6.4 # casing @ 1046'. PBTD @ 1016'.

Set Plug @ 893'.

Pictured Cliffs Perfs @ 943'-954'

## **Current Wellbore Schematic**

Bi-Knobs # 1 30-045-26256 S32 T30N R14W 1850' FNL & 940' FEL Lat: 36.77286, Long: -108.32682



7", 20# casing @ 103'. Circulated cement to surface.

2-7/8" 6.4 # casing @ 1046'. PBTD @ 1016'.

Pictured Cliffs Perf; @ '943'-954'