Received by OCD: 9/18/2019 11:36:14 AM

	Submit 1 Copy To Appropriate District Office District I – (575) 393-6161	State of New Mexico Energy, Minerals and Natural Resources		Form C-103 Revised July 18, 2013	
	$\frac{District I}{1625 \text{ N}} = (575) \frac{595}{595} \frac{50101}{50101}$ $\frac{1625 \text{ N}}{1625 \text{ N}} \text{ French Dr., Hobbs, NM 88240}$ $\frac{District II}{505} = (575) \frac{748}{748} - 1283$			WELL API NO. 30-045-31137	
	<u>District II</u> = (575) 748-1285 811 S. First St., Artesia, NM 88210 District III = (505) 334-6178	OIL CONSERVAT		5. Indicate Type of Lease	
	1000 Rio Brazos Rd , Aztec, NM 87410	1220 South St Santa Fe, N		6. State Oil & Gas Lease No.	
	District IV - (505) 476-3460 Santa Fe, NM 1220 S. St. Francis Dr., Santa Fe, NM 87505		NMSF 078766		
	SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			7. Lease Name or Unit Agreement Name Rosa Unit	
	PROPOSALS.) 1. Type of Well: Oil Well Gas Well X Other			8. Well Number 139B	
	2. Name of Operator LOGOS Operating, LLC			9. OGRID Number 289408	
	3. Address of Operator 2010 Afton Place, Farmington NM 87401			10. Pool name or Wildcat Blanco Mesaverde / Basin Dakota	
4. Well Location					
	Unit Letter K		FSL line and	1885 feet from the <u>FWL</u> line	
	Section 17	Township 31N	Range 06W	NMPM County San Juan	
	11. Elevation (Show whether DR, RKB, RT, GR, etc.) 6404'				
	12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
	NOTICE OF	INTENTION TO:	SUE	SEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPI PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB					
	DOWNHOLE COMMINGLE				
	CLOSED-LOOP SYSTEM [OTHER:		OTHER:		
	13. Describe proposed or con		te all pertinent details, ar	ad give pertinent dates, including estimated date	
	of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
		ivision Order R-13122.			
Pools to be commingled: Blanco Mesaverde (72319) and Perforated Intervals:			and Basin Dakota (7159	9).	
Blanco Mesaverde: 5378' - 6286';					
Basin Dakota 8186' - 8337'			rde and 56% Rasin Dakota. This is based upon		
	Fixed percentage allocation based upon production data 44% Blanco Mesaverde and 56% Basin Dakota. This is based upon the historic production of both the Mesaverde and Dakota production zones within the well.				
K	Commingling will not reduce the value of reserves.				
		e spacing unit have not been noti ed on sundry notice form 3160-5		downhole commingle per order R-12991.	
	DHC#5062				
	Spud Date:	Rig Relea	se Date.		
	I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
	SIGNATURE	2 WILL_TITLE_	Regulatory Specialist	DATE 9/16/2019	
Type or print name <u>Marie E. Florez</u> E-mail address: <u>mflorez@logosresourcesllc.c</u> For State Use Only				sresourcesllc.comPHONE: <u>505-787-2218</u>	
	APPROVED BY: Kollen	st			
	Conditions of Approval (if any):	TITLE			



Down-hole Commingle Procedure

Rosa Unit 139B

1895' FSL & 1885' FWL Section 17, T31N, R06W San Juan County, New Mexico LAT: 36.897482° N LONG: -107.488231° W Mesaverde/Dakota

PROJECT OBJECTIVE:

Remove packer and commingle Mesaverde and Dakota.

WORKOVER PROCEDURE:

- 1. Hold safety meeting. MIRU workover rig. Place fire and safety equipment in strategic locations. Comply with all LOGOS, BLM and NMOCD rules and regulations.
- 2. Lay flow lines. Check and record casing and tubing pressures. RU blow lines from casing valves to rig pit. Kill well if necessary. Blow casing pressure down if necessary.
- 3. ND wellhead. NU BOP.
- 4. Release Mesaverde tubing string. TOOH scanning and visually inspecting string. Lay down joints with visible holes and red banded and green banded tubing joints.
- 5. Release Dakota tubing string. Determine if long string will pull and sting out of packer. TOOH scanning and visually inspecting string. Lay down joints with visible holes and red banded and green banded tubing joints.
- 6. RIH with packer plucker to retrieve Model D Packer at 6400'. TOOH with packer plucker assembly and string.
- 7. RIH with single tubing string.
- 8. Run standing valve on shear tool, load tubing and pressure test to 500 psig. Swab back fluid from PT and retrieve standing valve.
- 9. Swab well in to unload.
- 10. Return to production as a Mesaverde/Dakota commingle.

PRODUCTION ALLOCATION

Historic production data from both zones in this well was gathered and analyzed. Cumulative production was used to determine baseline allocations and baseline allocation was verified with recent average production history.

Cumulative Production

Total production from well	1,002.007 MMcf	
Total MV production	441.844 MMcf	
Total DK production	560.163 MMcf	

MV allocation = MV production/total production = 441.844/1,002.007 = **44%** DK allocation = DK production/total production = 560.163/1,002.007 = **56%**



