	Form 3160-5 June 2015) OCD Received 6/24/2020 DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.						FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018 5. Lease Serial No. NMSF077972 6. If Indian, Allottee or Tribe Name			
	SUBMIT IN TRIPLICATE - Other instructions on page 2							<ol> <li>If Unit or CA/Agreement, Name and/or No. NMNM73901</li> </ol>		
1	1. Type of Well □ Oil Well 🛛 Gas Well □ Other							8. Well Name and No. RICHARDSON COM 3		
2	2. Name of Operator LOGOS OPERATING LLC Contact: MARIE E FLOREZ E-Mail: mflorez@logosresourcesllc.com							9. API Well No. 30-045-06808-00-S1		
3	<sup>3a.</sup> Address 2010 AFTON PLAC FARMINGTON, NM	3b. Phone No. (include area code) Ph: 505-787-2218			10. Field and Pool or Exploratory Area BASIN DAKOTA					
4	4. Location of Well (Footage, Sec., T., R., M., or Survey Description)						11. County or Parish, State			
	Sec 2 T27N R13W SESW 1055FSL 1775FWL 36.599913 N Lat, 108.191482 W Lon							SAN JUAN COUNTY, NM		
_	12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA									
	TYPE OF SUBMISSIONTYPE OF ACTIO									
	□ Notice of Intent		□ Acidize	Hydraulic Fracturing		<ul> <li>Production (Start/Resume)</li> <li>Reclamation</li> </ul>		۱ ۵	Water Shut-Off	
MK	Subsequent Report		□ Alter Casing						Well Integrity	
Man			Casing Repair	_	New Construction Recomplete			⊠ ( Wo	Other orkover Operations	
	Final Abandonmen	t Notice	<ul> <li>Change Plans</li> <li>Convert to Injection</li> </ul>		-		□ Tempor □ Water D	arily Abandon		
13	3. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. Workover Operations - Bradenhead Repair									
1	14. I hereby certify that the foregoing is true and correct. Electronic Submission #516106 verified by the BLM Well Information System									
	For LOGOS OPERATIN				LC, sent to the Farmington JOE KILLINS on 05/28/2020 (20JK0391SE) Title REGULATORY SPECIALIST					
	Mane(1 funew 1 spea) WANTE E FLOREZ				T IIIC					
	Signature (Electronic Submission)				Date	05/20/20	20			
_			THIS SPACE FO	DR FEDER	AL OR S	STATE C	OFFICE U	SE		
	100						19			

Approved By ACCEPTED	JOE KILLINS <sub>Title</sub> ENGINEER	Date 05/28/2020
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Office Farmington	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions	on	page	2)	*
---------------	----	------	----	---

<sup>2/</sup> \*\* BLM REVISED \*\*

2/9/2020 ND BOP. Install new rubbers in tbg hanger. Pressure test, 7-10psi loss per min. PU packer set packer @ 5'. Pressure test above packer, 7-10 psi loss per min. LD Packer. Latch on to RBP @ 31'. LD TOOH, w/ casing scraper. Trip into 1990' & set RBP. TOOH. PU Packer & trip in @ 990'. Pressure test from packer to RBP. Good test. TOOH, to 630 & set packer. Pressure test f/ packer to RBP – Good test. TOOH, to 330 & set packer. Pressure test f/ packer to RBP – Good test. TOOH, to 30 & set packer. Pressure test f/ packer to RBP – Good test. TOOH to 15' then 4' & set packer. Pressure tested f/ packer to RBP- Good test. RU WL. Run CBL f/1927' to surface. Notified and received verbal approval from Brandon Powell (OCD) & Joe Killins by email (BLM) to perform a squeeze on the following well to fix a BH repair. Good cement coverage up to 300', per the CBL ran on 2/9/2020. LOGOS will perf above the shoe collar, +\- @ 278' and squeeze. RU Basin WL. Shoot 4SPF @ 278'. RD. Circulate down 4.5" out new shot holes to surface out of BH. RU Cement crew. Pumped 110sx. Displaced w/ 1.5bbls of H2O. Circulated good cmt to surface out of BH. Wash lines up. Winterize rig. WOC.

2/10/2020 Warm RU. Hook pump lines up and Circ., pump over pit. PU blade bit & RIH. Tagged TOC @ 79'. DO cmt f/79' to 280'. RIH, to 300'. Circulate. TOOH. TIH, w/ csg scraper. TOOH. TIH, w/ packer & test csg f/300' – 1990'. TIH w/ mule shoe. EOT @ 348'. LOGOS notified and received verbal approval from Brandon Powell (OCD) and Joe Killins (BLM) to perform a 2nd squeeze on the following well. The 1st squeeze did not take. LOGOS will perform a 2nd squeeze in the same area and spot a balance plug. Pumped 21sx of cmt. Displaced .75bbls of FW.TOOH, w/ tbg to 31'. Circ., & CO hole. PU packer & set 17'. Squeez 1.1bbls. Locked up and left 851psi on it. Winterize pumps. WOC.

2/11/2020 Warm RU. PU blade bit and tagged TOC @ 69'. PU swivel & drill collars. DO cmt f/69' - 104'.

2/12/2020 Continue to DO cmt f/ 140' to 357'. Circ., & CO hole. TOOH w/ bit & drill collars. PU packer & pubs. Performed MIT w/ NMOCD rep on location. Pressure to 560psi for 30 mins – Good test. TIH, w/ RBP retrieving tools. Tagged sand. Reverse sand from RBP. RD swivel. PU swabbing lubricator. Wabbed well. Latch RBP. Equalized well and released RBP. TOOH, w/ tbg. Kill well w/ 20bbls . TOOH, w/ tbg. LD RBP. LD drill collards. Change BOP rams to 2-1/16".

2/13/2020 Strap pipe & run 160jts of J-55 2-1/16" production tbg @ 6141', w/ mule shoe and seat nipple. ND BOP. NU WH RD.

On future sundry's include tubing weight and grade

