Form 3160-5 (June 2015)

OCD Received 7/7/2020

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

5. Lease Serial No. JIC101

## SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.

andoned well. Use form 3160-3 (APD) for such proposals.	6. If Indian, Allottee or Tribe Name JICARILLA APACHE	
SUBMIT IN TRIPLICATE - Other instructions on page 2	7. If Unit or CA/Agreement, Name and/or No.	
	0.337.11.31 1.31	

1. Type of Well	8. Well Name and No.	
☐ Oil Well    Gas Well    Other	HURON 1A	
2. Name of Operator Contact: ETTA TRUJILLO		9. API Well No.
HILCORP ENERGY COMPANY E-Mail: ettrujillo@hi	30-039-21511-00-S1	
3a. Address	3b. Phone No. (include area code)	10. Field and Pool or Exploratory Area
382 ROAD 3100 AZTEC, NM 87410	Ph: 505-324-5161	BLANCO
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		11. County or Parish, State
Sec 2 T26N R4W SWNW 1850FNL 0790FWL		RIO ARRIBA COUNTY, NM
Sec 2 12011 K4VV SVVINVV 1650FINL 0/90FVVL		RIO ARRIDA COUNTY, NIVI

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA						
TYPE OF SUBMISSION	TYPE OF ACTION					
<ul> <li>Notice of Intent</li> <li>Subsequent Report</li> <li>Final Abandonment Notice</li> </ul>	☐ Acidize ☐ Alter Casing ☐ Casing Repair ☐ Change Plans ☐ Convert to Injection	<ul><li>□ Deepen</li><li>□ Hydraulic Fracturing</li><li>□ New Construction</li><li>□ Plug and Abandon</li><li>□ Plug Back</li></ul>	☐ Production (Start/Resume) ☐ Reclamation ☐ Recomplete ☐ Temporarily Abandon ☐ Water Disposal	<ul><li>□ Water Shut-Off</li><li>□ Well Integrity</li><li>☒ Other</li></ul>		

Hilcorp Energy request permission to repair the bradenhead on the subject well per the attached procedure and current wellbore schematic.

14. I hereby certify that the foregoing is true and correct.  Electronic Submission #520815 verified by the BLM Well Information System  For HILCORP ENERGY COMPANY, sent to the Rio Puerco  Committed to AFMSS for processing by JOE KILLINS on 07/06/2020 (20JK0050SE)						
Name (Printed/Typed)	ETTA TRUJILLO	Title	OPERATIONS REGULATORY TECH S	3R		
Signature	(Electronic Submission)	Date	07/01/2020			
THIS SPACE FOR FEDERAL OR STATE OFFICE USE						
Approved By JOE KIL	LLINS	TitleF	PETROLEUM ENGINEER	Date 07/06/2020		
Conditions of approval, if a certify that the applicant he	any, are attached. Approval of this notice does not warrant or olds legal or equitable title to those rights in the subject lease plicant to conduct operations thereon.	Office	Rio Puerco	•		

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

<sup>13.</sup> Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.



## HILCORP ENERGY COMPANY HURON 1A BH Repair Sundry

## JOB PROCEDURES

1. PT test ports on WH (if test ports are available) to determine if the wellhead seals have integrity. If WH seals fail, pump filling into test ports to attempt to packoff WH seals and conduct another BH test and send results NMOCD/BLM/JICARILLA. If BH test passes after pumping packoff material into wellhead, conduct no further work. If BH test fails after pumping packoff material into wellhead, move to P&A. If initial PT on WH seals pass or test ports are not on the wellhead move to P&A the wellbore



## HILCORP ENERGY COMPANY HURON 1A BH Repair Sundry

