Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals. 5. Lease Serial No. NMNM99735 6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on page 2			7. If Unit or CA/Agreement, Name and/or No.	
Type of Well ☐ Oil Well ☐ Gas Well ☑ Other: COAL BED METHANE			8. Well Name and No. SYNERGY 21-7-8 132	
Name of Operator Contact: GLEN PAPP SYNERGY OPERATING, LLC E-Mail: gpapp@synergyoperating.com			9. API Well No. 30-043-21032-00-S1	
Ph:	Phone No. (include area code) : 505-599-4908 505-599-4900	10. Fi	10. Field and Pool or Exploratory Area BASIN FRUITLAND COAL	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			11. County or Parish, State	
Sec 8 T21N R7W NWNW 830FNL 970FWL 36.071322 N Lat, 107.605202 W Lon	NMOCD REC'D 9/29/20		SANDOVAL COUNTY, NM	
12. CHECK THE APPROPRIATE BOX(ES) TO I	INDICATE NATURE OF	NOTICE, REPO	ORT, OR OTHE	R DATA
TYPE OF SUBMISSION	TYPE OF ACTION			
□ Notice of Intent □ Acidize □ Alter Casing □ Casing Repair □ Final Abandonment Notice □ Change Plans	□ Deepen□ Hydraulic Fracturing□ New Construction☒ Plug and Abandon	□ Production (Start/Resume)□ Reclamation□ Recomplete□ Temporarily Abandon		☐ Water Shut-Off ☐ Well Integrity ☐ Other
BP Convert to Injection	☐ Plug Back	☐ Water Disposal	1	
Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. Synergy Operating LLC has completed the plugging of the wellbore in the subject well. Attached in a separate file are the follow documents: 1) Daily reports of the downhole plugging operations 2) Copy of the MIT(Mechanical Integrity Test) pressure chart Synergy plans to begin the surface reclamation procedure this fall and will notify the BLM's FFO prior to commencing field work.				
Electronic Submission #530149 verified by the BLM Well Information System For SYNERGY OPERATING, LLC, sent to the Farmington Committed to AFMSS for processing by JOE KILLINS on 09/21/2020 (20JK0720SE)				
Name(Printed/Typed) THOMAS MULLINS	Title ENGINE	ERING MANAGE	R/PARTNER	
Signature (Electronic Submission)	Date 09/15/20	9/15/2020		
THIS SPACE FOR F	EDERAL OR STATE O	FFICE USE		
Approved By ACCEPTED	JOE KILLIN Title ENGINEER	S		Date 09/21/2020
Conditions of approval, if any, are attached. Approval of this notice does not we certify that the applicant holds legal or equitable title to those rights in the subjective would entitle the applicant to conduct operations thereon.		on		
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.				

Synergy # 132 - Summary

8/18/20 - Synergy # 132

Notify NMOCD and BLM of planned MIT test. MIRU WSI Enterprises. Perform MIT test on 5-1/2" production casing and CIBP @ 632'. Test to 550#, slow bleed to 511# and chart for 30 mins. Good Test. Move to Synergy # 139

8/29/20 - MIRU 1'' Poly coil equipment. ND WH, GIH w/ 1'' poly coil with connection at 500' of roll, spool in the hole and tag up on CIBP at 632'. NU WH and fitting, ready for cement crew and cementing notification.

9/10/20 – BLM Representative Jimmie Dobson witnessing cement activity. MIRU Aztec Well Service Cementers. ND WH, NU Cementing Wellhead assembly for poly pipe. Dig out around wellhead with backhoe. Establish circulation with fresh water, pump 11.5 bbls Fresh Water Ahead, Pump 88 sacks total cement (103.84 ft3) at 15.6 ppg, circulate cement to surface. Cement Plug from 632' to Surface. ND WH. Welder Cut off wellhead below ground level. Check Surface cement depth at 26', Fill and Top off Cellar with cement. Wash Up Equipment. RD and Release Equipment to Synergy # 139 location.

