Form 3160-5 June 2015) UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT						FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018		
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.						 Lease Serial No. NMNM99735 If Indian, Allottee or Tribe Name 		
SUBMIT IN TRIPLICATE - Other instructions on page 2						7. If Unit or CA/Agreement, Name and/or No.		
1. Type of Well						8. Well Name and No.		
Oil Well Gas Well Other: COAL BED METHANE						SYNERGY 21-7-8 139		
2. Name of Operator SYNERGY OPERATING, LLC Contact: GLEN PAPP E-Mail: gpapp@synergyoperating.com						9. API Well No. 30-043-21034-00-S1		
3a. Address		3b. Phone No. (include area code) Ph: 505-599-4908			10. Field and Pool or Exploratory Area BASIN FRUITLAND COAL			
	ON, NM 87499 Vell (Footage, Sec., T	Fx: 505-599-4900			11. County or Parish, State			
	NR7W NWNE 710	NMOCD REC'D			SANDOVAL COUNTY, NM			
	N Lat, 107.595790	9/29/20						
12.	CHECK THE A	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE O	F NOTICE,	REPORT, OR OTH	IER DATA	
TYPE OF S	TYPE OF SUBMISSIONTYPE OF ACTION							
□ Notice of	Intent	□ Acidize	Deepen		□ Production (Start/Resume)		□ Water Shut-Off	
		□ Alter Casing	🗖 Hyd	raulic Fracturing	□ Reclamation		U Well Integrity	
Subsequent Report		_ • • • _		Construction	□ Recom		□ Other	
🗖 Final Aba	ndonment Notice BP	□ Change Plans ⊠ Plug and Ab □ Convert to Injection □ Plug Back			 Temporarily Abandon Water Disposal 			
If the proposal Attach the Bor following com testing has bee	l is to deepen direction nd under which the wo ppletion of the involved	eration: Clearly state all pertine ally or recomplete horizontally, rk will be performed or provide operations. If the operation re bandonment Notices must be fil inal inspection.	, give subsurface e the Bond No. or esults in a multip	locations and measu n file with BLM/BIA e completion or reco	red and true ve Required sub mpletion in a p	ertical depths of all pertin bsequent reports must be new interval, a Form 316	ent markers and zones. filed within 30 days 0-4 must be filed once	
Synergy Op	perating LLC has c	ompleted the plugging of	the wellbore	in the subject we	II.			
Attached in	a separate file are	the follow documents:						
1) Daily rep 2) Copy of t	orts of the downho the MIT(Mechanica	le plugging operations al Integrity Test) pressure	chart					
	ans to begin the su nmencing field wor	rface reclamation proced K.	ure this fall ar	nd will notify the I	BLM's FFO			
14. I hereby cert	ify that the foregoing is	Electronic Submission #	OPERATING,	LLĆ, sent to the I	Farmington	•		
Name(Printed/Typed) THOMAS MULLINS				Title ENGINEERING MANAGER/PARTNER				
Signature (Electronic Submission)				Date 09/15/2020				
		THIS SPACE FO	OR FEDERA		OFFICE U	SE		
Approved_By	ACCEPT		JOE KILLINS _{Title} ENGINEER			Date 09/21/2020		
Conditions of approval, if any, are attached. Approval of this notice does not w certify that the applicant holds legal or equitable title to those rights in the subje which would entitle the applicant to conduct operations thereon.				Office Farmington				
Title 18 U.S.C. Sec States any false, f	ction 1001 and Title 43 fictitious or fraudulent	U.S.C. Section 1212, make it a statements or representations as	crime for any post s to any matter w	erson knowingly and		ake to any department or	agency of the United	
(Instructions on pag	ge ²⁾ ** BLM REV	ISED ** BLM REVISE	D ** BLM RI	EVISED ** BLN		D ** BLM REVISE	D **	

Synergy # 139 – Summary

8/18/20 - Synergy # 139

Notify NMOCD and BLM of planned MIT test. MIRU WSI Enterprises. Perform MIT test on 5-1/2" production casing and CIBP @ 655'. Test to 530# and chart for 30 mins. Good Test. Release Testing Equipment.

8/29/20 - MIRU 1'' Poly coil equipment. ND WH, GIH w/ 1'' poly coil with connection at 500' of roll, spool in the hole and tag up on CIBP at 655'. NU WH and fitting, ready for cement crew and cementing notification.

9/10/20 – BLM Representative Jimmie Dobson witnessing cement activity. MIRU Aztec Well Service Cementers. ND WH, NU Cementing Wellhead assembly for poly pipe. Dig out around wellhead with backhoe. Establish circulation with fresh water, pump 11.5 bbls Fresh Water Ahead, Pump 90 sacks total cement (106.20 ft3) at 15.6 ppg, circulate cement to surface. Cement Plug from 655' to Surface. ND WH. Welder Cut off wellhead below ground level. Check Surface cement depth at 22', Fill and Top off Cellar with cement. Wash Up Equipment. RD and Release Equipment to Synergy # 131 location.

