Form 3160-5 (June 2015)

□ Subsequent Report

☐ Final Abandonment Notice

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

NMOCD REC'D 9/25/20

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

☐ Other

5. Lease Serial No. NMSF078771

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.

7. If Unit or CA/Agreement, Name and/or No.

6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on page 2				greement, Name and/or No. X	
Type of Well		8. Well Name and No. ROSA UNIT SWD 1			
2. Name of Operator Contact: MARIE E FLOREZ LOGOS OPERATING LLC E-Mail: mflorez@logosresourcesllc.com			9. API Well No. 30-039-27055	5-00-S1	
3a. Address 2010 AFTON PLACE FARMINGTON, NM 87401		3b. Phone No. (include area code) Ph: 505-787-2218		10. Field and Pool or Exploratory Area SWD MORRISON BLUFF ENTRADA	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 11. County or Parish, State				h, State	
Sec 23 T31N R6W NWSE 2420FSL 1210FEL RIO ARRIBA COUNTY, NM 36.884350 N Lat, 107.427190 W Lon			COUNTY, NM		
12. CHECK THE AF	PPROPRIATE BOX(ES)	TO INDICATE NATURE OI	F NOTICE, REPORT, OR O	THER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION				
Notice of Intent ■	☐ Acidize	☐ Deepen	☐ Production (Start/Resume)	☐ Water Shut-Off Well Integrity	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

☐ Plug Back

■ New Construction

□ Plug and Abandon

☐ Recomplete

■ Water Disposal

☐ Temporarily Abandon

LOGOS is requesting to perform a five year MIT test per the Salt Water Disposal Order(SWD)916.

***NMOCD- COA Schedule the Pressure test with Monica Kuehling. $\,B\!\!\!/\!\!\!\!/$

Casing Repair

□ Change Plans

☐ Convert to Injection

14. I hereby certify that the	ne foregoing is true and correct. Electronic Submission #530521 verifie For LOGOS OPERATING LI Committed to AFMSS for processing by J	LC, sen	t to the Farmington	
Name(Printed/Typed)	MARIE E FLOREZ	Title	REGULATORY SPECIALIST	
Signature	(Electronic Submission)	Date	09/17/2020	
Signature	,			
	THIS SPACE FOR FEDERA	IL OR	STATE OFFICE USE	
Approved By JOE KIL		Title E	NGINEER	Date 09/23/2020
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease		Office	Corminaton	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.



MECHANICAL INTEGRITY TEST- (2020)

Rosa Unit SWD 1
30-039-27055
2420' FSL & 1210' FEL
Sec 23, T31N, R06W
Rio Arriba County, Colorado
Lat 36.8845329° Long -107.4272766°
Morrison/Bluff/Entrada

PROJECT OBJECTIVE:

Top off the long string tubing-casing annulus with packer fluid. Rig up chart recorder and conduct mechanical integrity test.

WORKOVER PROCEDURE:

- Contact regulatory to ensure test has been scheduled with NMOCD.
- 2. Hold safety meeting. Comply with all LOGOS, BLM and NMOCD rules and regulations.
- 3. Top off the 3-1/2" x 7" tubing-casing annulus with packer fluid at least 24 hours before the pressure test.
- 4. Conduct preliminary pressure test to ensure packer is holding. Do not pressure up beyond 560 psig surface pressure.
- 6. Call out Wellcheck.
- 7. RU Wellcheck to chart pressure test as follows:
 - Top off with packer fluid, if needed
 - Pressure up the 3-1/2" x 7" tubing-casing annulus to 560 psig surface pressure
 - Record pressure on 1 hour chart with 1000 psig spring for 30 minutes
 - Contact engineer with results of pressure test
- 8. Bleed off pressure and release Wellcheck.



Wellbore Schematic

	Wonder Continue	20.0
Well Name:	Rosa Unit SWD #001	
Location:	Sec 23, T31N, R06W 2420' FSL & 1210' FEL	
County:	Rio Arriba	
API#:	30-039-27055	
Co-ordinates:	Lat 36.8845329 Long107.4272766	_
Elevations:	GROUND: 6243'	_
	KB: 6255'	
Denths (KR):	PRTD: 9140'	_

PBTD: 9140' TD: 9176'

Date Prepared:	10/15/2020 Gomez
Reviewed by:	10/21/2020 Moss
Spud Date:	6/28/2004
Completion Date:	10/28/2004
Last Workover Date:	12/4/2015

