

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

30-045-27442

**OPERATOR**

☒ Initial Report ☐ Final Report

Name of Company	ConocoPhillips Company	Contact	Kelsi Harrington
Address	3401 E. 30 <sup>th</sup> St., Farmington, NM 87402	Telephone No.	505-599-3403
Facility Name	San Juan 32-7 Unit 204	Facility Type	Gas Well API #3004527442
Surface Owner	State	Mineral Owner	State
		Lease No.	NME-503-13

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	36	32N	07W	815'	North	2005'	East	San Juan

Latitude 36.94148° N Longitude -107.51518° W

**NATURE OF RELEASE**

Type of Release – <b>Produced Water</b>	Volume of Release – <b>17 BBL</b>	Volume Recovered – <b>15 BBL</b>
Source of Release: <b>Water Tank</b>	Date and Hour of Occurrence <b>Unknown</b>	Date and Hour of Discovery <b>9/6/2011 2:30 P.M.</b>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour –	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\* **The water tank overflowed due to contractor error. Upon discovery, the well was shut in & a water truck was called to location.**

Describe Area Affected and Cleanup Action Taken.\* **All fluid was contained within the berm & approximately 15 BBL of fluid were recovered. COPC will assess the soils to determine if further action is needed.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Kelsi Harrington</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <b>Kelsi Harrington</b>	Approved by District Supervisor: <i>[Signature]</i>	
Title: <b>Environmental Consultant</b>	Approval Date: <b>10-18-11</b>	Expiration Date:
E-mail Address: <b>kelsi.g.harrington@conocophillips.com</b>	Conditions of Approval:	Attached <input type="checkbox"/>
Date: <b>9/23/2011</b> Phone: <b>505-599-3403</b>		

\* Attach Additional Sheets If Necessary

NJK1129255849

