

District I - (505) 393-6161

P.O. Box 1980

Hobbs, NM 88241-1980

District II - (505) 748-1283

811 South First

Artesia, NM 88210

District III - (505) 334-6178

1000 Rio Brazos Road

Aztec, NM 87410

District IV - (505) 827-7131

## State of New Mexico

## Energy Minerals and Natural Resources Department

## Oil Conservation Division

2040 South Pacheco Street


Santa Fe, New Mexico 87505

(505) 827-7131

Form C - 141

Originated 2/13/97

Submit 2 copies to  
Appropriate District  
Office in accordance  
with Rule 116 on  
back side of form



## Release Notification and Corrective Action

## OPERATOR

☐ Initial Report☒ Final Report

Name Conoco Inc.	Contact Shirley L. Ebert
Address 3315 Bloomfield Hwy ; Farmington, NM 87401	Telephone No. 505-324-5813
Facility Name San Juan 28-7 # 255	Facility Type Oil & Gas Production
Surface Owner Blm	Mineral Owner Blm
	Lease No. SF079289A

## LOCATION OF RELEASE

Unit Letter E	Section 15	Township 28N	Range 7W	Feet from the 1890'	North/South Line North	Feet from the 1130'	East/West Line East	County Rio Arriba
------------------	---------------	-----------------	-------------	------------------------	---------------------------	------------------------	------------------------	----------------------

## NATURE OF RELEASE

Type of Release Oil	Volume of Release 156 bbls	Volume Recovered 14.5
Source of Release SEPARATOR DUMP LINE / TANK	Date and Hour of Occurrence 3/16/00 UNKNOWN	Date and Hour of Discovery 3/16/00 2:30 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, to Whom? Not Required <input checked="" type="checkbox"/>	
By Whom? 1	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	

If a Watercourse was Impacted, Describe Fully. (Attach additional Sheets If Necessary)

Describe Cause of Problem and Remedial Action Taken. (Attach Additional Sheets If Necessary)

Someone had tampered with the dump in separator resulting in oil carrying over to water tank, filling tank & spilling over.

Describe Area Affected and Cleanup Action Taken. (Attach Additional Sheets If Necessary)

Reset dump mechanism on separator - vacuum truck recovered approximately 14 1/2 bbls of fluid - inside of burned pit will be dug out & landfilled on location

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state or local laws and/or regulations.

Signature: Shirley L. Ebert	OIL CONSERVATION DIVISION	
Printed Name: Shirley L. EBERT	Approved by: <i>Denny G. Zent</i>	District Supervisor: for Frank Chavez
Title: SHEAR SPECIALIST	Approval Date: 3/31/00	Expiration Date:
Date: 3/27/00	Phone: (505) 324-5813	Conditions of Approval: Attached

Not in computer  
WJK127336563