

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 South First, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
2040 South Pacheco  
Santa Fe, NM 87505

Form C-141  
Revised March 17, 1999

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

### Release Notification and Corrective Action

30-039-26203

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company <b>Williams Field Services</b>	Contact <b>Frank Barata</b>
Address <b>188CR 4900 Bloomfield NM 87413</b>	Telephone No. <b>505-632-4634</b>
Facility Name <b>Rosa #343</b>	Facility Type <b>Well</b>

Surface Owner	Mineral Owner	Lease No.
---------------	---------------	-----------

### LOCATION OF RELEASE

Unit Letter	Section <b>26</b>	Township <b>31N</b>	Range <b>5W</b>	Feet from the	North/South Line	Feet from the	East/West Line	County <b>Rio Arriba</b>
-------------	----------------------	------------------------	--------------------	---------------	------------------	---------------	----------------	-----------------------------

### NATURE OF RELEASE

Type of Release <b>Produced Water</b>	Volume of Release <b>10-15 bbl</b>	Volume Recovered <b>0</b>
Source of Release <b>Well</b>	Date and Hour of Occurrence <b>10/9/00 3 pm</b>	Date and Hour of Discovery <b>10/10/00 10:35 am</b>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

New well was put in and technicians underestimated the amount of water that would be produced. The well unloaded into a 320 bbl tank, consequently overflowing the tank. Truck was immediately called out to pump out the water.

Describe Area Affected and Cleanup Action Taken.\*

The bermed area was washed out. The produced water also ran across and off the location. A back hoe was called out to fix the berm.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <b>Clara M. Garcia</b>	OIL CONSERVATION DIVISION		
Printed Name: <b>Clara M. Garcia</b>	Approved by <b>Denny Font</b> District Supervisor: <b>for Frank Chavez</b>		
Title: <b>Compliance Administrator - Enve</b>	Approval Date: <b>10/12/00</b>	Expiration Date:	
Date: <b>10/10/00</b>	Phone: <b>505-634-4456</b>	Conditions of Approval	Attached <input type="checkbox"/>

\* Attach Additional Sheets If Necessary

Not in computer

NJK1217853750