Form 3160-5						FORM APPROVED	
(April 2004)					OMB NO. 1004-0137		
BUREAU OF LAND MANAGEMENT					Exertes March 31, 2007 5. Lease Serial No.		
SUNDRY NOTICES AND REPORTS ON WELLS 45678							
					5.7077383	6. If Indian, Allottee or Tribe Name	
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals,							
			E S	200 ~X			
SUBMIT IN TRIPLICATE - Other instructions on reverse Gide					7. If Unit or CA/Agreement, Name and/or No.		
1. Type of Well					9 Well Name o	nd No	
Oil Well X Gas Well Other					8. Well Name and No. FEDERAL GAS COM #1		
2. Name of Operator							
XTO Energy Inc.					9. API Well No.		
3a. Address 3b. Phone No. (include area code)					30-045-07196		
2700 Farmington Ave., Bldg. K. Ste 1 Farmington, 505-324-1090 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					10. Field and Pool, or Exploratory Area BASIN DAKOTA		
					DASLIV DARO	Tr.	
SEC 28A-T28N-R10W 1190' FNL & 1190' FEL					11. County or Parish, State		
		* .			SAN JUAN	NM	
12.	CHECK APPROPRIATE	BOY(ES) TO IN	NCATE NATURE C	ENOTICE RE			
TYPE OF SUBMISSION TYPE OF ACTION					N		
X Notic	e of Intent	Acidize	Deepen	Production	on (Start/Resume)	Water Shut-Off	
ليتنا		Alter Casing	Fracture Treat	Reclama	tion	Well Integrity	
Subsequent Report							
		Casing Repair	New Constructio		•	X Other SOZ CSG LK	
Final Abandonment Notice		Change Plans	Plug and Abando	n Tempora	arily Abandon		
		Convert to Injecti	on Plug Back	Water D	isposal		
Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.) XTO Energy Inc. received verbal permission to squeeze casing from Matt Halbert @ 2:00 p.m. & charlie Perrin w/NMOCD @ 2:15 p.m on 6/8/05. Casing leak is from 4009'-4138'. XTO plans to squeeze w/35 sx							
	-	_		_			
	+ 0.3% dispersant lea	_					
Inc. will submit a subsequent sundry when work is completed. Form C103 has been submitted to NMOCD							
requesting use of a workover pit for squeeze work and the pit will be closed in compliance w/NMOCD regulations when work is completed.							
regulacions	WHEN WOLK IS COMPLETE				0	005	
	*				070		
					T A		
				•	1 2 (E)	$\overset{\square}{\omega}$	
	\				ĭ	<u></u>	
					AINGT	 3	
	;				7 E		
					RECEIVED FARMINGTON	2	
	,				elice.	<u></u>	

14. I hereby certify that the foregoing is true and correct Name (Primed/Typed)

HOLLY C. DERKINS

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by Mall Hallard

Title

Date 6/9/05

Title

Date 1/6/as

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.