Form 3160-5* (August 2007)	orm 3160-5 August 2007) UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010 5. Lease Serial No. NMSF078828			
						6. If Indian, Allottee or Tribe Name EASTERN NAVAJO			
SUBMIT IN TRIPLICATE - Other instructions on reverse side.						<ol> <li>If Unit or CA/Agreement, Name and/or No. 892000844F</li> </ol>			
1. Type of Well □ Oil Well ⊠ Gas Well □ Other						8. Well Name and No. GALLEGOS CANYON UNIT 165E			
2. Name of Oper BP AMERI	ALLAH		9. API Well No. 30-045-26222-00-S1						
3a. Address 200 ENER FARMING	., R., M., or Survey Description	(include area code) 6-4632 10. Field and Pool, or UNNAMED 11. County or Parish,							
Sec 29 T28 36.628174	·		SAN JUAN COUNTY, NM						
	12. CHECK APPI	ROPRIATE BOX(ES) TO	O INDICATI	E NATURE OF 1	NOTICE, RI	EPORT, OR OTHE	R DATA	A	
TYPE OF SUBMISSION				TYPE OF ACTION					
Notice of		□ Acidize □ Alter Casing		ppen cture Treat	-	Production (Start/Resume) Reclamation		ater Shut-Off ell Integrity	
Subseque	nt Report	Casing Repair		v Construction		Recomplete		her	
·≷ □ Final Aba	indonment Notice	Change Plans	ge Plans 🛛 🗖 Plug		□ <sup>Tempor</sup>	arily Abandon			
		Convert to Injection	□ Plug Back □ Wate			Disposal			
13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration their lift he proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zo Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 day following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed or testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator had determined that the site is ready for final inspection.) BP America plans to recomplete the subject well (Recompletion Sundry was submitted and approved on 10/15/2012 EC154555), however in case of any casing failures or down-hole problems, BP requests permission to plug and abandon the entire wellbore. <b>CUD NOV 21 '12</b>								ters and zones. hin 30 days be filed once operator has	
Please see	the attached P&A	procedure and wellbore	diagrams. Th	is a contingency	plan in case		.0		
recompletion job fails. # Add Mancos plug from 4230'-4330' # Extend PC plug down to 1358' Notify NMOCD 24 hrs prior to beginning									
# Exten	Notify NMO prior to be operat	eginnlug							
14. Thereby cert	ify that the foregoing is	Electronic Submission #	A PRODUCTIC	N CO, sent to th	e Farmingtor	1		<u> </u>	
Name (Printed/Typed) RANAD ABDALLAH					-	RESENTATIVE			
Signature (Electronic Submission)				Date 11/14/2	2012				
		THIS SPACE FO	DR FEDER	AL OR STATE	OFFICE U	SE			
Approved By_STEPHEN MASON				TitlePETROLE		ER	I	Date 11/19/2012	
certify that the app	ed. Approval of this notice doe: uitable title to those rights in th uct operations thereon.	Office Farmington							
Title 18 U.S.C. Se States any false,	ction 1001 and Title 43 fictitious or fraudulent	U.S.C. Section 1212, make it a statements or representations as	a crime for any p s to any matter v	person knowingly an vithin its jurisdiction	d willfully to m	ake to any department of	agency of	of the United	

\*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED

NMOCD Av

## **BP - San Juan Wellwork Procedure**



# <u>GCU 165E</u> <u>30-045-26222</u>

Unit letter P SEC. 29, T28N, R12W 820' F2L, 920 FEL San Juan, NM Dakota Lease #: SF-078828 P&A date – TBD

#### **Basic Job Procedure:**

1. Pull tubing

2. Set CIBP @ 5830'

3. Spot 1003' plug from 4827'-5830' to Isolate Dakota and Gallup Formations

4. Set CIBP @ 3760\* 2271 2271 2171

5. Spot 1065' plug from-27702=3760' to isolate the Mesa Verde Formations

6. Set CIBP @ 1308'

7. Spot 460' plug from 825'-1308' to isolate the Fruitland and Pictured Cliffs Formations

8. Spot surface plug from 536' to surface


9. Install well marker and identification plate per regulatory requirements.

10. RD MO Location

Created by Neevia Document Converter trial version http://www.neevia.com


#### **GCU 165E**

# **Current Wellbore Diagram**



Created by Neevia Document Converter trial version http://www.neevia.com





Created by Neevia Document Converter trial version http://www.neevia.com

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intention to Abandon:

Re: Permanent Abandonment Well: 165E Gallegos Canyon Unit

#### CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."

2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.

3. The following modifications to your plugging program are to be made:

a) Place the Mesaverde plug from 2271' - 2171'.

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.