

Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR DEC 12 201: BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010

	DORUMO OF EMPLOYMENT	17 CODIVIDITI	_	Empireo:	5 d. , 5 d. , 2 d. d
Farmington Field (STERSE Serial No. NM-03402		
SUNDRY NOTICES AND REPORTS ON WELLS				6. If Indian, Allottee or Tribe Name	
	e this form for proposals t			o. If Malan, Photoco of Thou	vario
	well. Use Form 3160-3 (A				
SUBMIT IN TRIPLICATE - Other instructions on page 2.				7. If Unit of CA/Agreement, Name and/or No.	
1. Type of Well				San Juan 32-8 Unit	
Oil Well X Gas Well Other			8. Well Name and No.		
2. Name of Operator				San Juan 32-8 Unit 207 9. API Well No.	
ConocoPhillips Company				30-045-27447	
3a. Address		3b. Phone No. (include area code)		10. Field and Pool or Exploratory Area	
PO Box 4289, Farmington, NM 87499		(505) 326	-9700	Basin Fruitland Coal	
4. Location of Well (Footage, Sec., T.,I Surface Unit N (S	:\// Soc 22 T24	NI DOW	11. Country or Parish, State San Juan New Mexico		
Surface Unit N (SESW), 1125' FSL & 1850' FWL, Sec. 22, T31N, R8W				San Suan	, New Mexico
12. CHECK	THE APPROPRIATE BOX(ES)	TO INDICATE NAT	URE OF NOT	TICE, REPORT OR OTH	ER DATA
TYPE OF SUBMISSION TYPE OF AC				TION	
Notice of Intent	Acidize	Deepen		oduction (Start/Resume)	Water Shut-Off
	Alter Casing	Fracture Treat	==	eclamation	Well Integrity
X Subsequent Report	Casing Repair	New Construction	===	ecomplete	Other
17	Change Plans	X Plug and Abandon		emporarily Abandon	
Final Abandonment Metice	Convert to Injection	Plug Back	==	ater Disposal	
13. Describe Proposed or Completed Op	peration: Clearly state all pertinent deta	ils, including estimated s	starting date of an	v proposed work and approxim	ate duration thereof.
following completion of the involved Testing has been completed. Final determined that the site is ready for	work will be performed or provide the E red operations. If the operation results Abandonment Notices must be filed or final inspection.) &A'd on 12/1/12 per the at	in a multiple completion only after all requirements	or recompletion i	in a new interval, a Form 3160-	4 must be filed once
				R	CVD DEC 14'12
· · · · · · · · · · · · · · · · · · ·				t sant	DIL CONS. DIV. DIST. 3
•		•			
14. I hereby certify that the foregoing is	true and correct. Name (Printed/Type	ed)			
Dollie L. Busse			taff Regulate	ory Technician	
Signature	A Busse		12/12	,	
	THIS SPACE FO	R FEDERAL OR	STATE OFF	ICE USE	VIEW FOR RECORD
Approved by			1		
			Tin	Ū	NEC 1 3 2012
Conditions of approval, if any, are attack	hed. Approval of this notice does not v	varrant or certify	Title	FAFAAA	Date DOFFICE

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

Office

entitle the applicant to conduct operations thereon.

that the applicant holds legal or equitable title to those rights in the subject lease which would

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979

Farmington, New Mexico 87499 505-325-2627 *fax: 505-325-1211

Conoco Phillips San Juan 32-8 Unit 207 December 1, 2012

Page 1 of 1

1125' FSL and 1850' FWL, Section 22, T-31-N, R-8-W San Juan County, NM Lease Number: NM-03402 API #30-045-27447

Plug and Abandonment Report
Notified NMOCD and BLM on 11/26/12

Plug and Abandonment Summary:

- **Plug #1** pump 53 sxs (62.54 cf) Class B cement inside casing from 2910' to 2628' to cover the Fruitland coal tops.
- **Plug #2** pump 53 sxs (62.54 cf) Class B cement inside casing from 2195' to 1913' to cover the Kirtland and Ojo Alamo tops.
- Plug #3 with 56 sxs (66.08 cf) Class B cement inside casing from 840' to 540' to cover the Nacimiento top.
- Plug #4 with 117 sxs (138.19 cf) Class B cement from 240' to surface, circulate good cement out bradenhead and SIBH squeeze 8 sxs pressured up to 500 PSI to cover the surface casing shoe.
- Plug #5 with 40 sxs Class B cement found cement in 7" casing down 5' in annulus and install P&A marker.

Plugging Work Details:

- 11/27/12 Road rig and equipment to location. Spot A-Plus base beam. RU. Open up well; no pressures. SI well. ND 3" and 4" flowlines. NU 2" companion flange to casing valve. X-over to rods, PU on rods and LD horse head. SDFD.
- 11/28/12 Open up well; no pressures. PU on rods. Unseat pump. LD 1 polish rod, 1-4, 1-2 2-6 ¾" pony rods 119 ¾ rods 2-4′ pony, 6-1″ sinker, 1-4′ stabilizer, and 1 top hole down pump. X-over to 2-3/8″ tools. ND wellhead. NU 9″ x 7-1/16″ companion flange and BOP. Strip on companion flange and BOP due to bigger tubing hanger. POH. 1 joint 1-4′ sub, 100 joints, profile nipple and 1-20′ tail joint. 50 stands in derrick (3128′). 101 joints 2-3/8 EUE tubing. PU 1-7″ A-Plus casing scraper. Round trip to 2938′. SI well. SDFD.
- 11/29/12 Open up well; no pressures. PU 1-7" DHS CR. TIH to 2910' and set CR. Pressure test tubing to 1000 PSI, OK. Circulate well clean. Pressure test casing, leak. RU Basin Wireline. Ran CBL from 2910' to surface. Found TOC at 600' with stringers up to 240'. RD. ND BOP with companion flange and change out ring gasket. NU BOP and flange. Pressure test casing to 800 PSI, OK. PU 1-4' plugging sub. TIH to 2910'. SI well. SDFD.
- 11/30/12 Open up well; no pressures. Spot plugs #1, #2 and #3. Perforate 3 1-11/16" Bi-wire holes at 240'. ND BOP and companion flange. NU old wellhead. Establish circulation. Spot plug #4 with estimated TOC at surface. Dig out wellhead. SDFD.
- 12/1/12 Open up well; no pressures. Monitor well for gas. Issue Hot Work Permit. Cut off wellhead. Found cement in down 5' in casing and annulus. Spot plug #5 and install P&A marker.

Jamie Joe, BLM representative, was on location. Jim Yates, COPC representative, was on location.