	-				
71			RECEIV	/ED	
Form 3160-5 (February 2005)	DEPARTMENT C	) STATES DF THE INTERIOR ID MANAGEMENT	DEC 142	אַנ	FORM APPROVED OMB No. 1004-0137 xpires: March 31, 2007
			Farmington Field	1 -51 Lease Seria	l No.
		REPORTS ON WE			llottee or Tribe Name
		0-3 (APD) for such			
1. Type of Well	SUBMIT IN TRIPLICAT	E – Other instructions on	page 2.	7. If Unit of C Rosa Unit	A/Agreement, Name and/or No.
	🛛 Gas Well 🗌 O		8. Well Name and No. Rosa Unit #14C		
2. Name of Operator WPX Energy Production,			9. API Well No. 30-039-30132		
3a. Address 3b. Phone No. (include are			area code)	code) 10. Field and Pool or Exploratory Area	
PO Box 640Aztec,4. Location of Well (Footage2505' FNL & 895' FEL, sec	505-333-1806 Description)		Blanco MV / Basin DK 11. Country or Parish, State Rio Arriba		
12. CH	ECK THE APPROPRIAT	E BOX(ES) TO INDICATI	E NATURE OF NOTICE	, REPORT OR O	THER DATA
TYPE OF SUBMISSION			TYPE OF ACTION		
Notice of Intent	Acidize	Deepen Fracture Treat	Production (S	Start/Resume)	Water Shut-Off
Subsequent Report	Casing Repair	New Construction	Recomplete		Other <u>squeeze MC</u>
Final Abandonment Notic	ce Change Plans	Plug and Abandon	Temporarily		
all pertinent markers and subsequent reports must recompletion in a new in requirements, including	d zones. Attach the Bond u be filed within 30 days fo nterval, a Form 3160-4 mu reclamation, have been co	Inder which the work will b llowing completion of the i ist be filed once testing has impleted and the operator h	be performed or provide the nvolved operations. If the been completed. Final Ab as determined that the site	e Bond No. on fil operation results pandonment Notic is ready for final	•
<ul> <li><u>9/27/12</u> – MIRU HWS #6 to retrieve gauges, squeeze Mancos perforations, and with production tubing.</li> <li><u>9/28/12</u> – TOOH RBP and gauges at 6740'. TOOH RPB and gauges at 7010'.</li> </ul>					RCVD DEC 19112 DIL CONS. DIV.
<u>9/20/12</u> - 100H KBP	and gauges at or	40. TOOH RPB and	a gauges at 7010.		DIST. 3
<u>9/29/12</u> – Set 5-1/2" I good.	RTTS packer at 726	<i>r</i>		20' to 1000 ps	si for 5 minutes, test
9000.		(ZOL DKI	NUV)		
14. I hereby certify that the fore Name ( <i>Printed/Typed</i> ) Ben Mitchell	egoing is true and correct.	Ti	le Regulatory Specialist	··· <u>·</u> ····	
	TTO	Da	ate 12/12/12		
	THIS SPA	CE FOR FEDERAL		CE USE	
Approved by					
Conditions of approval, if any, certify that the applicant holds which would entitle the applica	se rights in the subject lease	Title Office	<u></u>	Date	
Title 18 U.S.C. Section 1001 at United States any false, fictition				ully to make to any	department or agency of the
(Instructions on page 2)			· · · · · · · · · · · · · · · · · · ·		TO MICH IN THE PARTY INTERPARTY IN THE PARTY IN THE PARTY IN THE PARTY IN THE PARTY INTERPARTY
		NMOC	D		DEC 17 2002
	<b>A</b>	Ŕ	* <b>, .</b>	P.	AFAINGTON FIELD OFFICE
	Copyright 2006 Forms	s in Word <u>(www.formsinword</u>	.com). For individual or sir	ngle-branch use on	ily,

· .

•

.

<u>10/1 thru 10/2/12</u> – Set easy drill CR at 7000'. Squeeze lower Mancos perforations with 50 sacks class C with 4% halide 9 cement 10.25 BBLS. Clean out casing with twister bit to 6770'. Set CR at 6770'. Cement with 55 sacks class G with 4% halide 9, 11 BBLS slurry.

10/4 thru 10/612 - Drill CR and cement from 6770' to 7158'. Test squeeze on Mancos. Test will not hold.

**10/8 thru 10/9/12** - TIH and set 5-1/2" CR at 6990' to try to squeeze the Mancos perforations again. Mix cement with 4.95 gals fresh water per sack of cement. Start down well with 10.25 bbls (50 sacks) of Class G cement w/ .4% H-9 and .2% HR-5 at 15.8 ppg, pump at a rate of 1 bpm at 1050 psi, displaced cement with 27 bbls of fresh water with a rate of 1 bpm at 1390 psi.

<u>10/10 thru 10/12/12</u> – TIH and drill out CR and cement from 6990' to 7291'. Set 5-1/2" packer at 6979'. Test squeeze on Mancos. Test will not hold.

<u>10/13/12</u> - MU 4"x 40' dump bailer, load bailer with 30 gal of 28% HCl acid, TIH and spot acid from 7170' to 7130', , TOOH with WL, load Bailer with 30 gal of 28% HCl acid, TIH and spot acid from 7100' to 7060'.

<u>10/15 thru 10/16/12</u> – TIH and set CR at 6780'. Mix cement w/ 4.95 gal per sack of fresh water, pump 15 bbls (75 sacks) of Type G cement with .4% Halad 9 and .2% HR-5 at 15.8 ppg w/ 1.15 yield. ; Pump cement displacement, pressure climbed to 2400 w/ .5 bpm at 19.5 bbls pumped, squeeze started at 20.5 bbls on displacement, pressure increased to 3500 psi w/ .2 bpm, well squeezed off at 21.5 bbls, tried multiple times to continue pumping off displacement, unable to pump anymore, 4.5 bbls of CMT left in tubing, 194' of cement left above retainer in 5.5" casing.

10/17 thru 10/19/12 - TIH and drill out CR and cement from 5987' to 7136'.

10/20 thru 10/25/12 - Rig repairs taking place.

<u>10/26/12</u> – TIH and set 5-1/2" packer at 6785' and RBP at 7008'. Test squeeze on Mancos. Test will not hold. TOOH with packer and RBP.


10/30/12 - RDMO HWS #6.

<u>11/28/12</u> – MIRU HWS #6 to land well as a MV only producing well. TIH and set Halliburton 5-1/2" WRP at 6010'. Dump bail approximately 10' of sand above WRP. Load well w/ 116 bbls of produced wtr, prsr test WRP to 500 psi with rig pump, monitor for 20 min w/ no leak off.

<u>11/29/12</u> – Land well at 5892' as follows: 1/2 MS, 1 joint of 2.375" J55, 4.7lb, 8rnd, EUE tubing, 1.78" FN set at 5862', 189 joints of 2.375" J55, 4.7lb, 8rnd, EUE tubing.

11/30/12 - RDMO HWS #6.

<u>Note:</u> This well has NOI approval to remove the monitoring equipment, squeeze the Mancos formation and return the well to production as a MV/DK commingle. Due to winter closure and troubles with the squeeze of the Mancos formation WPX has set plugs to isolate the three zones (see attached WB diagram) and will be producing only the MV through the winter.



HOLE SIZE	CASING	CEMENT	CU. FT.	CMT TOP
14 3/4"	10 3/4", 40.5#	280 s xs	395 cu.ft.	surface
9 7/8"	7 5/8", 26.4#	834 s xs	1681 cu.ft.	surface
6 3/4"	5 1/2", 17#	286 s xs	612 cu.ft.	1934'