Form 3160-5 UNITED STATES CAugust 2007) DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT			FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010 5. Lease Serial No.			
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.				SF-078161 6. If Indian, Allottee or Tribe Name		
เล่น ยัง โอเทซ์ เชิรเกอบูรเกียว SUBMIT IN TRIPLICATE - Other instructions on page 2. 1. Type of Well				7. If Unit of CA/Agreement, Name and/or No.		
Oil Well X Gas Well Other				8. Well Name and No. Lloyd B Com 100		
2. Name of Operator Burlington Resources Oil & Gas Company LP				9. API Well No. 30-045-34669		
3a. Address PO Box 4289, Farmington, NM 87499		3b. Phone No. (include are	(505) 326-9700		ool or Exploratory Area Basin Fruitland Coal	
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) Surface Unit F (SENW), 1650' FNL & 2014' FWL, Sec. 12			R11W	11. Country or Parish, State San Juan	, New Mexico	
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA						
TYPE OF SUBMISSION	E OF SUBMISSION TYPE OF AC			TION		
Notice of Intent X Subsequent Report	Acidize Alter Casing Casing Repair	Deepen Fracture Treat New Construction		Production (Start/Resume) Reclamation Recomplete	Water Shut-Off Well Integrity Other	
Final Abandonment Notice	Change Plans Convert to Injection	X Plug and Abandon Plug Back		Temporarily Abandon Water Disposal		
Attach the bond under which the v following completion of the involve	onally or recomplete horizontally, give work will be performed or provide the H ved operations. If the operation results I Abandonment Notices must be filed o	subsurface locations and m Bond No. on file with BLM/ in a multiple completion or	easured and to BIA. Require recompletion	rue vertical depths of all pertine ed subsequent reports must be f in a new interval, a Form 3160	ent markers and zones. Tiled within 30 days 0-4 must be filed once	
The subject well was P&A'd on 12/7/12 per the attached report.				RCVD JAN 10'13		
				!	OIL CONS. DIV.	
					DIST. 3	
14. I hereby certify that the foregoing is	s true and correct. Name (Printed/Type	ed)				
Dollie L. Busse	Title Sta	ff Regulat	ory Technician			
Signature MULA	Disse	Date	12/28	3/12		
	THIS SPACE FO	R FEDERAL OR S	ATE OF	ICE USE	WEPTED FOR FRECOR	
Approved by					JAN 08 2013	

entitle the applicant to conduct operations thereon. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify

that the applicant holds legal or equitable title to those rights in the subject lease which would

Title

Office

M

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979 Farmington, New Mexico 87499 505-325-2627 *fax: 505-325-1211

Burlington Resources Lloyd B Com 100

December 7, 2012 Page 1 of 1

1650' FNL and 2014' FWL, Section 12, T-29-N, R-11-W San Juan County, NM Lease Number: SF-078161 API #30-045-34669

Plug and Abandonment Report Notified NMOCD and BLM on 12/4/12

Plug and Abandonment Summary:

- **Plug #1** with 16 sxs (18.88 cf) Class B cement inside casing from 1778' to 1568' to cover the Fruitland Coal top.
- **Plug #2** with 19 sxs (22.42 cf) Class B cement inside casing from 935' to 685' to cover the Ojo Alamo and Kirtland top.
- Plug #3 with 32 sxs (37.76 cf) Class B cement 15 sxs (17.7 cf) in 4.5" casing, 17 sxs (20.06 cf) in annulus to cover the surface casing shoe.
- Plug #4 with 26 sxs Class B cement found cement at 11' to surface in 4.5" casing and annulus and install P&A marker.

Plugging Work Details:

- 12/4/12 Road rig and equipment to location. Spot in rig. SDFD.
- 12/5/12 Check well pressures: tubing 140 PSI, casing 295 PSI and bradenhead 0 PSI. RU relief lines. ND wellhead. NU BOP. Pressure test to 300 PSI for 15 minutes 1500 PSI for 15 minutes, OK. Pressure test bradenhead to 300 PSI, OK. Pull tubing hanger and install 2-3/8" stripping rubber and wipping rubber. Tally and TOH with 28 stands 2-3/8" tubing, LD 9 joints, 2' sub, 1 joint, F-nipple EOT at 2042'. PU 4.5" string mill. TIH with 28 stands and PU 2 joints to 1792'. LD 2 joints, TOH with 28 stands, LD 4.5" string mill. PU 4.5" DHS CR. TIH and set at 1778'. Pressure test tubing to 1000 PSI, OK. Establish circulation with 26 bbls. Pressure test casing to 800 PSI, OK. Spot plug #1 with estimated TOC at 1568'. SI well. SDFD.
- 12/6/12 Open up well; no pressures. RU Basin Wireline. Ran CBL from 1568' to surface with 500 PSI on casing. Found TOC at 41'. C. Perrin, NMOCD and S. Mason, BLM approved procedure change. TIH to 935'. Spot plug #2 with estimated TOC at 685'. Perforate 3 HSC holes at 35'. POH. Establish circulation, clean returns. Spot plug #3 with estimated TOC at surface. Pressure up to 300 PSI. SI well. Dig out wellhead. SDFD.
- 12/7/12 Open up well; no pressures. ND BOP. Perform and fill out Hot Work Permit. Cut off wellhead. Found cement at 11' to surface in 4.5" casing and annulus. Spot plug #4 and install P&A marker. RD & MOL.

Jim Morris, MVCI representative, was on location. Darrel Priddy, BLM representative, was on location.