

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office to
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Burlington Resources Oil & Gas Company	Contact Crystal Tafoya	
Address 3401 East 30th St, Farmington, NM	Telephone No. (505) 326-9837	
Facility Name: San Juan 30-6 Unit 31Y	Facility Type: Gas Well	
Surface Owner Fee	Mineral Owner Fee	API No. 30-039-26375

LOCATION OF RELEASE

Unit Letter D	Section 33	Township 30N	Range 6W	Feet from the 1205	North/South Line North	Feet from the 1300	East/West Line West	County Rio Arriba
-------------------------	----------------------	------------------------	--------------------	------------------------------	----------------------------------	------------------------------	-------------------------------	-----------------------------

Latitude **36.77302** Longitude **107.47244**

NATURE OF RELEASE

Type of Release Natural Gas	Volume of Release 24 mcf	Volume Recovered
Source of Release Rupture Disc	Date and Hour of Occurrence	Date and Hour of Discovery 12/11/2012 at 3:30pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* N/A		RCVD DEC 19 '12 OIL CONS. DIV. DIST. 3
Describe Cause of Problem and Remedial Action Taken.* Rupture disc popped due to flame failure and high side dump overpressure and stayed open due to freeze releasing 24mcf of Natural Gas.		
Describe Area Affected and Cleanup Action Taken.* Shut well in and repaired rupture disc and adjusted burner settings to prevent reoccurrence.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Crystal Tafoya	Approved by Environmental Specialist: 	
Title: Field Environmental Specialist	Approval Date: 1/23/2013	Expiration Date:
E-mail Address: crystal.tafoya@conocophillips.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 12/18/2012	Phone: (505) 326-9837	

* Attach Additional Sheets If Necessary

nJK1302333136