

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office to
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Burlington Resources Oil & Gas Company	Contact Crystal Tafoya
Address 3401 East 30th St, Farmington, NM	Telephone No. (505) 326-9837
Facility Name: Elliott Federal 22 1	Facility Type: Gas Well

Surface Owner BLM	Mineral Owner BLM (SF-078138)	API No. 30-045-09281
--------------------------	--------------------------------------	-----------------------------

LOCATION OF RELEASE

Unit Letter N	Section 22	Township 30N	Range 11W	Feet from the 860	North/South Line South	Feet from the 1620	East/West Line West	County San Juan
-------------------------	----------------------	------------------------	---------------------	-----------------------------	----------------------------------	------------------------------	-------------------------------	---------------------------

Latitude 36.79326 Longitude 107.98122

NATURE OF RELEASE

Type of Release Natural Gas	Volume of Release .049mcf	Volume Recovered
Source of Release Rupture Disc	Date and Hour of Occurrence 12/11/2012 at 9:00 am	Date and Hour of Discovery 12/11/12 at 10:37am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*
N/A

RCVD DEC 19 '12
OIL CONS. DIV.
DIST. 3



Describe Cause of Problem and Remedial Action Taken.*

Freeze resulted in overpressuring of the low pressure side of the HLP unit resulting in a gas release when the 1 1/2" safety rupture disc failed. .049mcf of natural gas was released.

Describe Area Affected and Cleanup Action Taken.*

Well was shut-in and blew down separator. Rupture disc was repaired. No further action will be taken.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Crystal Tafoya		Approved by Environmental Specialist: 	
Title: Field Environmental Specialist		Approval Date: <u>1/23/2013</u>	Expiration Date:
E-mail Address: <u>crystal.tafoya@conocophillips.com</u>		Conditions of Approval:	Attached <input type="checkbox"/>
Date: <u>12/18/12</u> Phone: <u>(505) 326-9837</u>			

* Attach Additional Sheets If Necessary

WJK1302332876