<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Form C-141 Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

т. т

Release Notification and Corrective Action													
		OPERA	ГOR			l Report	X	Final Report					
Name of Company Burlington Resources Oil & Gas, LP							Patsy Clugsto	n					
							No. 505-326-95	518					
Facility Name San Juan 30-6 Unit #57M							Facility Type Gas Well						
Surface Owner BLM Mineral Owner							Federal API No. 30-039-31092						
	1-												
· · · · · · · · · · · · · · · · · · ·							N OF RELEASE h/South Line Feet from the East/V		West Line County			· · · · · · · · · · · · · · · · · · ·	
		•	runge	r cet from the	1101111	South Bille				•		9	
D	30	T30N	R6W_	645'		North	835'	West		Rio Arriba		iba	
				Latitude: 36	5.7890 <u>9</u>	O Longitud	e: <u>107.51044</u>						
NATURE OF RELEASE													
Type of Release H2S							Volume of Release 300ppm Volume Recovered 0						
Source of Release encountered while drilling							Date and Hour of Occurrence: Date and Hour of Discovery 1/22/13 Date and Hour of Discovery						
Was Immediate Notice Given?							Whom?		11.43 am	·			
☐ Yes ☐ No ☐ Not Required													
By Whom? Jamie Goodwin						Date and Hour 1/22/13; 2:45 pm Followed up with an email @ 3:20 pm							
Was a Watercourse Reached?							If YES, Volume Impacting the Watercourse.						
☐ Yes ⊠ No							N/A RCVD JAN 25 '13						
If a Watercourse was Impacted, Describe Fully.*							OIL CONS. DIV.						
N/A					DIST. 3								
Describe Cause of Problem and Remedial Action Taken.*													
While drill the 12-1/4" surface hole on this new drill encountered H2S and LEL @ approx. 133'. Immediately stopped work and evacuated the location. DXP was called out to location and the H2S / LEL levels were read. All personnel were equipment with personal monitors and escape packs. Water was pumped down hole to kill any H2S. Changed over to mud drilling and finished drilling and cementing the surface casing. Note: BR will be writing up contingency plans for both the drilling and completion operations and they will be supplied to all field personnel and agencies. BLM was also given the volume discovered so that the basin H2S database can be updated.													
Describe Area	a Affected a	and Cleanup A	ction Tak	en.*									
Nothing to clean-up.													
regulations al public health should their o	I operators a or the environment. In acomment.	are required to onment. The ave failed to a ddition, NMO	report ar acceptance dequately CD accep	is true and completed of a C-141 report investigate and relations of a C-141 report tance of a C-141 relations.	lease no t by the mediate	otifications as NMOCD m contaminati	nd perform correct arked as "Final Ro on that pose a thro	tive act eport" d eat to g	ions for rele loes not relic round water,	ases which eve the oper surface wa	may en ator of ter, hur	danger liability man health	
000						OIL CONSERVATION DIVISION							
Signature: Patry lie St							$\sim 1/\sim 121/$						
							Approved by Environmental Specialist:						
							Approval Date: 30/2013 Expiration Date:						
E-mail Address: Patsy.L.Clugston@conocophillips.com						Conditions of Approval: Attached							
Date: 1-25-	-13	F	5-326-9518										

NJK1303027154

^{*} Attach Additional Sheets If Necessary