Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BURFALLOF LAND MANAGEMENT

JAN 25 2013

FORM APPROVED OMB No. 1004-0137

(August 2007)	DEFARTMENT OF THE			0. 1004-0157	
	BUREAU OF LAND MAN	NAGEMENT FREE MARGEON FI	Expires:	July 31, 2010	
•		Bureau of Land N	/ S. Lease Serial No.	Л-01772-A	
SUN	DRY NOTICES AND REPO	ORTS ON WELLS	6. If Indian, Allottee or Tribe N	Vame	
	e this form for proposals t well. Use Form 3160-3 (A				
SU	BMIT IN TRIPLICATE - Other ins	7. If Unit of CA/Agreement, Name and/or No.			
. Type of Well] · ··		
Oil Well	Gas Well Other		8. Well Name and No.		
				Reid 21	
2. Name of Operator			9. API Well No.		Ī
Burling	ton Resources Oil & Gas	Company LP	30-045-07301		
Ba. Address		3b. Phone No. (include area code)	10. Field and Pool or Explorate	ory Area .	
PO Box 4289, Farmingto	on, NM 87499	(505) 326-9700	Basin Dakota		
Location of Well (Footage, Sec., T., R	R.,M., or Survey Description)		11. Country or Parish, State		_
Surface UNIT L (NWS)	W), 1840' FSL & 930' FWL	, Sec. 19, T2/9N, R9W	San Juan	, New Mexico	
		8			_
12. CHECK T	THE APPROPRIATE BOX(ES)	TO INDICATE NATURE OF NO	OTICE, REPORT OR OTHE	ER DATA	
TYPE OF SUBMISSION		TYPE OF A	CTION		
X Notice of Intent	Acidize	Deepen	Production (Start/Resume)	Water Shut-Off	
	Alter Casing	Fracture Treat	Reclamation	Well Integrity	
Subsequent Report	Casing Repair	New Construction X	Recomplete	Other	_
	Change Plans	Plug and Abandon	Temporarily Abandon		_
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal		J
Describe Proposed or Completed Op	peration: Clearly state all pertinent det	tails, including estimated starting date o	f any proposed work and approxi	mate duration thereof.	_

If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

Plans are to recomplete this well in the Mesaverde formation and then DHC the existing Dakota with the Mesaverde. Attached is the MV plat and procedure. The DHC application will be submitted and approved before the work proceeds.

* Submit to ACENCIES For REVIEW PRIOR to perts

OIL CONS. DIV DIST. 3
JAN 3 0 2013

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) Denise Journey		Title	Regulatory Technician		
Signature	Derise Journey	Date		1/24/2013	
	THIS SPACE FOR FE	DERAL OR	STATE OFFICE USE		
Approved by	Original Signed: Stephen Mason		Title	Date JAN 2 8 2013	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			Office ·	,	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.



District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone: (575) 748-1283 Fax: (575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone: (505) 334-6178 Fax: (505) 334-6170
District IV


1220 S. St Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3470 Fax: (505) 476-3462

State of New Mexico

Energy, Minerals and Natural Resources

Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505 Form C-102 August 1, 2011

Permit 161013




JAN 25 2013

V	VELL LOCATION AND AC	REAGE DEDICATION PL	$_{ m AT}$ $_{-}$ Farmington Field O	
1. API Number 30–045–07301	2. Pool Code 72319	2. Pool Code 3. Pool Name		Samen
4. Property Code 18607	5. Property Name REID		6. Well No. 021	
7. OGRID No. 14538	8. Operator Name BURLINGTON RESOURCES OIL & GAS COMPANY LP		9. Elevation 5906	

10. Surface Location UL - Lot Section Township Range Lot Idn Feet From N/S Line Feet From E/W Line County S 930 W 19 28N 09W 1840 SAN JUAN L

11. Bottom Hole Location If Different From Surface N/S Line UL - Lot Lot Idn Feet From Feet From E/W Line Section Township Range County 14. Consolidation Code 15. Order No. 12. Dedicated Acres 13. Joint or Infill 302.28

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION



OPERATOR CERTIFICATION

I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief, and that this organization either owns a working interest or unleased mineral interest in the land including the proposed bottom hole location(s) or has a right to drill this well at this location pursuant to a contract with an owner of such a mineral or working interest, or to a voluntary pooling agreement or a compulsory pooling order heretofore entered by the division.

E-Signed By: Collins St. Regulatory Specialist

Date: 1/17/13

SURVEYOR CERTIFICATION

I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my belief.

Surveyed By: Ernest Echohawk Date of Survey: 9/8/1960 Certificate Number: 1545

Reid 21

Section 19, Township 28N, Range 9W

API#: 3004507301

Recomplete MV to Existing DK

01/15/13

Procedure:

- 1. MIRU service rig. TOOH with current production string.
- 2. MIRU wireline unit. RIH with a gauge ring for 4-1/2" 10.5#/ft casing. POOH.
- 3. RIH with a 4-1/2" CBP and set above Dakota Formation. POOH.
- 4. Pressure test casing to 600 psi.
- 5. Run a GR/CCL/CBL log from CBP' to surface. The CBL will be used to determine an accurate TOC and the GR will be used to determine formation tops.
- 6. Remedial cement work will be needed to cover Gallup and MV.
- 7. Pressure test squeeze holes to 600 psi. Set CBP over Gallup squeeze holes.
- 8. Perforate the Mesa Verde
- 9. Fracture stimulate the Mesa Verde.
- 10. Flow back frac on clean-up to a steel pit. RIH With wireline and set a composite bridge plug above top perf.
- 11. TIH with a mill and drill out top composite plug. Flow test MV.
- 12. Clean out to new PBTD and mill out CBP above squeeze holes and above Dakota. TOOH.
- 13. TIH and land production tubing. Flow test entire wellbore.
- 14. Release service rig and turn over to production.

Current Wellbore Diagram

