Form 3160-5 (August 2007)	DEPARTMENT OF TH		JAN	25	O13 FORM OMB N	APPROVED o. 1004-0137	
(3 =)	BUREAU OF LAND MA	NAGEMENT	Γ	1	Expires:	July 31, 2010	
					5. Lease(Serial No.	T 004005	
	SUNDRY NOTICES AND REF	RUE W WO STROY	eau or La	ind A.	் <u>சையென்</u> . S 6. If Indian, Allottee or Tribe 1	F-081085	
Do no	ot use this form for proposals						
aband	oned well. Use Form 3160-3 (APD) for suc	h proposa	als.			
	SUBMIT IN TRIPLICATE - Other in	structions on pag	je 2.		7. If Unit of CA/Agreement, N	lame and/or No.	
1. Type of Well				ļ			
Oil Well	X Gas Well Other	•			8. Well Name and No.	ater Federal 1	
2. Name of Operator					9. API Well No.	ater reuerar r	
	ConocoPhillips Comp	oany				045-08610	
3a. Address		3b. Phone No. (10. Field and Pool or Exploratory Area		
	nington, NM 87499	(505	326-9700	0		sin Dakota	
	ec., T.,R.,M., or Survey Description) (NWNW), 790' FNL & 790' FW	Sec 12 T2	9N R11W	,	11. Country or Parish, State San Juan	. New Mexico	
Curiace ONLI D	(14441444), 130 1142 @ 130 [441	-, 000. 12, 12	.514, 121144	'	oan odan	, 14C44 MCXICO	
12. CF	ECK THE APPROPRIATE BOX(E	S) TO INDICAT	E NATURE	OF NOT	ICE, REPORT OR OTH	ER DATA	
TYPE OF SUBMISSI		<u> </u>		OF AC			
						Water Cloud Off	
X Notice of Intent	Acidize Alter Casing	Deepen Fracture Tr	reat	=	oduction (Start/Resume) eclamation	Water Shut-Off Well Integrity	
Subsequent Report	Casing Repair	New Const		=	ecomplete	Other	
	Change Plans	Plug and A			emporarily Abandon		
Final Abandonment Not	 '	Plug Back	,		ater Disposal		
Testing has been completed determined that the site is represented the site is represented by the site	c involved operations. If the operation result. Final Abandonment Notices must be filed eady for final inspection.) complete this well in the Mesty plat and procedure. The Dh	only after all requi	irements, includ	ding reclan	nation, have been completed and the complete and	nd the operator has	
			·			OIL CONS. DIV DIST.	
* printo	perts submit Ch	91 fa.	Afencia.	, Re		JAN 3 0 2013	
14. I hereby certify that the for	egoing is true and correct. Name (Printed/I	yped)			Regulatory Tech	nician	
	Denise Journey	Ti	ile				
Signature	ist tourney	Da	ate		1/24/2013	3	
	THIS SPACE F	OR FEDERA	L OR STA	TE OFF	ICE USE		
Approved by							
*	iginal Signed: Stephen Maso	n		Vida		JAN 2 8 2013	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.



entitle the applicant to conduct operations thereon.

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would

Title

Office

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone: (575) 748-1283 Fax: (575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone: (505) 334-6178 Fax: (505) 334-6170
District IV

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462


12. Dedicated Acres

320.00 W

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

Form C-102 August 1, 2011

rugust i, 2011



JAN 25 2013

			WELI	L LOCAT	TION AN	D ACREAC	GE DEDIC	ATION PL	AT Puros	mingion Fic.s C <u>u of Lend Wan</u> a
045-08	1. 610 30-0 4	API Number 45–0861 (,	2. Pool Code 72319			3. Pool Name BLANCO-MESAVERDE (PRORATED GAS)			
	4. Property Code 31656 7. OGRID No. 217817			5. Property Name TIDEWATER FEDERAL			6. Well No. 001			
				8. Operator Name CONOCOPHILLIPS COMPANY			·	9. Elevation 5776		
					10. 9	Surface Loc	ation			
	UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County
	D	12	29N	11W		790	N	790	W	SAN JUAN
			. 1	1. Bottom	Hole Lo	cation If Di	fferent Fro	m Surface		
	UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION

14. Consolidation Code

13. Joint or Infill

OPERATOR CERTIFICATION

15. Order No.

I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief, and that this organization either owns a working interest or unleased mineral interest in the land including the proposed bottom hole location(s) or has a right to drill this well at this location pursuant to a contract with an owner of such a mineral or working interest, or to a voluntary pooling agreement or a compulsory pooling order heretofore entered by the division.

E-Signed By:

Title: Sr. Regulatory Specialist

Date: 11/17/13

SURVEYOR CERTIFICATION

I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my belief.

Surveyed By: James P. Leese Date of Survey: 5/11/1964 Certificate Number: 1463

Tidewater Federal 1

Section 12, Township 29N, Range 11W

API#: 3004508610

Recomplete MV to Existing DK

01/14/13

Procedure:

- 1. MIRU service rig. TOOH with current production string.
- 2. MIRU wireline unit. RIH with a gauge ring for 4-1/2" 10.5#/ft casing. POOH.
- 3. RIH with a 4-1/2" CBP and set above Dakota Formation. POOH.
- 4. Pressure test casing to 600 psi.
- 5. Run a GR/CCL/CBL log from CBP' to surface. The CBL will be used to determine an accurate TOC and the GR will be used to determine formation tops. Remedial cement work will be completed as needed.
- 6. Perforate the Point Lookout.
- 7. Fracture stimulate the Point Lookout. Set CFP over Point Lookout
- 8. Perforate Menefee.
- 9. Fracture Stimulate the Menefee.
- 10. Flow back frac on clean-up to a steel pit. RIH With wireline and set a composite bridge plug above top perf.
- 11. TIH with a mill and drill out top composite plug. Flow test MV.
- 12. Clean out to new PBTD and mill out CBP above Dakota. TOOH.
- 13. TIH and land production tubing. Flow test entire wellbore.
- 14. Release service rig and turn over to production.

Current Wellbore Diagram

