

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR ☐ Initial Report ☒ Final Report

Name of Company: ConocoPhillips Company	Contact: Ashley Maxwell	
Address: 3401 E. 30th St., Farmington, NM 87402	Telephone No. 505-324-5169	
Facility Name: Hamner 1A	Facility Type: Gas Well	
Surface Owner: Federal	Mineral Owner: Federal	API No.: 3004525327 Lease # SF-080245

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	20	29N	09W	1190'	South	2130'	East	San Juan

Latitude 36.706949 N Longitude -107.79907 W

NATURE OF RELEASE

Type of Release: Gas Release with Hydrocarbon	Volume of Release 53 mcf 0.5 Gal hydrocarbon	Volume Recovered - 0-
Source of Release: Lubricator	Date and Hour of Occurrence: 11/22/2012 @ 2:00PM	Date and Hour of Discovery: 11/23/2012 @ 12:15PM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? RCVD DEC 6 '12 OIL CONS. DIV. DIST. 3	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

Lubricator cap became loose causing the release of 53 mcf and 0.5 gallons hydrocarbon. No volume was recovered. Lubricator cap was reinstalled and simple green was applied and raked into hydrocarbon impacted soil.

Describe Area Affected and Cleanup Action Taken.*

Lubricator cap was reinstalled and simple green was applied and raked into hydrocarbon impacted soil.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name Ashley Maxwell		Approved by Environmental Specialist: 	
Title: Field Environmental Specialist		Approval Date: 2/1/2013	Expiration Date:
E-mail Address: ashley.p.wethington@conocophillips.com		Conditions of Approval:	Attached <input type="checkbox"/>
Date: December 3, 2012 Phone: 505-324-5169			

* Attach Additional Sheets If Necessary

njk 130420541