		RECE	]\/[	ED	
Form 3160-5	UNITED STATES		י ער ג 		PPROVED
(August 2007)	DEPARTMENT OF THE INTE	ERIOR IAN 18	x 201	OMB No.	1004-0137
	DEPARTMENT OF THE INTE BUREAU OF LAND MANAGE				ly 31, 2010
		Farmington F	ield	Jiffice SF	-080117
SU	NDRY NOTICES AND REPORTS	ON WELLS Land	Man	6. If Indian, Allottee or Tribe Na	me
	e this form for proposals to dril. I well. Use Form 3160-3 (APD) fo				
	UBMIT IN TRIPLICATE - Other instruction		<u>.</u>	7. If Unit of CA/Agreement, Nai	ne and/or No
1. Type of Well		<u></u>		•	fanito Unit
Oil Well	X Gas Well Other			8. Well Name and No.	
2. Name of Operator	· · · · · · · · · · · · · · · · · · ·			9. API Well No.	iito Unit 74R
	gton Resources Oil & Gas Comp				5-33739
3a. Address PO Box 4289, Farming		one No. (include area code (505) 326-9700	2)	10. Field and Pool or Explorator Basi	n Dakota
4. Location of Well (Footage, Sec., T.				11. Country or Parish, State	······································
Surface Unit A, 665'	FNL, 1165' FEL, Sec. 34, T27N, F	R9W		Rio Arriba ,	New Mexico
12. CHECK	THE APPROPRIATE BOX(ES) TO IN	DICATE NATURE O	F NO	I TICE, REPORT OR OTHE	R DATA
TYPE OF SUBMISSION		TYPE O	F AC	TION	
X Notice of Intent	Acidize De	eepen	P	roduction (Start/Resume)	Water Shut-Off
	Alter Casing	acture Treat	🗌 R	eclamation	Well Integrity
Subsequent Report		ew Construction		ecomplete	Other
		ug and Abandon		emporarily Abandon	<u> </u>
Final Abandonment Notice	Deperation: Clearly state all pertinent details, inc	ug Back		Vater Disposal	
determined that the site is ready	al Abandonment Notices must be filed only after or final inspection.) te this well in the Mesaverde for		_		
	t and procedure. The DHC appl				re the work proceeds.
- Conduct	MIT and pro	ovide res	sul	ts prior to	commencing
recon	Lation operatu	. Are			
					ROVD JAN 31 13
					OIL CONS. DIV.
					uii Muine Piva
					DIST. 3
14 Therefore and Control of Control					
14. Thereby certify that the foregoing	is true and correct. Name (Printed/Typed)	Title		Sr. Regulatory Spe	cialsit
$ \longrightarrow  $	Patsy Clugston	Title			
Signature	ur lucat	Date		1/18/2013	
	/ THIS SPACE FOR FE	DERAL OR STATE	E OFF	FICE USE	
Approved by	Λ ,		~	· · · · · · · · · · · · · · · · · · ·	
	mbrato	Title	e F	Etr. En.	Date 1/30/13
	ached. Approval of this notice does not warran		,	3	t (
entitle the applicant holds legal or equita	ble title to those rights in the subject lease whit ions thereon.	ch would Offi	ce		•
Title 18 U.S.C. Section 1001 and Titl	e 43 U.S.C. Section 1212, make it a crime for a		willfull	y to make to any department or a	gency of the United States any
	ts or representations as to any matter within its	jurisdiction.			
(Instruction on page 2)					

÷

NMOCD (	∕
---------	---

District I 1625 N. French Dr., Hobbs, NM 88240	State of	New Mexico	Form C-102 August 1, 2011
Phone:(575) 393-6161 Fax:(575) 393-0720 <u>District II</u> 811 S. First St., Artesia, NM 88210	Energy, Minerals	and Natural Resources	Permit 159612
Phone: (575) 748-1283 Fax: (575) 748-9720 District III	Oil Conser	vation Division	
1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170	1220 S. S	it Francis Dr.	RECEIVED
<u>District IV</u> 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462	Santa F	e, NM 87505	JAN 18 2013
WELL	LOCATION AND ACRE	AGE DEDICATION PLAT	
1. API Number	2. Pool Code	3. Pool Name	armington Field Office

1. API Number <b>30–045–33739</b>	2. Pool Code 72319	3. Poo BLANCO-MESAVERI	Bureau of Land Manag DE (PRORATED GAS)
4. Property Code 7138	5. Property 1 HUERFANIT		6. Well No. 074R
7. OGRID No. 14538	8. Operator 1 BURLINGTON RESOURCES O		9. Elevation 6456

#### **10. Surface Location**

			•	10.5	at mee Boe				
UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County
A	34	27N	09W	-	665 -	N	1165	E	SAN JUAN

### 11. Bottom Hole Location If Different From Surface

UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S L	ine	Feet From	E/W Line	County
12. Dedica 320.		13. J	loint or Infill		4. Consolidation	Code		· ·	15. Order No.	

## NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION

No. 1 Alexandre
State Base

#### **OPERATOR CERTIFICATION**

I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief, and that this organization either owns a working interest or unleased mineral interest in the land including the proposed bottom hole location(s) or has a right to drill this well at this location pursuant to a contract with an owner of such a mineral or working interest, or to a voluntary pooling agreement or a compulsory pooling order heretofore entered by the division.

E-Signed B Lichnician Title: Keg Date: 12/18/12

# SURVEYOR CERTIFICATION


I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my belief. Surveyed By: Jason Edwards Date of Survey: 3/1/2006 Certificate Number: 15269

#### Huerfanito Unit #74R

Section 34-T27N-R09W API #: 3004533739

## **MV Recompletion Procedure**

- 1. MIRU. Check casing, tubing and Braden head pressures. RU Gas Recovery Unit and flare stack. Blow down well, killing with 2% KCl as necessary.
- 2. ND Well head and NU BOP.
- 3. TOOH with tubing.
- 4. Wireline set CBP at 6,000' in 4-1/2", 11.6#, N-80, LT&C Production Casing. TOC (from CBL) at 800'.
- 5. Load hole with 2% KCL.
- 6. RU wireline company. Run CCL, Neutron & GR log.
- 7. Perforate PLO.
- 8. Rig up Frac Equipment.
- 9. Frac Point Lookout with 70Q foam.
- 10. Set CFP above top Point Lookout perf.
- 11. Perforate Menefee.
- 12. Frac Menefee with 70Q foam.
- 13. Set CBP
- 14. Rig down Frac equipment and wireline.
- 15. Drill out CFP's and CBP. Clean out hole.
- 16. Run production string.
- 17. ND BOP, NU Wellhead. RDMO.



-

Page 1/1