Form 3160-5 (March 2012)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

RECEIVED

FORM APPROVED OMB No. 1004-0137 Expires: October 31, 2014

JAN 22 201 5. Lease Serial No.

NMNM105187

SUNDRY NOTICES AND REPORTS ON WELLS

Farmington Field Configuration, Allottee or Tribe Name

Do not use this form for proposals to drill or to re-enter an or Land Management.

Supplied to the proposals of the proposals of the proposals of the proposals of the proposals.

abandoned well. Use Form 3160-3 (APD) for such proposals.							
SUBMIT IN TRIPLICATE – Other instructions on page 2.					7. If Unit of CA/Agreement, Name and/or No.		
1. Type of Well Oil Well Gas Well Other Dry Hole 2. Name of Operator High Plains Petroleum Corporation					8. Well Name and No. SI Federal 27 #1 9. API Well No. 30-043-21121		
			(include area co	ode)	10. Field and Pool or Exploratory Area San Isidro Mesaverde		
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) 2310' FSL & 2310' FEL, Sec. 27, T20N, R3W, NMPM					11. County or Parish, State Sandoval County, New Mexico		
12. CHEC	CK THE APPROPRIATE BO	OX(ES) TO IND	ICATE NATUR	E OF NOTIC	E, REPORT OR OTH	ER DATA	
TYPE OF SUBMISSION TYPE OF ACT					ION		
✓ Notice of Intent	Acidize Alter Casing		ire Treat	Recla	uction (Start/Resume)	Water Shut-Off Well Integrity	
Subsequent Report Final Abandonment Notice	Change Plans Convert to Injection		Construction and Abandon Back	Temp	mplete oorarily Abandon r Disposal	Other	
testing has been completed. Final determined that the site is ready for Plug and abandon as follows: (1) Cap the CIBP @ 2510' w (2) Set a cmt. plug from 215 (3) Set a cmt. plug from 50' it (4) Set a cmt. plug from 100 (5) Install a dryhole marker, it (6) Close the pit; (7) Restore the wellsite to its (8) Reseed; and	work will be performed or proved operations. If the operation Abandonment Notices must refinal inspection.) If 100' of cmt.; O' to 2050', which is above below the top of the Mesa below the base of the support of the Mesa or below the base of the support of the Mesa or below the Base of the support of the Mesa or below the Base of the support of the Mesa or below the Base of the support of the Mesa or below the Base of the support of the Mesa or below the Base of the Support of the Mesa or below the Support of the Mesa or below the Support of the Support of the Mesa or below the Support of the Support of the Support of the Support of the Suppo	ovide the Bond hion results in a mbe filed only after the perforation overde (1000) to reace esg. (402 C. 48	No. on file with I ultiple completion or all requirement on strom 2207' to to 50' above the of the surface	BLM/BIA. R on or recompi its, including to 2284'; top of the M	equired subsequent repletion in a new interval reclamation, have been	oorts must be filed within 30 days , a Form 3160-4 must be filed once	
John B. Somers II			Title Petroleum Engineer & President				
Signature John B.	Annus I		Date 01/18/2	013			
	THIS SPACE	FOR FEDE	RAL OR ST	ATE OF	ICE USE		
Approved by Original Sig	ned: Stephen Mason	s not warrant or c	Title ertify			JAN 2 4 2013 Date	
that the applicant holds legal or equitable t entitle the applicant to conduct operations	title to those rights in the subjethereon.	ect lease which wo	ould Office	nd willedier	o make to over deserve	nt or agency of the United States any false	

fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intention to Abandon:

Re: Permanent Abandonment

Well: 1 SI Federal 27

CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.
- 3. The following modifications to your plugging program are to be made:
- a) Place the Measverde plug from 1160' 1060'.
- b) Place the Pictured Cliffs/Surface plug from 413' to surface.

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.