Form 3160-5 (August 2007)

DEPARTMENT OF THE INTERIOR

FORM APPROVED OMB No. 1004-0137

Expires: July 31, 2).

	BUREAU OF LAND MAN	Expires: July 31, 2010					
				5. Lease Serial No.			
		ice Contract #153					
SUN	DRY NOTICES AND REPO	6nlffIndian, Allottee or Tribe Na	ime				
Do not use	e this form for proposals t	o drill or to re-enter a	n				
abandoned	well. Use Form 3160-3 (A	Jicarilla Apache					
	BMIT IN TRIPLICATE - Other ins	7. If Unit of CA/Agreement, Na	me and/or No.				
1. Type of Well							
Oil Well	Gas Well Other			8. Well Name and No.			
			_	Jicarilla 153 #14			
2. Name of Operator				9. API Well No.			
	ton Resources Oil & Gas				39-20123		
3a. Address		3b. Phone No. (include area co	,	10. Field and Pool or Explorator	•		
PO Box 4289, Farmingto	on, NM 87499	(505) 326-9700)	Basin DK	/ S. Blanco PC		
4. Location of Well (Footage, Sec., T., I				11. Country or Parish, State			
Surface UNIT I (NESE), 1650' FSL & 995' FEL, S	Rio Arriba ,	New Mexico				
12. CHECK 1	THE APPROPRIATE BOX(ES)	TO INDICATE NATURE	OF NO	TICE, REPORT OR OTHE	R DATA		
TYPE OF SUBMISSION		TYPE	OF AC	TION			
X Notice of Intent	Acidize	Deepen	P	roduction (Start/Resume)	Water Shut-Off		
<u>,</u>	Alter Casing	Fracture Treat	R	teclamation	Well Integrity		
Subsequent Report	Casing Repair	New Construction	XR	Recomplete	Other		
Z —	Change Plans	Plug and Abandon	┌┌	emporarily Abandon			
Final Abandonment Notice	Convert to Injection	Plug Back	□ v	Vater Disposal			
13. Describe Proposed or Completed Op	peration: Clearly state all pertinent de	ails, including estimated startin	g date of	any proposed work and approxim	ate duration thereof.		
	onally or recomplete horizontally, give						
	vork will be performed or provide the						
9 .	ed operations. If the operation results		-	•			
•	Abandonment Notices must be filed	only after all requirements, incl	uding rec	lamation, have been completed as	nd the operator has		
determined that the site is ready fo	r iinai inspection.)						
Plana ara ta raccomulata	this well in the Mesaverd	a formation and then	DUC 4	ha aviating Dakata/DC	zanaa with tha		
rians are to recomplete	; uns wen in the wesaverd	e romiauon and men	טחט נו	ne existinu Dakuta/PC	zones with the		

Mesaverde.

Attached is the MV plat and procedure. The DHC application will be submitted and approved before the work proceeds.

* submit CAL For AGENCIES REVIEW prior to perfs

RCVD FEB 12'13 OIL CONS. DIV. DIST. 3

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) DENISE JOURNEY	Title	Regula	tory Technician
Signature Denisi Journey	Date		2/5/2013
THIS PACE FOR FEI	DERAL OR	STATE OFFICE USE	
Approved by			
Original Signed: Stephen Mason		Title	Date FEB 0 8 2013
Conditions of approval, if any, are attached. Approval of this notice does not warrant that the applicant holds legal or equitable title to those rights in the subject lease whice entitle the applicant to conduct operations thereon.	Office		
entitle the applicant to conduct operations thereon. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for an	ny person knowi	ngly and willfully to make to any	department or agency of the United St

false, fictitious or fraudulent statements or representations as to any matter within its juri



District 1 1625 N. French Dr., Hobbs, NM 88240 Phone: (575) 393-6161 Fax: (575) 393-0720 District II 811 S. First St., Artesia, NM 88210

Phone: (575) 748-1283 Fax: (575) 748-9720 District III 1000 Rio Brazos Rd., Aztec, NM 87410

Phone: (505) 334-6178 Fax: (505) 334-6170 District IV

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3470 Fax: (505) 476-3462

State of New Mexico

Form C-102 August 1, 2011

Energy, Minerals and Natural Resources

Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

Permit 161407

FFB 06 2013

WELL LOCATION AND ACREAGE DEDICATION PLATammgton Field Citics

,	ARREST GOCK HOLL WILD VOI	ADMOD DEDICATION A	Manual and towns in the commence of			
1. API Number 30-039-20123	2. Pool Code 72319		I Name DE (PRORATED GAS)			
4. Property Code 16579	5. Propert JICARIL		6. Well No.			
7. OGRID No. 14538	1	8. Operator Name BURLINGTON RESOURCES OIL & GAS COMPANY LP				

10. Surface Location

UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County	ĺ
I	35	26N	05W		1650	s	995	E	RIO ARRIBA	

11. Bottom Hole Location If Different From Surface

UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County
1	cated Acres		. Joint or Infill	14	4. Consolidation (Code		15. Order No.	VP.F.E. 12: 115

DIST. 3

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION

OPERATOR CERTIFICATION

I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief, and that this organization either owns a working interest or unleased mineral interest in the land including the proposed bottom hole location(s) or has a right to drill this well at this location pursuant to a contract with an owner of such a mineral or working interest, or to a voluntary pooling agreement or a compulsory pooling order heretofore entered by the division.

E-Signed By: Title: Regulatory Technician

Date: 1/28/2013

SURVEYOR CERTIFICATION

I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my belief:

Surveyed By: James Leese

Date of Survey:

Certificate Number: 1463

Jicarilla 153 #14

Section 35-T26N-R05W API #: 3003920123

MV Recompletion Procedure

- 1. MIRU. Check casing, tubing and Braden head pressures. RU Gas Recovery Unit and flare stack. Blow down well, killing with 2% KCl as necessary.
- 2. ND Well head and NU BOP.
- 3. TOOH and lay down 2" J-55 short string tubing w/F-Nipple and perforated orange peeled sub @ 3,099'.
- 4. Release seal assembly and TOOH and lay down 2" J-55 long string tubing w/F-Nipple and seal assembly @ 7,210'. Will probably require fishing.
- 5. Clean out DK to PBTD and evaluate DK production.
- 6. Wireline set CBP at 6,500' in 4-1/2", 10.5#, J-55 Liner. TOL at 3,165'. 7-5/8" J-55, 26.4# casing @3,308'. Cement at top of liner and circulated to surface in 7-5/8".
- 7. Load hole with 2% KCL.
- 8. RU wireline company. Run CCL, CBL, GR and Neutron logs.
- 9. Perforate MV.
- 10. TIH w/frac string and set in top of liner.
- 11. Rig up Frac Equipment.
- 12. Frac MV with 70Q foam.
- 13. Rig down Frac equipment
- 14. Drill out CBP. Clean out hole. Tri-mingle DK, MV & PC
- 15. Run production string.
- 16. ND BOP, NU Wellhead. RDMO.

Geological Schematic ConocoPhillips **JICARILLA 153 #14** Well Config: - Original Hole, 1/22/2013 7:48:14 AM ftKB (MD) ftKB (TVB) Depth Markers Cr DSTPrf Zn ROP Orilling Parameter - Bit RPM () incl Schematic - Actual 11 Drilling Parameter - Int ROP (m/hr) 0.0001 319 Drilling Parameter - RPM () 320 322 PICTURED CLIFFS, 3,083 3,083 3,064 3,091 3,091 PERF PICTURED CLIFFS, 3,099 3,0643,130,8/23/1968 3,130 3,165 3,318 3,319 3,320 4,715 5,190 POINT LOOKOUT, 5,190 6,318 7,205 7,208 7,210 7,211 BASE GREENHORN, 7,249 7,249 7,274 7,275 DAKOTA, 7,275 -PERF DAKOTA, 7,2747,498, 7,498 7,504 7,537 Production 1, 4 1/2, 4.052, 3,165, 7,538 4,373.0 7,540

Page 1/1