Submitted in lieu of Form 3160-5 (June 1990)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

Use "APPLICATION FOR PERMIT" - for such proposals.

United States any false, fictitious or fraudulent statements.

RECEIVED

FORM APPROVED

Budget Bureau No. 1004-0135

MAR 06 2013

Expires: March 31, 1993

Farmington Field Office Bureau of Land Managemen.

1. Type of Well: Gas		5. Lease Number: SF-077651
2. Name of Operator:	· ········	6. If Indian, allottee or Tribe Name:
BURLINGTON RESOURCES OIL	. & GAS COMPANY LP	7. Unit Agreement Name:
3. Address and Phone No. of Operator:		7. Ont Agreement Name.
P. O. Box 4289, Farmington, NM	87499	8. Well Name and Number:
(505) 326-9700		RICHARDSON 102
 Location of Well, Footage, Sec. T, R, U FOOTAGE: 865' FSL & 1815' FV 		9. API Well No.
S: 10 T: 031N R: 012V		3004527865
		10. Field and Pool:
		FRC - BASIN CB::FRUITLAND COAL
		11. County and State: SAN JUAN, NM
12. CHECK APPROPRIATE BOX TO INDIC		
Notice of Intent	Recompletion	Change of Plans
X Subsequent Report Final Abandonment	Plugging Back	New Construction
Abandonment	Casing Repair Altering Casing	Non-Routine Fracturing Water Shut Off
Abandoninent		
13. Describe Proposed or Completed Operation This well was re-delivered on 1/4/201		Conversion to Injection
	erations 3 and produced natural gas and ent	
This well was re-delivered on 1/4/201 Notes: THIS WELL WAS SHUT I	erations 3 and produced natural gas and ent	rained hydrocarbons.
This well was re-delivered on 1/4/201 Notes: THIS WELL WAS SHUT I	erations 3 and produced natural gas and ent	rained hydrocarbons. G ON PUMP REPLACEMENT AND TUBING REPAIR.
This well was re-delivered on 1/4/201 Notes: THIS WELL WAS SHUT I	erations 3 and produced natural gas and ent	rained hydrocarbons. G ON PUMP REPLACEMENT AND TUBING REPAIR. RCVD MAR 13 '13 OIL CONS. DIV.
This well was re-delivered on 1/4/201 Notes: THIS WELL WAS SHUT I TP: 250 CP:	erations 3 and produced natural gas and ent	rained hydrocarbons. G ON PUMP REPLACEMENT AND TUBING REPAIR. RCVD MAR 13 '13
This well was re-delivered on 1/4/201 Notes: THIS WELL WAS SHUT I TP: 250 CP: Meter No.: 36170	erations 3 and produced natural gas and ent IIN MORE THAN 90 DAYS WAITING 250 Initial MCF: 205	rained hydrocarbons. G ON PUMP REPLACEMENT AND TUBING REPAIR. RCVD MAR 13 '13 OIL CONS. DIV.
This well was re-delivered on 1/4/201 Notes: THIS WELL WAS SHUT I TP: 250 CP: Meter No.: 36170 Gas Co.: WFC	erations 3 and produced natural gas and ent IIN MORE THAN 90 DAYS WAITING 250 Initial MCF: 205	rained hydrocarbons. G ON PUMP REPLACEMENT AND TUBING REPAIR. RCVD MAR 13 '13 OIL CONS. DIV.
This well was re-delivered on 1/4/201 Notes: THIS WELL WAS SHUT I TP: 250 CP: Meter No.: 36170 Gas Co.: WFC Proj Type.: REDELIVERY	erations 3 and produced natural gas and ent IIN MORE THAN 90 DAYS WAITING 250 Initial MCF: 205	rained hydrocarbons. G ON PUMP REPLACEMENT AND TUBING REPAIR. RCVD MAR 13'13 OIL CONS. DIV. DIST. 3
This well was re-delivered on 1/4/201 Notes: THIS WELL WAS SHUT I TP: 250 CP: Meter No.: 36170 Gas Co.: WFC Proj Type.: REDELIVERY	erations 3 and produced natural gas and ent IIN MORE THAN 90 DAYS WAITING 250 Initial MCF: 205	rained hydrocarbons. G ON PUMP REPLACEMENT AND TUBING REPAIR. RCVD MAR 13 '13 OIL CONS. DIV. DIST. 3
This well was re-delivered on 1/4/201 Notes: THIS WELL WAS SHUT I TP: 250 CP: Meter No.: 36170 Gas Co.: WFC Proj Type.: REDELIVERY 14. I Hereby certify that the foregoing is the signed of the same and the sa	erations 3 and produced natural gas and ent IIN MORE THAN 90 DAYS WAITING 250 Initial MCF: 205	rained hydrocarbons. G ON PUMP REPLACEMENT AND TUBING REPAIR. RCVD MAR 13 '13 OIL CONS. DIV. DIST. 3 atory Tech. Date: 3/6/2013
This well was re-delivered on 1/4/201 Notes: THIS WELL WAS SHUT I TP: 250 CP: Meter No.: 36170 Gas Co.: WFC Proj Type.: REDELIVERY 14. I Hereby certify that the foregoing is to signed Tamra Sessions	erations 3 and produced natural gas and ent IIN MORE THAN 90 DAYS WAITING 250 Initial MCF: 205	rained hydrocarbons. G ON PUMP REPLACEMENT AND TUBING REPAIR. RCVD MAR 13'13 OIL CONS. DIV. DIST. 3

NMOCD ca