District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV

State of New Mexico **Energy Minerals and Natural Resources**

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Oil Conservation Division 1220 South St. Francis Dr.

Form C-141

Revised August 8, 2011

1220 S. St. Francis Dr., Santa Fe, NM 87505 Santa Fe, NM 87505											
AT BURNING STATES OF THE STATE	en en Aleksandere er er amerikanen er e	official to the second of the	Rele	ease Notific	cation	and Co	orrective A	ction	and the second s		
						OPERA	ГOR		ial Report	☐ Final Repor	
Name of Co	ompany C	ConocoPhilli	ps Comp	any		Contact Lis					
Address 3401 East 30th Street, Farmington, NM						Telephone No. 505-326-9786					
Facility Nat	ne Hamn	nond WN F	ederal 7	1		Facility Type Gas Well					
Surface Owner BLM Mineral Owner						F ederal API No			o. 300452 .	3216	
LOCATION OF RELEASE											
Unit Letter	Section	Township	Range	Feet from the		n/South Line Feet from the East/West Line County					
I	35	27N	8W	1650'	S	South	990'	East	San J	uan	
	<u>t</u>	<u></u>	I	26 #26			107 (100)	_	 RCVD MAI	22213	
Latitude36.52677 Longitude107.64695_											
NATURE OF RELEASE											
Type of Rele						Volume of Release Volume Recovered					
Hydrocarbon						Produced Water 10.02 BBLs Hydrocarbon 2.52 BBLs 0 BBL 0 BBL					
Source of Release Production Tank						Date and Hour of Occurrence Date and Hour of Discovery					
Was Immediate Notice Given?						Unknown 03-21-2013; 10:00 AM					
Was Immedi	ate Notice (l Yes 🗀	No 🛛 Not R	eauired	If YES, To Whom?					
By Whom?					-1	Date and Hour					
DJ WHOIII:						Bute did from					
Was a Watercourse Reached? ☐ Yes ☒ No						If YES, Volume Impacting the Watercourse.					
If a Watercourse was Impacted, Describe Fully.* N/A											
A 1/4 A											
Describe Cause of Problem and Remedial Action Taken.*											
Production tank developed a leak due to a manway gasket causing the release of 10.02 BBLs of Produced Water and 2.52 BBLs of Hydrocarbon. Zero BBLs were recovered. Leak was contained in the Berm.											
Describe Area Affected and Cleanup Action Taken.* ConocoPhillips will replace gasket and will assess the soils to determine further action, if needed.											
Conocornii	nps win re	piace gasket a	ana wiii a	ssess the sons to	aetermi	ne further a	ction, it needed.				
								ınderstand that pu			
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger											
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health											
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other											
		ws and/or regu							- cp		
	·r.					OIL CONSERVATION DIVISION					
	$-\sqrt{\lambda}$	I/I	<u> </u>			Approved by Environmental Specialists () ()					
Signature:	-11	Mr. 49	•								
						Approved by Environmental Specialist:					
Printed Name	e: Lisa Hu	ınter		*** **			11.57	<u>V</u>		$\overline{}$	
Title: Field Environmental Specialist						Approval Date: 4/64/2013 Expiration Date:					

Conditions of Approval:

Phone: 505-326-9786

E-mail Address: <u>Lisa.Hunter@cop.com</u>

NJK 130943841

Attached [

March 26, 2013 * Attach Additional Sheets If Necessary