Submit 3 Copies To Appropriate District Office	State of New Mexico		Form C-103
District I	Energy, Minerals and Natural Resources		Jun 19, 2008
1625 N. French Dr., Hobbs, NM 88240 District II			WELL API NO. 30-039-06255
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION		5. Indicate Type of Lease
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.		STATE STATE
District IV	Santa Fe, NM 8	7505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505			E-291-35
	ICES AND REPORTS ON WELLS	<u> </u>	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			Johnston A Com B
1. Type of Well: Oil Well Gas Well Other P&A			8. Well Number 6
2. Name of Operator			9. OGRID Number
Burlington Resources Oil Gas Company LP			14538
3. Address of Operator P.O. Box 4289, Farmington, NM 87499-4289			10. Pool name or Wildcat Basin Fruitland Coal / Fruitland Sand
4. Well Location			
Unit Letter E : 150		line and890	
Section 36		Range 6W	NMPM San Juan County
	11. Elevation (Show whether DR 6618		
12 Check	Appropriate Box to Indicate N		Report or Other Data
			•
	ITENTION TO:		SEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WOR	
TEMPORARILY ABANDON DULL OR ALTER CASING	CHANGE PLANS MULTIPLE COMPL	COMMENCE DRI	
PULL OR ALTER CASING DOWNHOLE COMMINGLE	MOLTIPLE COMPL []	CASING/CEMENT	ТЈОВ 🗌
DOVINIOLE GOMINIMOLE			
OTHER:		OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated dat of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion			
of starting any proposed wo	ork). SEE RULE 1103. For Multip	ole Completions: At	tach wellbore diagram of proposed completion
or recompletion.		-	RCVD MAR 28 '13
The subject well was P&A'd on 3/1/13 per the attached report.			
			OIL CONS. DIV.
2110	Δ := \		DIST. 3
Spud Date:	Sig Rela	eased Date:	
Space Bate.		Lused Bate.	
I have been self-called a land of the self-called		- C 1 1 1	11 1' 0
I hereby certify that the information	above is true and complete to the b	est of my knowledge	e and belief.
SIGNATURE / //	Sussetitle_	Staff Regulatory	Technician DATE 3/28/13
Type or print name Dollie L. Bus	se E-mail address: dollie.	l.busse@conocophil	lips.com PHONE: 505-324-6104
For State Use Only	V 11	Deputy Oil & G	as Inspector.
APPROVED BY:	Juehlmo TITLE	Distric	
Conditions of Approval (if any):	r.		
	× '*	Approved for plug	ging of wellbore only. nd is retained pending.
	()	Receipt of C-103 (Subsequent Report of Well
	<u> </u>	Plugging) which m	ay be found @ OCD web
•		page under forms	us/ood
		www.emnrd.state.	us/ocu

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979 Farmington, New Mexico 87499 505-325-2627 *fax: 505-325-1211

Burlington Resources

Johnston A Com B #6

March 1, 2013 Page 1 of 1

1500' FNL and 890' FWL, Section 36, T-26-N, R-6-W San Juan County, NM Lease Number: E-291-35 API #30-039-06255

Plug and Abandonment Report Notified NMOCD and BLM on 2/25/13

Plug and Abandonment Summary:

- **Plug #1** with 64 sxs (75.52 cf) Class B cement inside casing from 2620' to 2055' to cover the Fruitland, Kirtland and Ojo Alamo tops.
- **Plug #2** with 53 sxs (62.54 cf) Class B cement inside casing from 988' to 820' with 29 sxs into annulus, 5 sxs under, 19 sxs above to cover the Nacimiento top.
- **Plug #3** with 24 sxs (28.32 cf) Class B cement inside casing from 187' to surface to cover the surface casing shoe.
- Plug #4 with 5 sxs Class B cement top off 5.5" casing 11' to surface and fill cellar and install P&A marker.

Plugging Work Details:

- 2/27/13 Rode rig and equipment to location. Spot in and RU. Open up well; no pressures. No tubing. RU relief lines. ND wellhead. NU BOP and function test. Tally 2-3/8" tubing off of float. PU 5.5" watermelon mill. PU 85 joints and tag CIBP at 2620'. Circulate well clean. Pressure test casing to 800 PSI. SI well. SDFD.
- 2/28/13 Open up well; no pressures. RU Basin Wireline. Ran CBL from 2620 to 0'. Found TOC at 1870' clear to 220' then ratty cement to surface. Note: S. Mason, BLM and B. Powell, NMOCD approved to continue plugging procedure as approved. TIH open-ended with 42 stands (84 joints) to 2620'. Spot plug #1 with estimated TOC at 2055'. RU Basin Wireline. Perforate 3 HSC holes at 1031'. Establish injection rate 5 bpm at 900 PSI. PU 5.5" Select Oil Tool CR and TIH set at 988'. Establish circulation 1.5 bpm at 900 PSI. Spot plugs #2 with estimated TOC at 820. LD joints to 187'. Spot plug #3 with estimated TOC at surface. ND BOP. NU wellhead. Pressure test casing to 300 PSI. SI well. SDFD.
- 3/1/13 Open up well; no pressures. Dig out wellhead. Fill out Hot Work Permit. Monitor well for gas. Cut off wellhead. Top off 5.5" casing 11' to surface and fill cellar. Spot plug #4 and install P&A marker. RD & MOL.

Paul Wiebe, NMOCD representative, was on location. Jim Yates, COPC representative, was on location.