Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

MAR 21 2013

FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010

Lease Serial No.

Farmington Field Office SF-078119 SUNDRY NOTICES AND REPORTS ON WELL ST Land Mal Marghiller, Allottee or Tribe Name Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other instructions on page 2. 7. If Unit of CA/Agreement, Name and/or No. 1. Type of Well Oil Well X Gas Well Other 8. Well Name and No. FC FEDERAL COM 3 2. Name of Operator 9. API Well No. ConocoPhillips Company 30-045-27545 3a. Address 3b. Phone No. (include area code) 10. Field and Pool or Exploratory Area PO Box 4289, Farmington, NM 87499 (505) 326-9700 **Basin Fruitland Coal** 4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) 11. Country or Parish, State UNIT B (NWNE), 820' FNL & 1670 ' FEL, Sec. 13, T32N, R11W **New Mexico** San Juan 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Acidize Deepen Production (Start/Resume) Water Shut-Off Reclamation Well Integrity Alter Casing Fracture Treat X Subsequent Report Casing Repair **New Construction** Recomplete Other Tubing & Pump Change Plans Plug and Abandon Temporarily Abandon Install Sundry Plug Back Water Disposal Final Abandonment Notice Convert to Injection 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) This well was completed as an open hole Fruitland Coal well in 1990, and is currently producing via the casing with no tubing in the hole, per Order TX-277. 3/12/13 - MIRU DWS 29. ND WH, NU BOPE, PT BOPE, Test OK, TIH w/7" RBP, set @ 1.030'. PT RBP to 600#. Test OK. ND BOPE. Change out wellhead. NU WH. PT to 1500#, good test. ND WH. NU BOPE. PT BOPE to 600# good test. Release RBP & TOOH. 3/15/13 - CO to 2,993'. TIH w/ 94 its, 2 3/8", 4,7#, J-55 tubing (new tubing), set @ 2,974' w/ FN @ 2,944'. ND BOPE NU WH. TIH w/ RHAC-Z Insert Pump & Rods (new pump & rods). Space out Rods. PT tubing to 1500#, good test. 3/15/13. ROUD MAR 26 113 OIL CONS. DIV. DIST. 3 14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) Regulatory Technician **Denise Journey** Title 3/19/2013 INIK ourne Signature THIS SPACE FOR FEDERAL OR STATE OFFICE USE Approved by

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

MMOCDA

Office

entitle the applicant to conduct operations thereon.

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify

that the applicant holds legal or equitable title to those rights in the subject lease which would