BUR	UNITED STATE PARTMENT OF THE EAU OF LAND MAN	INTERIOR ^{II} IAGEMENT	ADD 11	₩E 2013		FORM APPROVED OMB No. 1004-0137 xpires: October 31, 2014	
SUNDRY N Do not use this f	OTICES AND REPO	ORTS ON W to drill or to	ELLS R	2012	6. If Indian, Allottee of	or Tribe Name	
abandoned well.	orm for proposals a Use Form 3160-3 (A	NPD) for suc	h proposals	iela Om Manago	ж те:		
	TIN TRIPLICATE – Other	r instructions or	n page 2.		7. If Unit of CA/Agre	ement, Name and/or No.	
1. Type of Well	/ell 🔲 Other				8. Well Name and No USA 23-2		
2. Name of Operator Chevron USA Inc			· · · · ·		9. API Well No. 30-045-31150	······································	
3a. Address ATTN: Regulatory Specialist 332 Road 3100 Aztec New Mexico 87410		3b. Phone No. 505-333-1941	(include area code	2)	10. Field and Pool or Basin Fruitland	Exploratory Area	
4. Location of Well (Footage, Sec., T.,	R., M., or Survey Description		· · · · · · · · · · · · · · · · · · ·		11. County or Parish,	State	
312 FSL 2019 FWL N-23-32N-13W	· · · · · · · · · · · · · · · · · · ·				San Juan County, I	NM	
12. CHEC	K THE APPROPRIATE BO	OX(ES) TO IND	ICATE NATURE	OF NOTIC	CE, REPORT OR OTH	IER DATA	
TYPE OF SUBMISSION			ТҮР	E OF ACT	ION		
Notice of Intent	Acidize	Deep			uction (Start/Resume) amation	Water Shut-Off Well Integrity	
Subsequent Report	Casing Repair		Construction	_	mplete	Other Hole in tubing repair	
Final Abandonment Notice	Convert to Injection		and Abandon Back		porarily Abandon er Disposal		
stuck open. Offload new 2 3/8 tbg, RU tbg hand Pump 40 bbls down csg, ND WH, 0 NU Companion flange, Spool, Blind PU on hangar Remove 2 7/8 TIW, 1	r final inspection.) 80 psi, Bradenhead - 0 p handling tools pump. Rods shoulders w ling equipment companion flange for BOF ls, Pipe and Annulars, RU nstall pup jt, Relandl hang	osi, Lay line to f vere wore out. P's was wrong s I Floor, Tongs gar, Shell test E	lowback tank, Oj Total of 61 - 3/4" ize, Order correc	pen well to rods,(16 g ct flange.	o flowback tank and guided) 8' & 6' pony's	RCVD APR 15 '13 OIL CONS. DIV. DIST. 3 bleed down. RU Pump and lines. s, 1 1/4 x 22' PR w/ liner, Pump was	
See atttached pages for remainder	of procedure and well bo	re diagram.					
			т. +		· .		
14. I hereby certify that the foregoing is	true and correct. Name (Prim	ed/Typed)			<u> </u>	· · · · · · · · · · · · · · · · · · ·	
April E. Pohl			Title Regulator	ry Special	ist		
Signature April E	Pohl		Date 4-11	-13			
······································	THIS SPACE	FOR FEDE	RAL OR ST	ATE OF	FICE USE	AGOSPITED FOR RECORD	
Approved by		·····				APR 1 2 2013	
Conditions of approval, if any, are attached that the applicant holds legal or equitable entitle the applicant to conduct operations	title to those rights in the subj			···· ,. · · · ·		Date	
fictitious or fraudulent statements or repu			• • •	nd willfully	to make to any departm	ent or agency of the United States any false	
(Instructions on page 2)							
		NN)CDA				

3/19/2013

Check well, SITP - 180 psi, SICP - 180 psi, Open well to flowback tank and bleed down.

Pull and LD Hangar, Install stripper, PU & RIH w/ tbg, tag on second jt 1' in (33'), POOH, LD 49 jts, SN, 4ft perf sub, full jt muleshoe. Tally same. Pipe looks good, no holes found.

Tally pipe. Load racks w/ new 2 3/8 L80. PU and RIH w/3 7/8" bit, bit sub on 50 jts 2 3/8 tbg to 1583'

POOH w/ bit and scraper, LD tools

PU & RIH w/ RBP(G-Plug), Attempt to set at 1400', Could set and release but would not grip, attempt several times w/out success, POOH. PU & RIH w/ Model M. Set at 1400',

Load and test csg and plug to 500 psi, Test good, Bleed down. Secure well, SDFN.

3/20/2013

Check well, SITP - 0 psi, SICP - 0 psi, Open well to flowback tank, warm up equipment

POOH w/ 11 stnds, PU Mod M plug, RIH w/ 7 stands, Set plug at 520'. Release and POOH.

RD Floor, tongs, ND BOP's, annular, pipe, blind, spool.

ND old WH, NU W2 7 1/16 3K x 4 1/2" w/ 2" x 6" XH SO w/ 3K valves, Tbg Hangar w2B 7 x 2 3/8

NU Spool, Blind, Pipe and annulars, Test flange to 1200 psi.

RIH, Latch plug @ 520', Release and POOH, LD plug, RIH, Latch plug @ 1400', Release, let equalize and POOH, LD plug

PU & RIH w/ 3 7/8" bit, bit sub on 48 jts 2 3/8" tbg

Secure well, SDFN.

3/21/2013

Check well, SITP - 0 psi (string float), SICP - 190 psi, Open well to flowback tank. Warm up equipment RIH, tag fill @ 1624 on 52 jts, Install new stripper, RU Chicksan. Start air, Establish circulation @ 350 psi. Cleanout fill from 1624' to 1640' pipe meas, found hard bttm, Recovering small amount of frac sand, small amount of coal, black wtr. Pumping 14 BWPH mist @ 300 psi. Wtr cleaned up. SD air, LD 4 jts, POOH w/48 jts. PU & RIH w/ muleshoe(22.42), SN(1.10), 48 jts 2 3/8" 4.7# L80 tbg(1518.72), 8' x 2 3/8 pup jt(8.10), 6' x 2 3/8 pup jt(6.15), slick jt(32.00), PU Hangar(0.70) and land tbg. EOT- 1594.18, SN - 1572

RD Floor, Tongs, ND BOP's, NU B1 adapter, radigan and pump tee, Test Void to 1500 psi. Test good. Secure well, SDFN.

3/22/2013

Check well, SITP- 0 psi, SICP - 190 psi, Open well to flowback tank and bleed down.

PU & RIH in singles w/ 2" x 1 1/2" x 14 RWAC-Z pump (#CX610), 2" Stabilizer Bar, 3 - 1 1/4" x 25' Sinker bars, 4 - 3/4" T-54 2" Guided 5 per x 25' rods, 55 - 3/4 x 25' rods, T54 Plain, Space out w/ 1 1/4" x 22' Polish Rod, Load well and test tbg to 500 psi. Check pump action w/ rig, Good pump action.

RDMO.



Wellbore Schematic

USA 2	me 23-2	12363	Basin(Nev	v Mexico)					ivAaska	
	Original more, 49/2013 10	23:14 AM	Job Details						· · · · · · · · · · · · · · · · · · ·	
925 (R45)	Vertia: scremut	c (attua)	- Major Rig Work Over			3/15/	5ter1 0 2013			n dze 19. otto
			Casing Strings	Anna 101	4 ⁶ .		.v.u		<u> </u>	i cita (
67	· · · · · · · · · · · · · · · · · · ·									SetDepth
			Csg Des Surface	OC (11)	7	en (165) 20.00	Gra J-55	0e.	Top Thread	(MD) (625) 170
ч і .			Production Casing	4 1/		10.50				1.692
		illan direction da a la della del	Tubing Strings	·····						
1:	Tubing - Production set at 1,594.2/tKB on 3/21/2013 14:00									ptn (MC) (7-5)
		sing manger: 5-5; 1.00; 4 1/2;	Tubing - Production			3/21/	2013		1,589.19	1,594.
**		52 2-1	ten Des Tubing Hanger		ೆಡ	(n) ده 7	WA (2010)	Grade	<u>າ(ກິ)</u> 0.70	50n (CAS)
			Tubing		1	2 3/8	4.70	L-80	32.00	37.7
16			Tubing Pup Joint		1	2 3/8	4.70	L-80	6.15	43.8
		ologi, 6-33. 22.00, 2.3%, 1.995; 2-2	Tubing Pup Joint	*****		2 3/8		L-80	B.10	51.9
			Tubing Pump Seating Nipple		48	2 3/8 2 3/8	4.70	L-30	1,518.72 1.10	1,570.
		5.ng (Pup 2014, 35-44; 6.15; 2 3.8; 95; 2-3	Mule Shoe Tubing Jo			2 3/8			22.42	1.571.0
a2			Rod Strings							
		bing: Pup Joint; 44-52; 8.10; 2-3-5; 95; 2-4	Rods-Long on 3/22/	2013 08:00		RonDate		Chrone 1	and the second	sta (1.45);
1-1	- 🕅 🕅 👘 🕅 🕅 🛶	strg utdint, 5-169, 154.00; 7; 5 458;	Rods-Long				2013	Sring Lang	1,588.70	1,672.
		(08 Shoe, 169-170; 1.00, 7; 8:455,	tiom Cet	·····	.12	(r1) CO	WH (15/1)	61338	Le1 (fi)	9m (249)
-514			Polished Rod Sucker Rod		1 55	1 1/4	1.63		22.00 1.375.00	1,380.3
	· ※ ※ · · · · · · · · · · · · · · · · ·	2/2002 Ding: 52-1,571; 1,518.72; 2 3/3;	Sucker Rod, Guided	5 per	4	3/4	1.63		100.00	1.480.
-15.4		95; 2-5 657g Jacob 5-1,545; 1,639,00; 4 1/2; -	Sinker Bar		3	1 1/4	4.17		75.00	1.565.
		exig costa 511,545, 1,539,55, 4172, 52, 2-2	Stabilizer bar		1	3/4			2.70	1,558.
1 242 2		,	Rod Pump 2 x 1 1/2 x	14 RWAC		2			14.00	1,572.0
			Perforations						k	<u></u>
*****					Snot Dera	Enter	id Snat	u mathematica		
· 877 6			Cafe Top (#4		{E/053-0	Q TA	rta)		Zone & Competi	
			Other Strings	.0 1,500.0) 6.	۳ ۱		ruluan	d Coal, Origin	
- 333 4		ised Hole; 1,626-1,660; 11/21/2002) Carla S	el Depin (12	G) .			Сот	
				<u> </u>	· · · · · · · · · · · · · · · · · · ·					
• ### •			Other in Hole	00 (11(5) Bim	(6-<9)	RUTOM	Pij	0010	Con	1
			Cement	1.645.0 1.6	92.0 8/	31/2002			*** * ** *** *************************	
-3612										
· r : 1										
		mip Seating Silpple; 1,571-1,572; 10; 2:33: 1,730; 2-5								
I		vie Snoe Tucking Volmi; 1,572-1,534; 142; 2 33; 1,995; 2-7								
-342	. M 🚩 🕅 T	· · · · · · · · · · · · · · · ·								
· 642 :	A REPORT OF A			•						
1		pat Ciphar; 1,645-1,545; 1,00; 4, 1/2; 952; 2-3								
· 444 1		· · · ·								
1		asing Joint, 1,545-1,691; 45:00; 4 2; 4/352:2-4								
- 691.9		· · · · · · · · · · · · · · · · · · ·								
		oat Shoe: 1,691-1,692; 1,00; 4 1/2; 352; 2-5								
• 63- 6	Pr 3	raduction Catiling, Cemient; 5-1,592; 20/2002				-				
1										
• 444 4										
1	1		11							
1										