

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

RECEIVED

MAY 15 2013

FORM APPROVED
OMB No. 1004-0137
Expires: July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

Farmington Field Office
Bureau of Land Management

5. Lease Serial No.

SF-078119-A

6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on page 2.

1. Type of Well

☐

Oil Well

☒

Gas Well

☐

Other

2. Name of Operator

Burlington Resources Oil & Gas Company LP

7. If Unit of CA/Agreement, Name and/or No.

8. Well Name and No.

Mark Maddox 1M

9. API Well No.

30-045-35085

3a. Address

PO Box 4289, Farmington, NM 87499

3b. Phone No. (include area code)

(505) 326-9700

10. Field and Pool or Exploratory Area

Blanco MV/ Basin DK

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Surface UL J (NW/SE), 1607' FSL & 1803' FEL, Sec. 15 T32N, R11W

Bottomhole UL J (SE/SE), 735' FSL & 1160' FEL, Sec. 15 T32N, R11W

11. Country or Parish, State

San Juan

New Mexico

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

☐ Acidize

☐ Alter Casing

☐ Casing Repair

☐ Change Plans

☐ Convert to Injection

☐ Deepen

☐ Fracture Treat

☐ New Construction

☐ Plug and Abandon

☐ Plug Back

☐ Production (Start/Resume)

☐ Reclamation

☐ Recomplete

☐ Temporarily Abandon

☐ Water Disposal

☐ Water Shut-Off

☐ Well Integrity

☒ Other Cathodic

Sundry

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

Attached is a drawing for the placement of the cathodic ground, rectifier and cable for the subject well.

RCUD MAY 17 '13
OIL CONS. DIV.
DIST. 3

ACCEPTED FOR RECORD

MAY 16 2013

FARMINGTON FIELD OFFICE
BY M Kelly

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)

Kenny Davis

Staff Regulatory Technician

Title

Signature

Date

5/14/2013

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office



Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instruction on page 2)

NMOCDCa

Mark Maddox #1M

Unit J-S15, T32N, R11W, San Juan County, NM



Drill ground bed approximately 120' north of #1M wellhead at staked location. Install a 40-16 rectifier and stud pole and connect to UGAC vicinity the east side of the location. If possible, connect to the old groundbed, which has been stripped, and the new groundbed, and the #1A and #1M wellheads at the lengths below. Repair cables as needed.

#1A Cables:

Negative: 175'

Positive: 15'

UGAC: 50" (approx)

Total Ditch: 240'