

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office to
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company ConocoPhillips Company	Contact Crystal Tafoya
Address 3401 East 30th St, Farmington, NM	Telephone No. (505) 326-9837
Facility Name: San Juan 31-6 Unit 230A	Facility Type: Gas Well

Surface Owner NMGF	Mineral Owner BLM (SF-078999)	API No. 30-039-27401
---------------------------	--------------------------------------	-----------------------------

LOCATION OF RELEASE

Unit Letter I	Section 27	Township 31N	Range 6W	Feet from the 1465	North/South Line South	Feet from the 935	East/West Line East	County Rio Arriba
-------------------------	----------------------	------------------------	--------------------	------------------------------	----------------------------------	-----------------------------	-------------------------------	-----------------------------

Latitude **36.86734** Longitude **107.44379**

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 7 bbls	Volume Recovered 5 bbls
Source of Release Transfer Pump	Date and Hour of Occurrence Unknown	Date and Hour of Discovery 4/15/2013 at 10:30am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. RCVD APR 18 '13	
If a Watercourse was Impacted, Describe Fully.* N/A	OIL CONS. DIV. DIST. 3	



Describe Cause of Problem and Remedial Action Taken.*

Water Transfer Pump Engine starter relay failed, allowing the pumping unit to continue filling the water tank above normal levels allowing 7bbls of produced water to overflow. The pumping unit was shut-off immediately and water trucks called to location. 5bbls of produced water was recovered.

Describe Area Affected and Cleanup Action Taken.*

ConocoPhillips will assess the soil to determine a path forward for clean-up if necessary.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Crystal Tafoya	Approved by Environmental Specialist: 	
Title: Field Environmental Specialist	Approval Date: 5/21/2013	Expiration Date:
E-mail Address: crystal.tafoya@conocophillips.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 4/17/2013 Phone: (505) 326-9837		

* Attach Additional Sheets If Necessary

nJK1314140865