	Submit 3 Copies To Appropriate District Office	State of New Mexico	Form C-103	
-	<u></u>	, Minerals and Natural Resources	Jun 19, 2008 WELL API NO.	
	1625 N. French Dr., Hobbs, NM 88240 District II		30-039-24293	
	1501 W. Gland Ave., Artesta, INV 66210	CONSERVATION DIVISION	5. Indicate Type of Lease	
	District III 1000 Rio Brazos Rd., Aztec, NM 87410	220 South St. Francis Dr.	STATE STATE	
	District IV	Santa Fe, NM 87505	6. State Oil & Gas Lease No.	
	1220 S. St. Francis Dr., Santa Fe, NM 87505		B-10037-58	
	SUNDRY NOTICES AND REPORTS ON WELLS   (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A   DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH   PROPOSALS.)   1. Type of Well: Oil Well Gas Well Other P&A   2. Name of Operator		7. Lease Name or Unit Agreement Name San Juan 29-7 Unit NP	
			8. Well Number 509	
			9. OGRID Number	
	Burlington Resources Oil Gas Company LP		14538	
	3. Address of Operator		10. Pool name or Wildcat	
	P.O. Box 4289, Farmington, NM 87499-4289		Basin Fruitland Coal	
	4. Well Location			
	Unit Letter A : 795 feet from the North line and 1090 feet from the East line			
	Section 16 Township 29N Range 7W NMPM Rio Arriba County			
	11. Elevation (Show whether DR, RKB, RT, GR, etc.) 6262' GR			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:   PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING   TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS P AND A Image: Commence drilling opns Image: Commence drilling			ORK	
	OTHER:	OTHER:		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimate of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed comp or recompletion.				
			RCVD MAY 6 '13	
The subject well was P&A'd on 4/9/13 per the attached report.			OIL CONS. DIV.	
PNRONL				
Spud Date: Rig Released Date:			DIST. 3	
	I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
	SIGNATURE Mile Sume TITLE Staff Regulatory Technician DATE 5/3/13			
Type or print name Dollie L. Busse E-mail address: dollie.l.busse@conocophillips.com PHONE: 505-324-6104				
	For State Use Only			
APPROVED BY Deputy Oil & Gas Inspector,   Conditions of Approval (if any): TITLE District #3 DATE 5/15			Gas Inspector,	
			trict #3 DATE <b>27/5/12</b>	
	Approved for plugging of wellbore only. Liability under bond is retained pending. Receipt of C-103 (Subsequent Report of Well Plugging) which may be found @ OCD web page under forms www.emnrd.state.us/ocd			

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979 Farmington, New Mexico 87499 505-325-2627 \*fax: 505-325-1211

## Burlington Resources San Juan 29-7 Unit NP 509

April 9, 2013 Page 1 of 1

795' FNL and 1090' FEL, Section 16, T-29-N, R-7-W Rio Arriba County, NM Lease Number: B-10037-58 API #30-039-24293

Plug and Abandonment Report

Notified NMOCD and BLM on 3/22/13

## Plug and Abandonment Summary:

Plug #1 (combined #1 & #2) with CR at 2963' spot 64 sxs (75.52 cf) Class B cement inside casing from 2963' to 2544' with 11 sxs inside 4.5" liner and 53 sxs in 7" casing to cover the Fruitland Coal top.

- **Plug #3** with 65 sxs (76.7cf) Class B cement inside casing from 2387' to 2050'to cover the Kirtland and Ojo Alamo tops.
- Plug #4 with 31 sxs (36.58 cf) Class B cement inside casing from 962' to 802' to cover the Nacimiento top.
- Plug #5 with 72 sxs (84.96 cf) Class B cement inside casing from 283' to surface to cover the surface casing shoe.
- **Plug #6** with 45 sxs Class B cement found cement at surface in 7" casing and down 20 in annulus and install P&A marker.

## **Plugging Work Details:**

- 4/4/13 Rode rig and equipment to location. RU Expert Downhole Service. RIH and pulled bumper spring from 3039'. POH. RIH and tag fill at 3042'. SI well. SDFD.
- 4/5/13 Check well pressures: tubing 320 PSI, casing 360 PSI and bradenhead 0 PSI. RU relief lines and blow well down. ND wellhead. Pressure test pipe rams to 300 PSI and 1500 PSI, OK. Pull tubing hanger and install 2-3/8" stripping rubber. TOH and tally with total 98 joints: 1 joint, 2' sub and 1 joint, F-nipple and exp check 2-3/8" tubing, 3039'. Round trip 4.5" string mill to 2976'. TIH with 4.5" DHS CR and set at 2963'. Pressure test tubing to 1000 PSI, OK. Establish circulation. Pressure test casing to 800 PSI, OK. SI well. SDFD.
- 4/8/13 Open up well; no pressures. RU Blue Jet Wireline. Ran CBL from 2963' to surface, good cement all the way to surface. TIH to 2963'. Note: C. Perrin, NMOCD approved plug #1 & #2 combined. Establish circulation. Spot plug #1 with estimated TOC at 2544'. Establish circulation. Spot plugs #3, #4 and #5. Dig out wellhead. SI well. SDFD.
- 4/9/13 Open up well; no pressures. Open up well and tag TOC at 8'. ND BOP. High Desert cut off wellhead. Found cement at surface in 7" casing and down 20 in annulus. Spot plug #6 and install P&A marker. RD and MOL.

Paul Wiebe, NMOCD representative, was on location. Jim Morris, MVCI representative, was on location.