#### RECEIVED **ELECTRONIC REPORT**

Form 3160-5 (August 2007)

# **UNITED STATES** DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

9 2013 MAY

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

5. Lease Serial No.

6. If Indian, Allottee or Tribe Name

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.

122IND2772

	<u> </u>	BUREA	U OF LAN	D MANAGEM	ENUTE MOUNTAIN	IUIE	
SUBMIT IN TRIPLICATE - Other instructions on reverse side.					7. If Unit or CA/Agreement, Name and/or No.		
Type of Well					8. Well Name and No. UTE MTN UTE 80		
2. Name of Operator Contact: CATHERINE SMITH HUNTINGTON ENERGY LLC E-Mail: csmith@huntingtonenergy.com					9. API Well No. 30-045-34513-00-S1		
3a. Address 908 NW 71ST ST OKLAHOMA CITY, OK 73116  3b. Phone No. (include area of Ph: 405-840-9876 Ext.) Ph: 405-840-2011				10. Field and Pool, or Exploratory BARKER CREEK			
4. Location of Well (Footage, Sec., T			11. County or Parish, and State				
Sec 20 T32N R14W NWNE Tract B 1300FNL 1700FEL 36.977711 N Lat, 108.329380 W Lon					SAN JUAN COUNTY, NM		
12. CHECK APPI	ROPRIATE BOX(ES) TO	INDICATE NAT	URE OF N	NOTICE, RE	PORT, OR OTHER	R DATA	
TYPE OF SUBMISSION	TYPE OF ACTION						
☐ Notice of Intent	☐ Acidize	□ Deepen	□ Deepen		on (Start/Resume)	■ Water Shut-Off	
_	☐ Alter Casing	☐ Fracture T	☐ Fracture Treat		ion	■ Well Integrity	
Subsequent Report ☐ Casing Repair ☐ Ne		■ New Cons	truction	Recomplete		□ Other	
☐ Final Abandonment Notice	☐ Final Abandonment Notice ☐ Change Plans ☐		Abandon	☐ Temporarily Abandon			
bl	☐ Convert to Injection	tion Plug Back Wa		□ Water Di	ater Disposal		
Attach the Bond under which the wo following completion of the involved testing has been completed. Final Aldetermined that the site is ready for The above referenced well was on the well is attached. The w	I operations. If the operation res bandonment Notices shall be file inal inspection.) as recompleted in the Basi rell is non-productive and b	ults in a multiple comp d only after all require n Mancos formation	oletion or recoments, includents.  The sum	ompletion in a neing reclamation,	w interval, a Form 3160 have been completed, a	0-4 shall be filed once	
Recompletion Summary and the Wellbore Schematic.					RCVD JUN 4'13		
·	ACCEPTED FOR REJORD				OIL CONS. DIV.		
Ex. DWL 5/14/13 DIST. 3							
Bureau of Land Management							
14. I hereby certify that the foregoing is true and correct.  Electronic Submission #207060 verified by the BLM Well Information System  For HUNTINGTON ENERGY LLC, sent to the Durango  Committed to AFMSS for processing by BARBARA TELECKY on 05/10/2013 (13BDT0114SE)							
Name (Printed/Typed) CATHERI	NE SMITH	Title	REGUL	ATORY			
Signature (Electronic	Submission)	Date	05/09/2	013			
THIS SPACE FOR FEDERAL OR STATE OFFICE USE							
		Title			<del></del>	Dete	
Approved By			<del>-</del>			Date	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			ce				

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

## **Huntington Energy, L.L.C.**

908 NW 71<sup>st</sup> Street Oklahoma City, Oklahoma 73116 (405) 840-9876

#### **Ute Mountain Ute #80 – Recomplete to Mancos - Attachment**

Sec. 20-32N-14W San Juan Co., NM API #30-045-34513

**2/19/13:** MIRU LF RIG 7. ND WH, NU BOP. TOOH W/TBG. RU WEATHERFORD AND TEST CSG AND BOP TO 500 PSI FOR 30 MINS. RU BASIN AND RIH W/ DUMP BALER, DUMP <u>8 SX OF CMT OVER CIBP @ 2270'</u>, PBTD @ 2165'. PERF FROM 2050' TO 2120'. RD WL TRUCK. SWIFN.

**2/20/13:** CSG 0 PSI. LAY DOWN 6 JTS. TIH W/ 8' PERF SUB, .87 FN, 6.60' PACKER, 62 JTS OF 2 3/8" TBG 2021'. TOP PACKER @ 2021'. BOTTOM OF PACKER @ 2028', TAIL PIPE @ 2037'. ND BOP. NU WH. RU SWAB EQUIPMENT. SWAB BACK 8.4 BBLS. NO ENTRY. RD SWAB EQUIPMENT, RD.

**2/22/13:** CSG 0 PSI. MIRU PHX SLICKLINE & HALLIBURTON. SAFETY MTG. PRESS TEST LINES TO 3000 PSI. SI. OBSERVE PRESSURE. ISIP 1592 PSI. 5 MINS 1283 PSI. 10 MINS 1278 PSI. RIH W/TBG PLUG AND SET. RDMO.

**3/4/13:** MIRU PHX TBG 113 PSI. CSG 10 PSI. RIG UP TO SWAB. FLUID LEVEL @ SURFACE. RIH TO 300'. RIG DOWN PHX.

**3/12/13:** MIRU. RU SWAB EQUIPMENT, NO PRESSURE ON WELL. FLUID LEVEL @ 100' SWAB WELL DOWN NO ENTRY. RECOVER 6 BBLS. ND WELL HEAD AND NU BOP. TOOH W/PKR. PU RBP AND RIH. SET RBP @ 2021'. FILL HOLE W/2% KCL WTR AND PRESSURE TEST CSG & PLUG TO 500 PSI. HELD. TOOH, RU BASIN AND PERF FROM 1810-1924', .38", 2 SPF, 228 HOLES. RD BASIN, PU RETRIEVING TOOL AND PACKER. RUN IN HOLE & SET PKR @ 1783'. ND BOP. NU WELL HEAD. RU TO SWAB. SWIFN.

3/13/13: TBG 0 PSI. RUN W/SWAB, NO FLUID ENTRY. SWI. RD.

**3/18/13:** MIRU PHX AND HALLIBURTON. TBG 95 PSI. CSG 0 PSI. RIH W/ GAUGE RING. RIH AND UNLATCH TANDEM GAUGES. POOH. SAFETY MTG. PRESSURE TEST LINES TO 4000 PSI. RIH W/ TBG PLUG AND SET. RDMO.

4/1/13: MOVE IN PHX AND RU. RIH AND PULL GAUGES. TBG 150 PSI, CSG 340 PSI. RD PHX.

**4/3/13:** MIRU. TBG 190 PSI, CSG 340 PSI. PU SWAB TOOLS, FLUID LEVEL @ SURFACE. SWAB WELL DOWN NO ENTRY. REC 6 BBLS. LD SWAB TOOLS AND ND WELLHEAD, NU BOP. RD AND LATCH ON RBP. SET PLUG AND PRESSURE TEST TO 500 PSI W/RIG PUMP. SWIFN.

4/4/13: TBG AND CSG 0 PSI. MOVE IN HALLIBURTON AND RU. SAFETY MEETING. PRESSURE TEST LINES TO 5670 PSI. PUMP 15% HCL ACID (2.5 BBLS) AND FLUSH W/ 6.7 2% KCL WATER. RIG DOWN HALLIBURTON. TOOH W/TBG. RU BASIN & PERF F/1660-1722', .38",2 SPF, 124 HOLES. RD W/L. TIH TO SET PKR & PUT AWAY ACID. 2.5 BBLS & FLUSH TO BTM OF PERFS @ 1722'. BLEED DOWN. UNSET PKR & SET @ 1641'. EOT @ 1653'. ND BOP. NU WH. RIG DOWN.

PKR & SET @ 1641'. EOT @ 1653'. ND BOP. NU WH. RIG DOWN,

4/5/13: RU PHX AND HALLIBURTON. RIH W/GAUGE RING, POOH. RIH & UNLATCH TANDEM GAUGES.

POOH. SAFETY MTG. PRESS TEST LINES TO 3540 PSI. PUMP 500 GALS 15% HCL ACID, PUMP 36 BBLS

OF 2% KCL WATER @ 6.1 BPM PRESSURE 1562 PSI. AVG PSI 1375 PSI, ISIP 469 PSI, 5 MINS 439 PSI,

10 MINS 438 PSI. RIH W/ TBG PLUG AND SET. RIG DOWN PHX & HALLIBURTON.

Created by Neevia Document Converter trial version http://www.neevia.com

4/15/13: MIRU PHX WIRELINE & RIH. RETRIEVE GAUGES. TBG 0 PSI, CSG 0 PSI.

**4/17/13:** TBG 5 PSI, CSG 0 PSI. RU. SWAB RIG & SWAB WELL. FLUID LEVEL @ SURFACE TO START SWAB DOWN TO SN. SDFN.

**4/18/13:** TBG 40 PSI, CSG 0 PSI. RUN IN HOLE W/ SWAB (DRY) NO WATER ON SAND LINE. RIG DOWN

\*EVALUATE WELL.

### **Ute Mountain Ute #80**

CURRENT
San Juan County, New Mexico
Sec 20-32N-14W
1300' FNL & 1700' FEL

Today's Date: 5/9/2013

Spud: 7/22/08 API: 30-045-34513

Recomp to Mancos: 4/18/13

TOC: SURF MKRJT - 1345'

Mancos perforations:

1660' - 1722' 1810' - 1924'

Formation Tops:

Mancos: 440' Greenhorn 2157' Graneros 2215' Dakota 2284' Morrison 2523'

Pumped 94409 gal 70 q delta 140 w/ slc containing 100,443# 20/40 and a total of 1459528 scf N2

Inactive Perfs: 2286-2297', 2326-2334', 2350-2364', 2 SPF

Brkdwn: ISIP = 410 psi, 5 min - 50 psi, 10 min - 0.

Inactive Perfs: Burro Canyon 2495-2500' Lwr Cubero 2479-2482' Upper Cubero 2416-2424'



85/4" J-55 23# set @ 340'

4/18/13: Evaluate Well

Pkr @ 1641'.

2 3/8" tbg @ 1653'.

CIBP plug set @ 2270'

Cap w/8 sx cmt to PBTD @ 2165'

(top of Graneros @ 2205')

35' cement: CIBP @ 2403'

35' cement: CIBP set at 2473'

Float Collar 2748'

4 1/2" J-55 10.5# csg set @ 2769'

Upper Cubero 2416-2424'

TD: 2800'