Form 3160-5 (March 2012)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED OMB No. 1004-0137 Expires: October 31, 2014

MAY 01 201' 5. Lease Serial No.

JIC 68

SUNDRY NOTICES AND REPORTS ON WELLS

SUBM	IT IN TRIPLICATE - Other in	7. If Unit of CA	7. If Unit of CA/Agreement, Name and/or No.		
1. Type of Well			8. Well Name ar	ad No	
Oil Well Gas Well Other				Jicarilla B 3E	
2. Name of Operator Four Star Gas & Oil			9. API Well No. 30-039-22659		
3a. Address ATTN: Regulatory Specialist 332 Road 3100 Aztec New Mexico 87410 3b. Phone No. 505-333-194			ode) 10. Field and Po Basin Dakota	ol or Exploratory Area (71599)	
4. Location of Well (Footage, Sec., T. 790 FSL 1850 FWL N-05-24N-05W	-		11. County or Parish, State Rio Arriba County, New Mexico		
	CK THE APPROPRIATE BOX	((ES) TO INDICATE NATU			
TYPE OF SUBMISSION		<u></u>	YPE OF ACTION		
Notice of Intent	Acidize Alter Casing	Deepen Fracture Treat	Production (Start/Resur	Well Integrity	
Subsequent Report	Casing Repair Change Plans	New Construction Plug and Abandon	Recomplete Temporarily Abandon	Other Cleanout Repair tubing if needed	
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal		
Open well to flowback tank and ble Changing out hold down pins, repl: ND WH. NU BOP's, Blind, Pipe ar 4/18/2013 SITP - 0 psi, SICP - 440 psi, Open PU, Remove hangar, Install Stripp: Continue to POOH, LD prod pipe, Tally, Fill at 6923 (30' fill) Bttm per	aced one, able to get the oth- nd Annulars, RU Floor. Test well to flowback tank and ble er, PU & RIH w/ 2 jts, Tag on Pipe looks good, 212 jts total	BOP's to 250/1500. Secu eed down. Lay 2nd line to 2nd jt 10' in. POOH, LDd I, SN & Pump out plug.	re well, SDFN flowback tank. 2 tag jts, POOH, LD prod tbe	RCVD MAY 20 '13 OIL CONS. DIV. DIST. 3	
See attached pages for remainder	of procedure and well bore o	diagram.			
 I hereby certify that the foregoing is 	true and correct. Name (Printed	Typed)			
April E. Pohl			tory Specialist		
	$\sim \Lambda \alpha$		1 00/2	, , , , , , , , , , , , , , , , , , , 	
Signature Spril &	5/8h/	Date 5	·1 - 2013	0.045	
Signature Spril &	THIS SPACE F	FOR FEDERAL OR S	TATE OFFICE USE	ACCEPTED FO	
Signature Spri E	THIS SPACE F		TATE OFFICE USE	MAY 1 6 2013	

(Instructions on page 2)

fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false,

4/19/2013

SICP - 20 psi, Open to flowback tank.

PU & RIH w/ 4 3/4" bit, bit sub w/ string float, PU and RIH in singles w/ 2 3/8, L80 tbg, Tag @ 6918 on 219 jts Start air, establish circulation, start mist @ 12 bwph & 600 psi.

Cleanout well from 6918' to PBTD-6953 recovering frac sand, frac balls, parrafin. Pump sweeps off bttm. Still making some sand SD air, POOH w/ 5 jts, Secure well, SDFN.

4/22/2013

SITP - 0 psi, (string float), SICP - 480 psi, Open well to tank and bleed down.

RIH, Tag for fill @ 6936' (17' fill). Start air, Establish Circulation @ 12 bwph mist & 500 psi.

Cleanout/wash from 6936 to 6953'. recovering frac sand. Pumping sweeps, Last sample - Trace sand in 5 gallon sample SD air, Bleed down, POOH w/ 2 3/8 tbg. Secure well, SDFN.

4/23/2013

0 psi (string float), SICP - 380 psi, Open well to flowback tank and bleed down POOH w/ remaining tbg & bit, LD bit, Killed well w/ 20 bbls w/ 15 stds left to pull PU and RIH w/ notched collar, SN on 2 3/8 tbg. Tag bttm @ 6953' on 220 jts and 8' sub, No fill, LD 3 jts PU Hangar, Land Hangar, Total of Knotched Collar (0.40), SN (1.10), 216 jts 2 3/8, 4.7#, L-80, 8rd EUE yellow band tbg (6827.85), 2 3/8" pup jt (8.20) 1 jt tbg, Hangar (.7), EOT- 6881.05), SN - 6880.65. RD Floor, tongs, ND BOP's, NU WH, Test void to 1500 psi. RD Pump and lines, PU Equipment, Too windy to lay down derrick, will lay down in A.M.



Wellbore Schematic

Wet Nar Jicaril	ne LESSE la B-3E Jicarilla 'B'	Basin(New Mexico) Basin(New Mexico) Basin(New Mexico)
1.0	Origina mole, 4/24/2013 1.00.31 FM	Job Details
(CO)	Vertical schematic (actual)	Major Rig Work Over (MRWO) Stant Citio Refats a Date
637		Casing Strings
ا بـــ	AND	Sat Dath
	Tuping Hanger, 11-12; 0.70; 5.1/2; 2-1 Casing Hanger; 11-12; 1.00; 5.1/2; 2-1	Cog Das OD (kg) Whiten (bTi) Grade Top Titread (MD) (bS) Surface 8 5/8 24:90 K-55 322
;	Gasting Hanger; 11-12; 1:00; 5 1:2; 5:002; 2-1	Production Casing 5 1/2 14:00 J-55 7.034
* * }		Tubing Strings
•::	Tuping; 12-43-31.60; 2-36; 1.995; 2-2	Tubing - Production set at 6,881.1ftKB on 4/23/2013 09:00
-1-		Troog Servicion Run Sale Strop Length (ft) Self Depart (ND) (3-55) Tubing - Production 4/23/2013 6.870.05 6.861.
27.5	Tuzing; 12-43: 31.80; 2:38; 1.995; 2-2	(E-m. Des Jas OD (In) WI (Mr); Grade Len (II) Str. (D/G)
:::	1 uarg; ta-2 31.6); 2 36, 1995; 24	Tubing Hanger 5 1/2 0.70 11.
	Tusing Pur John 43-52; 8-20; 2-3-3,	Tubing 1 2 3/8 4.70 L-60 31.80 51. Tubing Pup Joint 1 2 3/8 4.70 L-60 8.20 51.
,	1.995; 2-2	Tubing 216 2 3/8 4.70 L-80 6,827.85 5,879.
· ·	Casting 1.57% 11/322, 311.00; 6 5/3,	Pump Seating Nipple 2 3/8 1.10 5,880.
-444	8,097,14	Notched collar 2 3/8 0.40 6,661.
22-2	Surface Casing Cement; 11-322; 3/27/1961	Perforations
- 6863	Cae'ng John 12-2,597; 2,535,90; 5	Shot Care Entered Shot
2367-	Production Casing Centent; 12-2,597;	
	C11/1551 Slage Tox: 0 597-2,595; 1 00; 6 1/4;	Other Strings
:::.	4957; 2-3	Run Data Pur Date Get Depth (RAS) Com
: 141 -		
:56:-		Other in Hole Ses Top (BKS) 50m (BKS), Rundale Pridate Com-
1400-	Stope Too' 1597-2,995; 1 00, 6 1/4, 4,957; 2-2 Tubing; 52-5,380; 6,827,85; 2 38; 1,995; 2-4	Cement 6.953.0 7,004.0 4/20/1981
2 722 6	Casing John: 2598-4,807; 2,209,00; 5	
	1/2; 4,538° 2-4 Production Casting Cement: 2,500-	
- 1	Production Casting Centert: 2,600- 4,607; 4:11/981 Stage Too; 4:607-4,505; 1:00; 6:1/4; 4,937; 2-5	
44274	4,057, 2-5	
+ 554 -		
45542		
*525.6		
34423	Gasting Abrit 4-898-5,953; 2,145,00; 5	
		4
firt (

1 ALC: -	Puring Seafing Nipp at 6,880-6,831; 1.10; 2.32; 1.780; 2-5	
43424		

642-6	Cased mole 6 665-6.923; 4/20/1951	
48024		
*#50:		

. edit	Plam Cotar, 6,953-6,954; 1.00; 5 1/2; 4,937; 2-7	
4454 -		
15-13	Casing Nort: 6.954-7,003; 49,00; 5	
	1/2; 4,336; 2-5	
1200:		
* 5934	Float Shoe 7,003-7,004; 1,90; 5 t/2;	
*****	Production Casing Centerti 4,900-7,004; 411 1981	
· · · · · ·		
]		JL
	· · · · · · · · · · · · · · · · · · ·	Page 1/1 Report Printed: 4/24/201