

submitted in lieu of Form 3160-5

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT Sundry Notices and Reports on Wells

MAY 28 2013

Farmington Field Office Bureau of Land Managemen.

Sundry No	otices and Reports or	1 vveiis		
		*	5.	Lease Number NM 18322
1. Type of Well	and the same		6.	If Indian, All. or
Gas X			-	Tribe Name
			7.	Unit Agreement Name
2. Name of Operator				
Schalk Development Company			8.	Well Name & Number
3. Address & Phone No. of Operator		, _ , ,	0.	Schalk 29-4 #10
o. Address at hone its. of operator				Ochan 25-4 #10
P.O. Box 25825, Albuquerque, NM 87125			9.	API Well No.
				30-039-22765
Location of Well, Footage, Sec., T, R, M			10.	Field and Pool
0.001 F.01 .0.001 F.1/1 .0				Choza Mesa PC
980' FSL & 800' FWL, Section 23, T-29-N, I	₹-4-VV,		44	0
•			11.	County & State Rio Arriba County, NM
				Rio Amba County, Nivi
Final Abandonment — Casing — Alterin — Other - 13. Describe Proposed or Completed Operat The operator P&A'd the above well per the at	g Casing (Production test ons	Vater Shut off Conversion to Injec	-	DIST. 3
14. I hereby certify that the foregoing is true	and correct.			
Signed ack crane	Title Production	Superintendent	Data	May 22, 2042
Jack Evans	Title <u>Froduction</u>	Superinterident	Date _	May 23, 2013
Odok Evans				
(This space for Federal or State Office use)				
APPROVED BY	Title			_ Date
CONDITION OF APPROVAL, if any:				
Title 18 U.S.C. Section 1001, makes it a crime for	r any person knowin	gly to make to any	depart	ment or agency of the
United States any false, fictitious or fraudulent st	atements or represer	ntations as to any n	natter v	within its jurisdiction.
		·		•
		3.2	CONT.	MARCH MECONO

NWOCD

MAY 3 0 2013 PACKERGTON FIELD OFFICE Fil Jim

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979 Farmington, New Mexico 87499 505-325-2627 *fax: 505-325-1211

Schalk Development Schalk 29-4 #10

May 2, 2013 Page 1 of 2

930' FSL and 800' FWL, Section 23, T-29-N, R-4-W Rio Arriba County, NM Lease Number: NM 18322 API #30-039-22765

Plug and Abandonment Report Notified NMOCD and BLM on 4/26/13

Plug and Abandonment Summary:

- Plug #1 spot 24 sxs (28.32 cf) Class B cement inside casing from 4915' to 4591' to cover the Chacra top. Tag TOC at 4648'.
- Plug #2 spot 44 sxs (51.92 cf) Class B cement inside casing from 3995' to 3400' to cover the Pictured Cliffs, Fruitland, Kirtland and Ojo Alamo tops. Tag TOC at 3424'.
- Plug #3 spot 24 sxs (28.32 cf) Class B cement inside casing from 2378' to 2054' to cover the Nacimiento top. Tag TOC at 2106'.
- Plug #4 spot 137 sxs (161.66 cf) Class B cement inside casing from 357' to surface, circulate good cement out bradenhead valve.
- Plug #5 spot 22 sxs (25.96 cf) Class B cement to top off casings and install P&A marker.

Plugging Work Details:

- 4/26/13 MOL and RU. Check well pressures: SITP 600 PSI, SICP 45 PSI and SIBHP 1 PSI. RU relief lines to pit and blow well down. ND wellhead. NU BOP and test. PU on tubing string and LD hanger. SI well. SDFD.
- 4/29/13 Check well pressures: casing 35 PSI, tubing 500 PSI and bradenhead 0 PSI. Blow well down. TOH and inspect 131 joints 2-3/8" tubing and SN; total 4114.92'. Found tubing pitted past 3900'. Round trip 4.5" casing scraper to 3995'. PU tubing (with 27 joints A+ workstring) and TIH to 4915'. RU pump to bradenhead valve and pump 20 bbls; BH on a vacuum. RU pump to tubing and establish circulation out casing valve with 48 bbls of water. Pump total 70 bbls of water. Spot Plug #1. PUH and WOC. SI well. SDFD.
- 4/30/13 Check well pressures: casing 10 PSI, bradenhead 0 PSI and tubing has plugging sub at 2641'. TIH with tubing and tag TOC at 4648'. TOH and LD tubing. PU 4.5" DHS cement retainer and TIH; set at 3995'. Pressure test tubing to 1000#. Sting out of CR. Establish circulation and load casing with 65 bbls of water. Attempt to pressure test casing to 800#; bled down to 600# in 30 seconds. TOH with tubing and LD setting. RU A-Plus wireline and run CBL from 3985' to surface. Called TOC at 1560'. TIH with tubing to CR at 3995'. J. Hagstrom, BLM, and B. Powell, NMOCD, approved procedure changes. Spot Plug #2 to estimated TOC at 3400'. PUH. SI well. SDFD.

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979 Farmington, New Mexico 87499 505-325-2627 *fax: 505-325-1211

Schalk Development Schalk 29-4 #10 May 2, 2013 Page 2 of 2

Plugging Work Details (continued):

- 5/1/13 Open up well; no pressures. TIH and tag TOC at 3424'. PUH to 2378'. Attempt to pressure test casing; same results. Spot Plug #3 mixed 2% Calcium Chloride with cement to estimate TOC 2054'. PUH and WOC. TIH and tag TOC at 2106'. TOH and LD tubing. Pressure test casing to 800#. Perforate 3 squeeze holes at 357'. Pump down casing 2 bpm at 700# and establish circulation out bradenhead valve with 30 bbls of water. Pumped 50 bbls ahead; returns not fully cleaned up. Spot Plug #4 to surface. SI well. SDFD.
- 5/2/13 Open up well; no pressures. Found cement down 30' in 4.5" casing. ND BOP. Dig out wellhead. Write Hot Work Permit. Cut off wellhead. Found cement down 2' in annulus. Spot Plug #5 and install P&A marker. RD and MOL.

John Hagstrom and Mark Decker, BLM representatives, were on location.