

RECEIVED

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

MAY 30 2013

FORM APPROVED  
OMB No. 1004-0137  
Expires: October 31, 2014**SUNDRY NOTICES AND REPORTS ON WELLS**  
**Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.**5. Lease Serial No.  
NMSL - 079601  
6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on page 2.

## 1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

7. If Unit of CA/Agreement, Name and/or No.

## 2. Name of Operator

"Pre-Ongard" well operator AKA Four Star Oil &amp; Gas Company

8. Well Name and No.  
"Pre-Ongard" Well #6 AKA Lydia Rentz #6

## 3a. Address

ATTN: Regulatory Specialist  
332 Road 3100 Aztec New Mexico 87410

## 3b. Phone No. (include area code)

505-333-1941

9. API Well No.  
30-039-05878

## 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1190 FSL 1450 FWL N-20-25N-03W

10. Field and Pool or Exploratory Area  
Basin Fruitland Coal11. County or Parish, State  
Rio Arriba County, New Mexico

## 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other Complete P&A activities of 2001
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

Following plugging and abandonment done in 2001, the landowner was to have assumed ownership as a water well and provided documentation to that effect. However, due to the lack of progress in that area, Four Star Oil & Gas has decided to complete the plug and abandonment process to include the fresh water zone.

The project is slated to begin July 31, 2013

RCVD JUN 5 '13  
OIL CONS. DIV.  
DIST. 3

- MIRU workover rig and equipment. ND wellhead. NU BOP's. Test BOP's.
- RU tubing handling equipment. POOH with 2-7/8" tubing and stator pump
- Order out workstring for cleanout and cmt operations.
- RUN CBL from 3100' (PBDT) - STAY IN CONTACT WITH NMOCD TO DETERMINE NEXT STEP Place a cement plug from 2138'-2038'
- PU 5-1/2" CMT Retainer and set at 500'. Set a cement plug 280'-180'
- MIRU CMT provider; establish injection down workstring and pump 500 SKS of class G neat cement on top of retainer. SI Braden head valves once good CMT has circulated to surface.
- Pump remainder of CMT. Sting out of retainer and pump 15 sks of CMT on top of retainer. Pull up and reverse circulate clean up tubing and TOOH.
- Pull up hole 50' and set a CMT plug 8 sks CMT. TOOH. ND BOP cut of wellhead, top fill with CMT. Weld on dry hole marker.
- RDMO.

Notify NMOCD 24 hrs  
prior to beginning  
operations

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)

April E. Pohl

Title Regulatory Specialist

Signature

*April E Pohl*

Date

*May 30, 2013*

## THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Original Signed: Stephen Mason

Title

Date

JUN 03 2013

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

NMOCD




**Lydia Rentz #6**  
**Rio Arriba County, New Mexico**  
**Proposed well bore schematic**

API: 30-039-0587800  
Legals: Sec 20 - T 25N - R 3W  
Field: Blanco MV

KB Elev 7369'  
Gr Elev 7362'

Geologic Tops:	
San Jose	Surface
Nacimiento	500'
Ojo Alamo	3420'
Kirtland	3555'
Fruitland	3667'
Pictured Cliffs	3773'
Lewis	3809'



Prepared by: Jamie Elkington  
Date: 5/13/2013

Revised by:  
Date:




**Lydia Rentz #6**  
**Rio Arriba County, New Mexico**  
**Proposed well bore schematic**

API: 30-039-0587800  
Legals: Sec 20 - T 25N - R 3W  
Field: Blanco MV

KB Elev 7369'  
Gr Elev 7362'

Geologic Tops:	
San Jose	Surface
Nacimiento	500'
Ojo Alamo	3420'
Kirtland	3555'
Fruitland	3667'
Pictured Cliffs	3773'
Lewis	3809'



Prepared by: Jamie Elkington  
Date: 5/13/2013

Revised by:  
Date:

UNITED STATES DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT  
FARMINGTON DISTRICT OFFICE  
6251 COLLEGE BLVD.  
FARMINGTON, NEW MEXICO 87402

Attachment to notice of  
Intention to Abandon:

Re: Permanent Abandonment  
Well: 6 Lydia Rentz

CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.
3. The following modifications to your plugging program are to be made:
  - a) Place a cement plug from 2138' – 2038' to cover the Nacimiento top inside and outside the 5 ½" casing.
  - b) Place the Surface Casing Shoe plug from 280' – 180'.

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.