Submit 3 Copies To Appropriate District Office Energy	State of New Mex			Form C-103	
District I 1625 N. French Dr., Hobbs, NM 87240	Minerals and Natur	al Kesources	WELL API NO.	June 19, 2008	
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION			30-039-21334		
District III 1220 South St. Francis Dr.			5. Indicate Type STATE	e of Lease FEE X	
1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 District IV			6. State Oil & C		
1220 S. St. Francis Dr., Santa Fe, NM 87505			NMSF 078912		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name: Lindrith Unit Com		
1. Type of Well: Oil Well Gas Well X Other			8. Well Number	91	
2. Name of Operator Energon Poscureos Corporation			1	9. OGRID Number 162928	
Energen Resources Corporation 3. Address of Operator				10. Pool name or Wildcat	
2010 Afton Place. Farmington, NM 87401			South Blanco Pictured Cliffs		
4. Well Location				·	
Unit Letter N : 1130' fe	eet from the Sout	th line and	1800' feet i	from the West line	
		Range 02W	NMPM	County Rio Arriba	
11. Elevat	tion <i>(Show whether L</i> 7168	<i>DR, RKB, RT, GR, .</i> 3' GL	etc.)		
12. Check Appropriate			Report or Othe	er Data	
12. Check Appropriate	Dox to indicate is	valure of Notice	, Report, or Our	51 Data	
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK PLUG ANI	D ABANDON 🔲	REMEDIAL WORK		ALTERING CASING	
TEMPORARILY ABANDON CHANGE	PLANS 🔲	COMMENCE DRIL	LING OPNS. 🔲	P AND A	
PULL OR ALTER CASING	E COMPL	CASING/CEMENT	JOB 🗆	274.240°4	
DOWNHOLE COMMINGLE			ı	RCVD JUL 2'13 OIL CONS. DIV.	
				DIST. 3	
OTHER:		OTHER:			
 Describe proposed or completed operations. of starting any proposed work). SEE RULE or recompletion. 	-	-	•	=	
Energen Resources permanently plugge procedure.	ed and abandoned	the Lindrith Un	it Com 91 accord	ing to the attached	
OCD was notified that bradenhead pro and did not build back up, so no bra authorization to continue P&A activ- Approved for plugging of wellbore only Liability under bond is retained pendin Receipt of C-103 (Subsequent Report of	adenhead gas samp ities. .g. DNN 0	les were able to			
Spud Date Plugging) which may be found @ OCD page under forms www.emnrd.state.us/ocd	web Rig Releas	e Date:	4/4/13		
I hereby certify that the information above is true	and complete to the b	est of my knowled	ge and belief.		
SIGNATURE OUL MANUE	L TITL	<u>E</u> Distric	<u>t Engineer</u>	DATE 7/1/13	
Type or print name <u>Collin Placke</u>	E-ma	cplacke@ene il address:	ergen.com	PHONE <u>505.325.6800</u>	
For State Use Only		Deputy Oil 8	Gas Inspecto	or,	
APPROVED BY 134 / Yell	TITI		trict #3	DATE 7/5/13	
Conditions of Approval (if any):	PY				

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979 Farmington, New Mexico 87499 505-325-2627 *fax: 505-325-1211

Energen Resource Corporation Lindrith Unit Com #91

April 4, 2013 Page 1 of 2

1130' FSL and 1800' FWL, Section 29, T-24-N, R-02-W Rio Arriba County, NM Lease Number: Fee API #30-039-21334

Plug and Abandonment Report Notified NMOCD and BLM on 3/28/13

Plug and Abandonment Summary:

- Plug #1 with existing CIBP at 2995' with 12 sxs Class B cement inside casing from 2995' to 2560' to isolate the Pictured Cliffs interval and cover the Fruitland, Kirtland and Ojo Alamo tops.
- Plug #2 with CR at 1382', mix and pump 44 sxs Class B cement, squeeze 35 sxs outside 2-7/8" casing and leave 9 sxs inside casing to cover the Nacimiento top.
- Plug #3 mix and pump 57 sxs Class B cement down 2-7/8" casing from 160' to surface, circulate good cement to pit.
- Plug #4 spot 28 sxs Class B cement to top off surface casing and install P&A marker.

Plugging Work Details:

- 3/28/13 MOL and RU. Check well pressures: casing 50# and bradenhead 20#. Note: no tubing in well. Layout relief lines and blow well down. ND wellhead. NU BOP and test. Change over for 1-1/4" tubing. Round trip 2-1/4" gauge ring to 3030'. PU 2-7/8" wireline CIBP and RIH; set at 3006'. SI well. SDFD.
- 3/29/13 Check well pressures: casing 45# and bradenhead 30#. Blow well down. RU Basin Wireline Truck. Top well off with 17 bbls of water. Run CBL from 3006' (top of existing CIBP) to surface. Log shows TOC at 2350'. No bond from 2350' to 610' and bond from 610' to 210'. No cement to surface. Emailed log to Collin Placke, Energen and Charlie Perrin, NMOCD for review. SI well. SDFD.
- 4/1/13 Open up well; no pressures. Casing on a vacuum. Bradenhead was left open to vent. SI bradenhead for 10 minutes; pressure was 5#. TIH with 92 joints tubing workstring and tag existing CIBP at 2995'. Circulate well clean with 16 bbls of water. Attempt to pressure test casing 750#; leak 1 bpm. Spot Plug #1 with existing CIBP at 2995' with 12 sxs Class B cement inside casing from 2995' to 2560' to isolate the Pictured Cliffs interval and cover the Fruitland, Kirtland and Ojo Alamo tops. TOH with tubing. SI well and WOC. Note: supervisor and 2 hands stayed behind to check bradenhead pressure and catch gas sample. After 2 hours bradenhead pressure was less than 1#; unable to catch sample. SDFD.

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979 Farmington, New Mexico 87499 505-325-2627 *fax: 505-325-1211

Energen Resource Corporation Lindrith Unit Com #91 April 4, 2013 Page 2 of 2

Plugging Work Details Cont'd:

- Check well pressures: casing 0# and bradenhead less than 1#; unable to catch gas sample. TIH with tubing and tag Plug #1 good at 2572'. Attempt to pressure test casing; leak 1 bpm at 750#. C. Perrin, NMOCD, approved to continue P&A as approved. TOH with tubing. Perforate 3 bi-wire squeeze holes at 1382'. PU 2-7/8" wireline cement retainer and RIH; set at 1382'. PU stinger and TIH. Attempt to pressure test casing; same results. Sting into CR and establish rate into squeeze holes 2 bpm at 950#. Plug #2 with CR at 1382', mix and pump 44 sxs Class B cement, squeeze 35 sxs outside 2-7/8" casing and leave 9 sxs inside casing to cover the Nacimiento top. TOH and LD tubing. SI well. SDFD.
- Check well pressures: casing 23# and bradenhead 0#. Open up well and blow down pressure. TIH with tubing and tag Plug #2 good at 1100'. TOH and LD tubing. Attempt to pressure test casing, leak 1 bpm at 700#. Perforate 3 bi-wire squeeze holes at 160'. Note: John Durham with NMOCD approved procedure change. Perform dye test; bradenhead circulated 1.5 bbls and circulated dye in returns after 9.5 bbls. Note: John Durham approved procedure change. Plug #3 mix and pump 57 sxs Class B cement down 2-7/8" casing from 160' to surface, circulate good cement to pit. SI well and WOC. Dig out wellhead. ND BOP. Issue Hot Work Permit. Cut off wellhead. Found cement at surface in 8-5/8" x 2-7/8" annulus and down 46' in 2-7/8" casing. RD rig and equipment. Plug #4 spot 28 sxs Class B cement to top off surface casing and install P&A marker. SDFD.

4/4/13 MOL.

John Durham, NMOCD representative, was on location.