Submit 3 Copies To Appropriate District	State of New M	lexico	Form C-103
Office District I	Energy, Minerals and Natural Resources		Jun 19, 2008
1625 N. French Dr., Hobbs, NM 88240	837		WELL API NO.
District II	OIL CONSERVATION	N DIVISION	30-045-25676
1301 W. Grand Ave., Artesia, NM 88210 District III	1220 South St. Fra		5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 8		STATE FEE
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	Sama re, Nivi e	37303	6. State Oil & Gas Lease No. FEE
	ICES AND REPORTS ON WELL	Ś	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			Decker A
1. Type of Well: Oil Well ☐ Gas Well ☒ Other P&A			8. Well Number 2E
2. Name of Operator			9. OGRID Number
Burlington Resources Oil Gas Company LP			14538
3. Address of Operator P.O. Box 4289, Farmington, NM 87499-4289			10. Pool name or Wildcat Basin Dakota
4. Well Location			
Unit Letter B : 790	feet from the North	line and1830	feet from the <u>East</u> line
Section 3		ange 12W	NMPM San Juan County
	11. Elevation (Show whether D		
the second se		8' GR	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING			
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPNS.☐ P AND A ☐			
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMEN	IT JOB
DOWNHOLE COMMINGLE			
OTHER:		OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated dat			
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion			
or recompletion.			DAUST TIBLE ACTOR
			RCVD JUN 26'13
The subject well was P&A'd on 5/28/13 per the attached report.			OIL CONS. DIV.
			DIST. 3
Spud Date:	Rig Re	leased Date:	
,		0110	
I handy contify that the information		MICOU	14
I hereby certify that the information	above is true and complete to the	best of my knowledg	ge and belief.
SIGNATURE (1) Allig	J (Susse TITLE_	Staff Regulatory	Technician DATE <u>6/25/13</u>
Type or print name Dollie L. Busse E-mail address: dollie.l.busse@conocophillips.com PHONE: 505-324-6104			
For State Use Only		_	•
APPROVED BY: Bol D	TITLE_		Gas Inspector, ict #3 DATE 7/5/13
Conditions of Approval (if any):	Av		
,	` `	Approved for	r plugging of wellbore only.
		Liability und Receipt of C	er bond is retained pending.
		Plugging) wh	103 (Subsequent Report of Well ich may be found @ OCD web
•	•	page under fo	orms
		www.emnrd.	

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979 Farmington, New Mexico 87499 505-325-2627 *fax: 505-325-1211

Burlington Resources

Decker A 2E

May 28, 2013 Page 1 of 2

790' FNL and 1830' FEL, Section 3, T-31-N, R-12-W San Juan County, NM Lease Number: Fee API #30-045-25676

Plug and Abandonment Report Notified NMOCD and BLM on 5/17/13

Plug and Abandonment Summary:

- Plug #1 with CR at 7097' spot 13 sxs (15.34 cf) Class B cement inside casing from 7097' to 6926' to cover the Dakota top.
- Plug #2 with 12 sxs (14.16 cf) Class B cement inside casing from 5412' to 5254' to cover the Mancos top.
- **Plug #3** with 34 sxs (40.12 cf) Class B cement inside casing from 4938' to 4639' with 15 sxs in 4.5" casing, 19 sxs in 7" casing to cover the intermediate shoe casing and liner top.
- Plug #4 with 29 sxs (34.22 cf) Class B cement inside casing from 4315' to 4160' to cover the Mesaverde top.
- Plug #5 with CR at 3770' spot 55 sxs (64.9 cf) Class B cement inside casing from 3812' to 3658' with 26 sxs in annulus, 8 sxs below CR, 21 sxs above CR to cover the Chacra top.
- Plug #6 with 29 sxs (34.22 cf) Class B cement inside casing from 2607' to 2453' to cover the Pictured Cliffs top.
- Plug #7 with 29 sxs (34.22 cf) Class B cement inside casing from 2042' to 1880' to cover the Fruitland top.
- Plug #8 with 57 sxs (67.26 cf) Class B cement inside casing from 1815' to 1511' to cover the Kirtland top.
- **Plug #9** with 122 sxs (143.96 cf) Class B cement with 52 sxs, 70 sxs in annulus from 278' to surface to cover the surface casing shoe.
- Plug #10 spot 35 sxs Class B cement and install P&A marker.

Plugging Work Details:

- 5/20/13 Rode rig and equipment to location. Spot in and RU. Check well pressures: tubing 280 PSI, casing 340 PSI and bradenhead 0 PSI. RU relief lines. SI well. SDFD.
- 5/21/13 Bump test H2S equipment. Check well pressures: tubing 280 PSI, casing 340 PSI and bradenhead 0 PSI. Blow well down. ND wellhead and NU BOP. Pressure test pipe rams to 300 PSI and 1500 PSI, OK. Pull tubing hanger. TOH and tally 116 stands, 5 joints, SN, MA (238 joints) total 2-3/8" tubing EUE, total 7241'. Round trip 4.5" mill to 7123'. SI well. SDFD.
- 5/22/13 Bump test H2S equipment. Check well pressures:- no tubing, casing 280 PSI and bradenhead 0 PSI. Attempt to TIH, found broken wires in drill line. Wait on drill line. Change out drill line. TIH with 4.5" DHS CR and set at 7097'. Pressure test tubing to 1000 PSI. Establish circulation. Pressure test casing to 800 PSI, OK. SI well. SDFD.

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979 Farmington, New Mexico 87499 505-325-2627 *fax: 505-325-1211

Burlington Resources **Decker A 2E**

May 28, 2013 Page 2 of 2

Plugging Work Details (continued):

- 5/23/13 Bump test H2S equipment. Check well pressures: tubing and casing 410 PSI and bradenhead 0 PSI. Blow well down. RU Blue Jet wireline. Ran CBL from 7097' to surface, TOC at 390'. Establish circulation. Spot plugs #1, #2, #3 and #4. SI well. SDFD.
- 5/24/13 Bump test H2S equipment. Open up well; no pressures. RIH with 7" gauge ring, found tight spot from 3675' to 3705', work through to 3800'. Perforate 3 HSC squeeze holes at 3812'. Establish rate of 1 bpm at 1000 PSI. TIH with 7" DHS CR and set at 3770'. Establish circulation rate of 1 bpm at 800 PSI. Spot plugs #5, #6, #7 and #8. Perforate 3 HSC squeeze holes at 278'. Spot plug #9 with estimated TOC at surface. SI well. SDFD.
- 5/28/13 Bump test H2S equipment. ND BOP. Dig out wellhead. RU High Desert and cut off wellhead. Found cement at surface. Spot plug #10 and install P&A marker. RD and MOL.

Jim Morris, MVCI representative, was on location. John Durham, NMOCD representative, was on location.