

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office to
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Burlington Resources Oil & Gas Company	Contact Crystal Tafoya
Address 3401 East 30th St, Farmington, NM	Telephone No. (505) 326-9837
Facility Name: Hare 14A	Facility Type: Gas

Surface Owner BLM	Mineral Owner BLM (SF-076958)	API No. 30-045-29527
--------------------------	--------------------------------------	-----------------------------

LOCATION OF RELEASE

Unit Letter C	Section 10	Township 29N	Range 10W	Feet from the 1175	North/South Line North	Feet from the 1710	East/West Line West	County San Juan
-------------------------	----------------------	------------------------	---------------------	------------------------------	----------------------------------	------------------------------	-------------------------------	---------------------------

Latitude 36.74496 Longitude 107.87481

NATURE OF RELEASE

Type of Release Produced Water / Hydrocarbon	Volume of Release 11bbls / 35bbls	Volume Recovered None
Source of Release Oil Production Tank	Date and Hour of Occurrence Unknown	Date and Hour of Discovery 6/10/2013 at 7:30 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? BLM - Mark Kelly & NMOCD - Jonathan Kelly	
By Whom? Crystal Tafoya	Date and Hour 6/12/2013 at 7:00 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*



1/4" hole discovered on the weld near the bottom of the oil production tank due to suspected corrosion allowing 35bbls Hydrocarbon (crude oil) and 11bbls Produced Water to be released. No fluid was recovered and the well was immediately shut-in. The release did not leave location. Impacted soil was treated with Simple Green immediately.

Describe Area Affected and Cleanup Action Taken.*

ConocoPhillips will assess the soil to determine a path forward for clean-up if necessary.

OIL CONS. DIV. DIST. 3
JUN 12 2013

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Crystal Tafoya		Approved by Environmental Specialist: 	
Title: Field Environmental Specialist		Approval Date: 7/11/2013	Expiration Date:
E-mail Address: crystal.tafoya@conocophillips.com		Conditions of Approval:	Attached <input type="checkbox"/>
Date: 6/12/2013 Phone: (505) 326-9837			

* Attach Additional Sheets If Necessary

nJK1319051750