(Submit 3 Copies To Appropriate District Office	State of New Me			Form C-103	
District_1	Energy, Minerals and Natu	iral Resources	WELL API NO.	June 19, 2008	
1625 N. French Dr., Hobbs, NM 87240 District II	OIL CONSERVATION DIVISION		30-045-30341		
1301 W. Grand Ave., Artesia, NM 88210 District III	1220 South St. Francis Dr.		5. Indicate Type of Lease		
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505		STATE FEE 🗷		
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505			6. State Oil & Gas	Lease No.	
		OR PLUG BACK TO A	7. Lease Name or TEXAKOMA LA PLA	Unit Agreement Name:	
1. Type of Well: Oil Well Gas Well X Other			8. Well Number		
2. Name of Operator					
XTO Energy Inc.			ļ		
3. Address of Operator			10. Pool name or Wildcat		
4. Well Location	MEXICO 87410		BASIN FRUITLAND	COAL	
Unit LetterA :	1296 feet from the NO	RTH line and	665 feet from	m the EAST line	
Socian	Township agar	Dance 10**	NIMDM	Country	
Section 18	Township 31N 11. Elevation (Show whether	Range 13W	NMPM	County SAN JUAN	
\		579 <u>6'</u>			
12. Check A	ppropriate Box to Indicate	Nature of Notice.	Report, or Other	Data	
The second second	11F	,	1 ,		
NOTICE OF INTENTION TO:			SSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK				ALTERING CASING	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILL	INC OPNS	P AND A	
				F AND A	
PULL OR ALTER CASING	MULTIPLE COMPL L	CASING/CEMENT	ю П		
DOWNHOLE COMMINGLE					
OTHER:		OTHER:			
13. Describe proposed or complete of starting any proposed work). or recompletion.	d operations. (Clearly state all persons SEE RULE 1103. For Multiple	ertinent details, and gi			
XTO Energy Inc. intends t	o plug and abandon this we	ell per the attach	ed procedure. Ple	ase see also the	
attached current and prop	osed wellbore diagrams.				
	an rons	, DIV DIST. 3	••		
	OlFooras	1 2 2013	Notify N Prior t	MOCD 24 hrs to beginning	
	AUG	1 2 2010	ope	erations	
<u></u>					
Spud Date:	Rig Relea	ase Date:			
I hereby certify that the information	above is true and complete to the	e best of my knowledg	ge and belief.		
X(), a, a, C	1 marrow				
SIGNATURE	TIT TIT		ORY ANALYST	DATE <u>8/8/2013</u>	
Type or print name SHERRY J. MOR	ROW E-n	sherry_morrow@x nail address:		PHONE <u>505-333-3630</u>	
For State Use Only	21		Gas Inspector,	3-13-16	
APPROVED BY			rict #3	DATE	
Conditions of Approval (if any):	,	^			

LWA	
TKK	
Approved]	

PLUG AND ABANDONMENT PROCEDURE

June 13, 2013

Texakoma La Plata 18-1

Basin Fruitland Coal
1296' FNL and 665' FEL, Section 18, T31N, R13W
San Juan County, New Mexico / API 30-045-30341
Lat: ______ / Lat: ______

Note: All cement volumes use 100% excess outside pipe and 50' excess inside. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be Class B, mixed at 15.6 ppg with a 1.18 cf/sx yield.

- 1. This project requires a NMOCD C-144 CLEZ Closed-Loop System Permit for the use of an A-Plus steel tank to handle waste fluids circulated from the well and cement wash up.
- Install and test location rig anchors. Comply with all NMOCD, BLM, and Operator safety
 regulations. MOL and RU daylight pulling unit. Conduct safety meeting for all personnel on
 location. Record casing, tubing and bradenhead pressures. NU relief line and blow down well.
 Kill well with water as necessary and at least pump tubing capacity of water down the tubing. ND
 wellhead and NU BOP. Function test BOP.
- 3. Rods: Yes_X__, No____, Unknown____.
 Tubing: Yes_X_, No____, Unknown____, Size____2.375"__, Length ____1650'__.
 Packer: Yes____, No_X__, Unknown_____, Type_____.

 If this well has rods or a packer, then modify the work sequence in step #2 as appropriate.
- 4. Plug #1 (Pictured Cliffs top and Fruitland interval, 1606' 1013'): Round trip 4.5" gauge ring to 1606' or as deep as possible. RIH and set 4.5" cement retainer at 1606'. Pressure test tubing to 1000 PSI. Circulate well clean. Attempt to pressure test casing to 800 PSI. If casing does not test then spot or tag subsequent plugs as appropriate. Mix 49 sxs Class B cement inside casing to isolate the Pictured Cliffs top and Fruitland interval. PUH.
- 5. Plug #2 (8.625" casing shoe, 585' 0'): Attempt to pressure test the bradenhead annulus to 300 PSI; note the volume to load. If the BH annulus holds pressure, then establish circulation out casing valve with water. Mix approximately 48 sxs cement and spot a balanced plug from 585' to surface, circulate good cement out casing valve. TOH and LD tubing. Shut well in and WOC. If the BH annulus does not test, then perforate at the appropriate depth and attempt to circulate cement to surface filling the casing from 181' and the annulus from the squeeze holes to surface. Shut in well and WOC.
- 6. ND BOP and cut off casing below surface casing flange. Install P&A marker with cement to comply with regulations. RD, move off location, cut off anchors and restore location.

Texakoma La Plata 18-1

Current

Basin Fruitland Coal

1296' FNL, 665' FEL, Section 18, T-31-N, R-13-W, San Juan County, NM / API #30-045-30341

Today's Date: 6/13/13

Spud: 8/30/00

Completed: 10/25/00

Elevation: 5796' GL

5801' KB


8-3/4" hole

Ojo Alamo @ 535'

Fruitland @ 1063'

Pictured Cliffs @ 1735'

6-1/4" hole



TD 1839' PBTD 1791' TOC circulated to surface per sundry notice

7" 20#, J-55 Casing set @ 172' Cement with 65 sxs, circulated to surface

2.375" tubing at 1650' (54 jts, perf sub, SN with rods and pump)

Fruitland Coal Perforations: 1656' ~ 1672'

4.5", 10.5#, J-55 Casing set @ 1839' Cement with 225 sxs Circulate cement to surface

Texakoma La Plata 18-1

Proposed P&A

Basin Fruitland Coal

1296' FNL, 665' FEL, Section 18, T-31-N, R-13-W, San Juan County, NM / API #30-045-30341 Lat ______ / Long ______

Today's Date: 6/13/13

Spud: 8/30/00

ř

Completed: 10/25/00

Elevation: 5796' GL

5801' KB


8-3/4" hole

Ojo Alamo @ 535'

Fruitland @ 1063'

Pictured Cliffs @ 1735'

6-1/4" hole



TD 1839' PBTD 1791' TOC circulated to surface per sundry

7" 20#, J-55 Casing set @ 172' Cement with 65 sxs, circulated to surface

Plug #2: 585' - 0' Class B Cement, 48 sxs

Plug #1: 1606' - 1013' Class B Cement, 49 sxs

Set CR @ 1606'

Fruitland Coal Perforations: 1656' – 1672'

4.5", 10.5#, J-55 Casing set @ 1839' Cement with 225 sxs Circulate cement to surface