Submit 3 Copies To Appropriate District Office	State of New Mexico		Form C-103 Jun 19, 2008
<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources		WELL API NO.
District II	OIL CONSERVATION DIVISION		30-045-09456
1301 W. Grand Ave., Artesia, NM 88210 District III	1220 South St. Francis Dr.		5. Indicate Type of Lease STATE STATE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505		6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	· · · · · · · · · · · · · · · · · · ·		E-10796
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			7. Lease Name or Unit Agreement Name State Com T
PROPOSALS.) 1. Type of Well: Oil Well 🔲 Gas Well 🔀 Other <b>P&amp;A</b>			8. Well Number 16
2. Name of Operator			9. OGRID Number
ConocoPhillips Company			217817
3. Address of Operator			10. Pool name or Wildcat
P.O. Box 4289, Farmington, NM 87499-4289			Aztec PC
4. Well Location	<u> </u>		L
Unit Letter M : 935	feet from the <u>South</u>	line and840	feet from the <u>West</u> line
Section 16		ange 11W	NMPM San Juan County
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 5678' GR			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:   PERFORM REMEDIAL WORK I PLUG AND ABANDON I TEMPORARILY ABANDON I CHANGE PLANS I COMMENCE DRILLING OPNS. P AND A			
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT	L DOB
OTHER:			
	leted operations. (Clearly state all		I give pertinent dates, including estimated date
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion			
or recompletion.			
			RCVD AUG 21 '13
The subject well was P&A'd on 7/17/13 per the attached report.			
Approved for plugging of wellbore only. Liability under bond is retained pending.			DIST. 3
	Receipt of C-103 (Subse	retained pending.	
Spud Date: Plugging) which may be found @ OCD web			
PNR ONLY page under forms www.emnrd.state.us/ocd			
I hereby certify that the information above is true and complete to the sector and belief.			
	~ <i>\$</i>	ى . <u> ر دە دەر .</u>	
SIGNATURE PORT Or	UNY	Regulatory Techn	icianDATE8/16/13
Type or print nameDenise Journey E-mail address:Denise.Journey@conocophillips.comPHONE: 505-326-9556			
For State Use Only Deputy Oil & Gas Inspector,			
APPROVED BY:	TITLE	District	
Conditions of Approval (if any):			
•• • • • • • • • • • • • • • • • • • • •	• •		

Alp

## A-PLUS WELL SERVICE, INC.

P.O. BOX 1979 Farmington, New Mexico 87499 505-325-2627 \*fax: 505-325-1211

## Conoco Phillips State Com T #16

July 17, 2013 Page 1 of 1

935' FSL and 840' FWL, Section 16, T-30-N, R-11-W San Juan County, NM Lease Number: E-10796 API #30-045-09456

Plug and Abandonment Report Notified NMOCD and BLM on 7/11/13

## Plug and Abandonment Summary:

- Plug #1 with CIBP at 2012' spot 80 sxs (94.4 cf) Class B cement inside casing from 2012' to 1306' to cover the Pictured Cliffs and Fruitland tops.
- Plug #2 with CR at 720' spot 124 sxs (146.33 cf) Class B cement inside casing from 765' to 498' with 6 sxs below, 25 sxs above and 93 sxs outside to cover the Ojo Alamo and Kirtland tops.
- **Plug #3** with 93 sxs (109.74 cf) Class B cement inside casing from 140' to surface' with 16 sxs inside and 77 sxs outside to cover the surface casing shoe.
- Plug #4 with 32 sxs Class B cement top off casings and install P&A marker.

## Plugging Work Details:

- 7/11/13 Transfer tools and equipment. SDFD.
- 7/12/13 Road rig and equipment to location. Spot in and RU. Perform start well inspections. Check well pressures: tubing 700 PSI, casing 100 PSI and bradenhead TSTM. Blow well down. ND wellhead. Strip on BOP and function test. Could not test BOP due to 1". LD joints on Double S Hot Shot trailer 99 joints, of 1" tubing total 2079'. SI well. SDFD.
- 7/15/13 Check well pressures: no tubing and casing 100 PSI. Blow well down and change out piperams. TIH and tally 5.5 string mill to 2013'. RU Blue Jet wireline. RIH with gauge ring and set at 2012'. Establish circulation. Attempt to pressure test casing lost 40# in 5 minutes, leak. SI well. SDFD due to weather conditions.
- 7/16/13 Open up well; no pressures. RU Blue Jet wireline. Ran CBL from 2012' to surface, with estimated TOC at 2000'. Pressure test casing to 800 PSI, OK. Establish circulation. Spot plug #1 with estimated TOC at 1306'. RU Blue Jet wireline. Perforate 3 HSC squeeze holes at 765'. Establish rate of 3 bpm at 500 PSI. TIH with 5.5 DHS CR and set at 720'. Spot plug #2 with estimated TOC at 498'. RU Blue Jet wireline. Perforate 3 HSC squeeze holes at 140'. Establish circulation. ND BOP and NU wellhead. Spot plug #3 with estimated TOC at surface. SI well. SDFD.
- 7/17/13 Open up well; no pressures. Dig out wellhead. RU High Desert. Perform Hot Work Permit and cut off wellhead. Top of casings at surface. Spot plug #4 and install P&A marker. RD and MOL.

Vic Montoya, MVCI representative, was on location. Jonathan Kelly, NMOCD representative, was on location.