

RECEIVED

Form 3160-5
(August 2007)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB No. 1004-0137
Expires: July 31, 2010

Farmington Field Office
Bureau of Land Management

AUG 22 2013

UNDERTAKING OF SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on page 2.

1. Type of Well <input type="checkbox"/> Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other		5. Lease Serial No. SF-077922
2. Name of Operator Burlington Resources Oil & Gas Company LP		6. If Indian, Allottee or Tribe Name
3a. Address PO Box 4289, Farmington, NM 87499	3b. Phone No. (include area code) (505) 326-9700	7. If Unit of CA/Agreement, Name and/or No.
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Surface Unit B (NWNE), 800' FNL & 1730' FEL, Sec.34, T30N, R12W		8. Well Name and No. McGrath SWD 4
		9. API Well No. 30-045-25923
		10. Field and Pool or Exploratory Area Mesaverde SWD
		11. Country or Parish, State San Juan New Mexico

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA


TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input checked="" type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)


7/12/13 The 4197' packer in procedure is not holding, asked permission to pump plug from 4374' to end of tbg @ 4213'. Called Steve Mason w/ BLM & Charlie Perrin w/ OCD. Both gave verbal approval.
7/16/13 The packer in hole was supposed to shut off water, asked approval to shoot tbg off @ 3896' & set 150' plug on top of it. Called Steve Mason w/ BLM & Charlie Perrin w/ OCD. Both gave verbal approval.
7/19/13 Plug 4&5 need to be combined as there is only 120' between them. Bill Diers on site w/ BLM, Called Brandon Powell w/ Ocd and got verbal approval.
7/19/2013 2nd call. Surface perfs @ 281' PT to 1000#-OK. Tied onto Bradenhead & pumped 5 bbl's water down (145') PT to 500# and test was good. Bill Diers on site w/ BLM wants to perf @ 125', run in tbg and circ to surface inside and in annulus. Called Brando Powell w/ OCD & got verbal approval.

The subject well was P&A'd on 7/25/13 per the above notifications and the attached reports.

RCVD AUG 26 '13
OIL CONS. DIV.
DIST. 3

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)	
Kenny Davis	Title Staff Regulatory Technician
Signature 	Date 8/22/2013

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by 	Title	Date AUG 22 2013
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Office	FARMINGTON FIELD OFFICE

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instruction on page 2)

NMOCDA

216

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979

Farmington, New Mexico 87499

505-325-2627 *fax: 505-325-1211

Burlington Resources

McGrath SWD 4

July 22, 2013

Page 1 of 2

800' FNL and 1730' FEL, Section 34, T-30-N, R-12-W

San Juan County, NM

Lease Number: SF-077922

API #30-045-25923

Plug and Abandonment Report
Notified NMOCD and BLM on 7/8/13

Plug and Abandonment Summary:

- Plug #1** with 40 sxs (47.2 cf) Class B cement inside casing to 4212'. Tag TOC at 3896'.
- Plug #2** with 17 sxs (20.06 cf) Class B cement with 2% CaCl inside casing from 3893' to 3743' disp with 13.8# mud to cover the Mesaverde top.
- Plug #2a** with 23 sxs (27.14 cf) Class B cement inside casing from 3893' to 3690' disp with 13.8# mud to cover the Mesaverde top.
- Plug #2b** with CR at 3485' spot 88 sxs (103.84 cf) Class B cement inside casing with 59 sxs in annulus, 6 sxs below CR, 23 sxs above CR TOC at 3282' to cover the Mesaverde top.
- Plug #3** with CR at 2594' spot 48 sxs (56.64 cf) Class B cement inside casing from 2644' to 2489', 30 sxs in annulus, 6 sxs below CR, 12 sxs above CR TOC at 2489' to cover the Chacra top.
- Plug #4 (original plug #3 and plugs 4&5 combined)** with 49 sxs (57.82 cf) Class B cement inside casing from 1940' to 1508' to cover the Pictured Cliffs, Fruitland Coal tops.
- Plug #6** with 36 sxs (42.48 cf) Class B cement inside casing from 628' to 311' to cover the Kirtland and Ojo Alamo tops.
- Plug #7** with 37 sxs (43.66 cf) Class B cement inside casing from 281' to surface to cover the surface casing shoe.
- Plug #8** with 30 sxs Class B cement top off casings and install P&A marker.

Plugging Work Details:

- 7/10/13 Rode rig equipment to location. Spot in. Bump test H2S equipment. Check well pressures: tubing 600 PSI, casing 160 PSI and bradenhead TSTM. RU relief lines and blow well down. ND wellhead. NU BOP and noticed tubing started blowing. Shut in tubing. Pressured up to 1000 PSI. Attempt to blow well down. Wait on Phoenix. RU Phoenix and retrieve plug in tubing. RIH and set another plug at 4212'. Pressure still at 1000 PSI. Wait on orders. RIH and retrieve plug at 4212'. RIH and set another plug on/off tool at 4198'. Pressure still the same. SI well. SDFD. Note: Procedure change approved BLM/ NMOCD.
- 7/11/13 Bump test H2S equipment. Check well pressures: tubing 1040 PSI, casing and bradenhead 0 PSI. RU relief lines attempt to blow well down. SI well and wait on orders. RU Phoenix and RIH retrieve plug. Pump 80 bbls of water establish a rate of 2 bpm at 1200 PSI, SI tubing. Wait on acid. RU Baker Petrolite. Pump 500 gals acid with 1 bbl flush. RU pump to tubing and pump 24 bbls to spot acid at 2800'. SI tubing. Wait 30 minutes and pump 2 bbls to 3130'. SI well. SDFD.
- 7/12/13 Bump test H2S equipment. Check well pressures: tubing 1040 PSI, casing and bradenhead 0 PSI. Pump 10 bbls flush acid past packer and SI well. RU Phoenix. RIH and set plug at 4212' below packer. POH. Open tubing still flowing. SI pressure at 1040 PSI. Note: Procedure change approved BLM/NMOCD. Spot plug #1a with estimated TOC at 4212'. SI well. SDFD.

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979

Farmington, New Mexico 87499

505-325-2627 *fax: 505-325-1211

Burlington Resources
McGrath SWD 4

July 22, 2013
Page 2 of 2

Plugging Work Details (continued):

- 7/15/13 Bump test H2S equipment. Check well pressures: tubing 420 PSI, casing and bradenhead 0 PSI. RU relief lines tubing blew right down. SI for an hour and 0 PSI. Start mixing gel to VISC at 13.8#. Check pressure on tubing 0 PSI. Attempt to release off packer at 4196' unable to release. Wait on orders to jet cut tubing. SI well. SDFD.
- 7/16/13 Bump test H2S equipment. Open up well; no pressures. RU relief lines. RU Wireline Specialties. Tag TOC at 3896'. Note: Procedure change approved BLM/ NMOCD. RIH and cut tubing at 3893'. Pull tubing hanger. Establish circulation. Pump 60 bbls 13.8# mud. SI casing attempt to pressure test pump 4 bbls no pressure, pulled 1 joint discover need slip grip elevators. Wait on elevators. Regulator broken. SI well. SDFD.
- 7/17/13 Bump test H2S equipment. Open up well; no pressures. Establish circulation. Spot plug #1 with estimated TOC at 3743'. LD 1 joint, 2-6' subs, 2-4' sub, LD 118 joints (119 joints total) EUE 9.3# 3-1/2" at 3893'. Tally 124 joints 2-3/8" tubing, EUE 4.7#, A-Plus tubing. Tag top of 3.5" cut at 3893'. Establish circulation. SI casing attempt to pressure test to 820 PSI bled down to 780 PSI. Spot plug #1a with estimated TOC at 3690'. SI well. SDFD.
- 7/18/13 Bump test H2S equipment. Open up well; no pressures. Tag TOC at 3781'. RIH with 5.5" GR to 1362' unable to get down. Perforate 3 HSC squeeze holes at 3535'. Attempt to get rate, pumped 35 bbls 13.8# mud, no pressure. TIH with 5.5" string mill to 3507'. TIH with 5.5" DHS CR and set at 3485'. Pressure test tubing to 1000 PSI. Reverse circulate with 96 bbls till clean returns. Establish rate of 1.5 bpm at 900 PSI. Pressure test casing to 800 PSI, OK. Spot plug #2 with estimated TOC at 3282'. Reverse circulate from 3254' to 2644'. SI well. SDFD.
- 7/19/13 Bump test H2S equipment. Open up well; no pressures. Perforate 3 HSC squeeze holes at 2644'. Establish rate of 1 bpm at 1100 PSI. TIH with 5.5" DHS CR and set at 2594'. Establish circulation. Spot plug #3 with estimated TOC at 2489'. Reverse circulate 11 bbls from 2470' to 1960'. Establish circulation. Note: Procedure change approved BLM/NMOCD. Spot plug #4 (combined 4&5) with estimated TOC at 1508'. Reverse circulate with 8 bbls from 1471' to 620'. Spot plug #6 with estimated TOC at 311'. Perforate 3 HSC squeeze holes at 281'. Attempt to get circulation pressured up to 1000 PSI. Bradenhead pressured to 500 PSI. Note: Procedure change approved BLM/ NMOCD. Perforate 3 HSC squeeze holes at 125'. Establish circulation. Spot plug #7 with estimated TOC at surface. SI well. SDFD.
- 7/22/13 Bump test H2S equipment. Open up well; no pressures. Tag TOC at 8'. ND BOP and dig out wellhead. RU High Desert. Cut off wellhead. Top off casings. Spot plug #6 and install P&A marker. RD and MOL.

Jim Morris, MVCI representative, was on location.
Bill Diers, BLM representative, was on location.