

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report



Name of Company Burlington Resources, a Wholly Owned Subsidiary of ConocoPhillips Company	Contact Lisa Hunter	
Address 3401 East 30th Street, Farmington, NM 87402	Telephone No. 505-326-9786	
Facility Name Frontier C #1	Facility Type Gas Well	
Surface Owner Federal	Mineral Owner Federal	API No. 3004506585

LOCATION OF RELEASE

Unit Letter D	Section 16	Township 27N	Range 11W	Feet from the 890'	North/South Line North	Feet from the 890'	East/West Line West	County San Juan
-------------------------	----------------------	------------------------	---------------------	------------------------------	----------------------------------	------------------------------	-------------------------------	---------------------------

Latitude 36.57993 Longitude -108.01453

NATURE OF RELEASE

Type of Release Conventional/Produced Water	Volume of Release 8 BBL	Volume Recovered 0 BBL
Source of Release Tank	Date and Hour of Occurrence Unknown	Date and Hour of Discovery 05-21-13 2:00 PM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		RCVD MAY 30 '13
OIL CONS. DIV.		
DIST. 3		
Describe Cause of Problem and Remedial Action Taken.* During maintenance, a small leak was discovered on the welded area that attaches the manway to the tank, causing the release of 8 BBLs of Produced Water, in which zero BBLs were recovered. Leak was plugged and tanker truck call to remove product from tank. Vacuum truck removed remaining product. Spill was contained within the Berm.		
Describe Area Affected and Cleanup Action Taken.* ConocoPhillips will replace tank, and will assess the soils to determine further action, if needed.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Lisa M. Hunter	Approved by Environmental Specialist: 	
Title: Field Environmental Specialist	Approval Date: 9/24/2013	Expiration Date:
E-mail Address: Lisa.Hunter@cop.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: May 28, 2013	Phone: 505-326-9786	

* Attach Additional Sheets If Necessary

NJK 1326748902