Submit 3 Copies To Appropriate District	State of New Me	exico	Form C-103
Office District I	Energy, Minerals and Natu	ral Resources	Jun 19, 2008
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION	DIVISION	30-039-25331
<u>District III</u>	1220 South St. Fran		5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87		STATE FEE S
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, Nivi o	7505	6. State Oil & Gas Lease No. FEE
87505 St. 1 Taniels Dr., Santa Te, 14141			PEE
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			7. Lease Name or Unit Agreement Name San Juan 30-6 Unit
PROPOSALS.)  1. Type of Well: Oil Well ☐ Gas Well ☒ Other <b>P&amp;A</b>			8. Well Number POW 2
2. Name of Operator			9. OGRID Number
Burlington Resources Oil Gas Company LP			14538
3. Address of Operator			10. Pool name or Wildcat
P.O. Box 4289, Farmington, NM 87499-4289			Basin FC
4. Well Location			
Unit Letter <b>C</b> : 1120	feet from the North	line and 1210	feet from the West line
Section 33 Township 30N Range 6W NMPM Rio Arriba County			
11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
to the state of the	6265		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
12. Check Appropriate Box to indicate Nature of Notice, Report of Other Bata			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK			RK $\square$ ALTERING CASING $\square$ $^{1}$
TEMPORARILY ABANDON			ILLING OPNS.□ P AND A 🛛
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐ CASING/CEMENT			T JOB
DOWNHOLE COMMINGLE			
OTHER. ET		OTUED.	
OTHER:   13 Describe proposed or comp	leted operations (Clearly state all	OTHER: L	ad give pertinent dates, including estimated date
			ttach wellbore diagram of proposed completion
6/4/13 Notified Brandon Po	owell/OCD to request permission to	combine Plugs 1&	2 Verbal approval rec'yd
0/4/15 Notified Brandon 1 C	`\	comonic i luga ia	• •
The subject well was P&A'	d on $9/\sqrt{11/13}$ per the notification ab	ove and the attache	RCVD OCT 9'13
			OIL GURD, UIV.
			DIST. 3
Spud Date:	Rig Rele	eased Date:	
DNR O	$\mathcal{N}_{\mathcal{L}}$		
I hereby certify that the information-	above is true and complete to the h	est of my knowleds	ge and belief
Thereby certify that the interplaced	above that and complete to the c	cot of my mile mount	50 mid benem
SIGNATURE TITLE Staff Regulatory Technician DATE 10/9/13			
	_E-mail address:Kenny.r.d	lavis@conocophilli	ps.com PHONE: 505-599-4045
For State Use Only  Deputy Oil & Gas Inspector,			
ADDROVED DV. M.			
APPROVED BY:	TITLE_	Distri	ct #3 DATE 10/15/13
Conditions of Approval (if any):	PY	Approved for	plugging of wellbore only.
		Liability undo	er bond is retained pending
		Receipt of C-1	03 (Subsequent Report of Wall
		Plugging) whi page under fo	ch may be found @ OCD web

www.emnrd.state.us/ocd

Mp

## A-PLUS WELL SERVICE, INC.

P.O. BOX 1979 Farmington, New Mexico 87499 505-325-2627 \*fax: 505-325-1211

Burlington Resources
San Juan 30-6 Unit POW 2

September 11, 2013 Page 1 of 1

1120' FNL and 1210' FWL, Section 33, T-30-N, R-6-W Rio Arriba County, NM Lease Number: FEE API #30-039-25331

Plug and Abandonment Report Notified NMOCD and BLM on 9/6/13

## Plug and Abandonment Summary:

- Plug #1 with 12 sxs (14.16 cf) Class B cement inside casing from 3313' to 3156' to cover the Pictured Cliffs top.
- Plug #2 (combined 2&3) with 26 sxs (30.68 cf) Class B cement inside casing from 3027' to 2742' to cover the Fruitland top.
- Plug #4 with 29 sxs (34.22 cf) Class B cement inside casing from 2530' to 2200' to cover the Ojo Alamo and Kirtland tops.
- Plug #5 with 12 sxs (14.16 cf) Class B cement inside casing from 1092' to 992' to cover the Nacimiento top.
- **Plug #6** with 13 sxs (15.34 cf) Class B cement inside casing from 272' to 172' to cover the surface casing shoe.
- Plug #7 with 28 sxs (33.04 cf) Class B cement inside casing from 50' to surface.
- Plug #8 with 40 sxs Class B cement top off casings and weld on P&A marker.

## **Plugging Work Details:**

- 9/6/13 Rode rig and equipment to location. Spot in. SDFD.
- 9/9/13 Bump test H2S equipment. Check well pressures: casing and bradenhead 0 PSI and tubing 50 PSI. Blow well down. PU on production string, LD tubing hanger and NU BOP. Attempt to release 4.5 AD-1 packer pulled 2 joints, hung up. Work packer free. TOH and tally 2-3/8" tubing 97 joints, LD 1-4.5" AD-1 PKR, 1-Jt tubing, 1 profile nipple, 1 mule shoe. Total 3057'. TIH open-ended to 3313'. Spot plug #1 with estimated TOC at 3156'. Flush tubing with 12 bbls. TIH with 4.5" Select Oil Tool CR and set at 3027'. Pull 10K over string weight load tubing with 10 bbls. Pressure test tubing to 1000 PSI, OK. Circulate well clean. Pressures test casing to 800 PSI, OK. SI well. SDFD.
- 9/10/13 Bump test H2S equipment. Open up well; no pressures. RU Basin Wireline. Ran CBL to surface, estimated TOC at 104'. TIH open-ended to 3027'. Spot plug #2 (combined 2&3), #4, #5 and #6. Perforate 3 HSC holes at 50'. Establish circulation. Spot plug #7 with estimated TOC at surface. SI well. SDFD.
- 9/11/13 Open up well, no pressures. Tag TOC at 10'. "ND BOP. Dig out wellhead. Fill out Hot Work Permit. RU High Desert. Cut off wellhead. Top off casings. Spot plug #8 and weld on P&A marker. RD and MOL.

Josh Jacobs, COPC representative, was on location. John Durham, NMOCD representative, was on location.