

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: BP America Production Company	Contact: Courtney Cochran
Address: 200 Energy Ct. Farmington, NM 87401	Telephone No.: 505-326-9457
Facility Name: Florance O 20	Facility Type: Natural Gas Well

Surface Owner: Federal	Mineral Owner: Federal	API No.: 3004509376
------------------------	------------------------	---------------------

LOCATION OF RELEASE

Unit Letter B	Section 24	Township 30N	Range 09W	Feet from the 990	North/South Line North	Feet from the 1650	East/West Line East	County: San Juan
------------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	------------------

Latitude 36.8012 Longitude 107.72802

NATURE OF RELEASE

Type of Release: Produced Water & Condensate	Volume of Release: 85 bbls Produced Water & Condensate	Volume Recovered: 53 bbls Condensate
Source of Release: Drilled Ball Valve on Production Tank	Date and Hour of Occurrence: 10/2/2013 4:00 pm	Date and Hour of Discovery: 10/2/2013 4:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Brandon Powell - NMOCD; Shari Ketcham - BLM	
By Whom? Courtney Cochran - BP	Date and Hour: 10/3/2013 8:00 am	RCVD OCT 18 '13 Revised
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. OIL CONS. DIV. DIST. 3	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

Truck driver was on location to pull water off production tank to ready tank for sale. During the removal of the bull plug the drain valve was not backed up with a second pipe wrench causing the end cap of the ball valve to unscrew allowing the valve to separate and empty the tank into the steel ring containment area. Truck driver was able to recover 53 bbls of condensate from secondary containment area.

Describe Area Affected and Cleanup Action Taken.*

Unrecovered produced water and condensate soaked into the ground within the secondary containment area. A small amount of condensate did seep underneath the steel ring and run down the fill of the Florance O 20 and onto the pad of the Florance 112. No fluid left lease. Initial investigation to determine extent of impacts will begin on 10/7/2013 to allow for benzene in the air to dissipate.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Courtney Cochran		Approved by Environmental Specialist: 	
Title: Field Environmental Advisor		Approval Date: <u>10/22/2013</u>	Expiration Date:
E-mail Address: <u>Courtney.Cochran@bp.com</u>		Conditions of Approval:	
Date: 10/17/2013 Phone: 505-326-9457		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

nJK1329539679