

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

☒ Initial Report ☐ Final Report

Name of Company Great Western Drilling Co.	Contact Cullan Keller
Address 115W. Aztec Blvd. #203. Aztec N.M. 87401	Telephone No. 505-320-8504
Facility Name Callow Fed. 1 G	Facility Type Tank Battery

Surface Owner Bolack Ranch	Mineral Owner Fee	API No. 30-045-32164
----------------------------	-------------------	----------------------

**LOCATION OF RELEASE**

Unit Letter O	Section 33	Township 29-N	Range 13-W	Feet from the	North/South Line	Feet from the	East/West Line	County San Juan
------------------	---------------	------------------	---------------	---------------	------------------	---------------	----------------	-----------------

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release Pipeline leak	Volume of Release 1BBL oil- 1BBL water	Volume Recovered 0
Source of Release Pipeline	Date and Hour of Occurrence 9- 21-13	Date and Hour of Discovery 9-21-13 3:00pm
Was Immediate Notice Given? Required <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not	If YES, To Whom? Jonathan Kelly-OCD, Mark Kelly-BLM, Tommy Bolack- land owner	
By Whom? Cullan Keller	Date and Hour 9-23-13, 8:00am	
Was a Watercourse Reached? <input type="checkbox"/> X Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse. Less than 1/2 BBL	

RCVD OCT 3 '13

If a Watercourse was Impacted, Describe Fully.\*  
The oil and water ran about 40 ft. down a dry wash next to the leak.

OIL CONS. DIV.  
DIST. 3



**Describe Cause of Problem and Remedial Action Taken.\***

The flowline running from the well head to the separator, which is about half a mile long, sprung a leak. The well head and separator were shut in and blown down.

**Describe Area Affected and Cleanup Action Taken.\***

The oil and water ran about 40 ft. down a dry wash running next to the flow line. The oil and contaminated soil were removed and Envirotech sampled the area. Most of the area passed, one section of sandstone did not. We raked the sandstone with the backhoe and left to air out until we fix the pipeline. We will test again when we dig up flowline to fix leak.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Cullan Keller	Approved by Environmental Specialist: 	
Title: Asst. Forman	Approval Date: 10/23/2013	Expiration Date:
E-mail Address: cullank2002@gmail.com	Conditions of Approval:	Attached <input type="checkbox"/>

WJ2132965530