Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB NO. 1004-0135
Expires: July 31, 2016

5. Lease Serial No. NMSF078385

SUNDRY	NMSF078385	NMSF078385							
Do not use thi abandoned wel	6. If Indian, Allottee or Tribe Name								
SUBMIT IN TRI	7. If Unit or CA/Agree	7. If Unit or CA/Agreement, Name and/or No.							
Type of Well Oil Well	er			8. Well Name and No. FLORANCE P 39					
Name of Operator BP AMERICA PRODUCTION	Contact: CO. E-Mail:.Toya.Colvir	N		9. API Well No. 30-045-09034-00-D1					
3a. Address 501 WESTLAKE PARK BLVD HOUSTON, TX 77079	(include area c 6-7148	ode)	10. Field and Pool, or Exploratory BASIN DAKOTA BLANCO MESAVERDE						
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description)			11. County or Parish, a	nd Sta	te .			
Sec 35 T30N R8W NWNE 099 36.772949 N Lat, 107.641129				SAN JUAN COUNTY, NM					
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA									
TYPE OF SUBMISSION				TYPE OF ACTION					
☐ Notice of Intent	☐ Acidize	Deep	Deepen Pro		uction (Start/Resume)	tion (Start/Resume)			
_	☐ Alter Casing	☐ Fract	ture Treat	☐ Recla	amation	nation ` 🗆 W			
Subsequent Report Subsequent Re	☐ Casing Repair	☐ New	Construction	☐ Reco	mplete		Other		
☐ Final Abandonment Notice	☐ Change Plans	□ Plug	and Abandon	□ Temp	oorarily Abandon				
a p	☐ Convert to Injection	Plug	Back	□ Wate	r Disposal				
Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed with following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shalt testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the determined that the site is ready for final inspection.) BP America Production Company would like to submit the plug back and swab operation summaries for the subject well. Please see attached document. RCVD JAN 28 DIST. 3									
14. I hereby certify that the foregoing is		T							
Electronic Submission #232893 verified by the BLM Well Information System For BP AMERICA PRODUCTION CO., sent to the Farmington Committed to AFMSS for processing by STEVE MASON on 01/24/2014 (14SXM0592SE)									
Name (Printed/Typed) TOYA CO	LVIN		Title REC	SULATORY A	NALYST				
Signature (Electronic S	Submission)		Date 01/2	3/2014					
THIS SPACE FOR FEDERAL OR STATE OFFICE USE									
Approved By ACCEPT		STEPH TitlePETRO	IEN MASON DLEUM ENG	INEER	·	Date 01/24/2014			
Conditions of approval, if any, are attache certify that the applicant holds legal or equivalent would entitle the applicant to conductive the conductive transfer or conductive transf	Office Farm	nington							
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.									

Plugging & Swab Operations for the Florance P 39 - April 2013- October 2013

April 2013

04/29/2013- BLOW WELL DOWN, RIG UP, KILL TBG, N/D WELLHEAD, , INSTALL H SUB WITH PRETESTED TWC, N/UP WELL CONTROL EQUIPMENT, TEST WELL CONTROL EQUIPMENT, TRY TO PULL HANGER TO RIG FLOOR, WORK FOR AWHILE THEN SHUT DOWN

04/30/2013- CHANGE OUT TO N-80, PULLED HANGER FREE AT 70K, TEST WIRELINE SPECIALITIES WELL CONTROL EQUIPMENT, TAGGED CW CHOKE @ 5033', RIG DOWN WIRELINE EQUIPMENT, SHUT DOWN

May 2013

05/01/2013- CUT TBG. IN TWO @ 5020', POH STANDING BACK, TUBING CHANGED FROM EUE TO BUTTRESS AFTER 66 STANDS, WE HAVE 16 STANDS OF BUTTRESS, SHUT DOWN SECURE WELL

05/02/2013- RIH WITH OVER SHOT/JARRING ASSEMBLY, JAR SEAL ASSEMBLY OUT OF BAKER PACKER, POH L/D USED PRODUCTION TUBING, RECOVERED BAKER PACKER SEAL ASSEMBLY, SECURE WELL, SHUT DOWN

05/03/2013- CHANGE OUT TBG. TRAILERS, RIH WITH PACKER PICKER/MILL AND P/UP TBG. RUN TO 7000', THEN PULL 100' ABOVE PERFORATIONS WITH MILL, TEST AIR UNIT LINES- GOOD TEST, PUMP AIR MIST AROUND AT 4450', WELLBORE IS UNLOADED WITH AIR

05/06/2013- RIH WITH MILL, R/UP POWER SWIVEL, BREAK CIRCULATION WITH AIR MIST, PLUCK PACKER, START MILLING UP BAKER PACKER, POH ABOVE MV PERFORATIONS, SHUT DOWN

05/07/2013- POH, CALL WIE, RIH WITH PACKER PICKER/MILLING BHA, RIG UP POWER SWIVEL, AIR MIST ESTABLISH CIRCULATION, MILL ON BAKER PACKER 3 HRS., L/D 2-JOINTS, SECURE WELL

05/08/2013- MAKE 2 CONNECTIONS WITH POWER SWIVEL, ESTABLISH AIR MIST CIRCULATION, MILLING OPERATIONS ON BAKER PACKER, CLEAN UP WELL, R/D SWIVEL, POH SHUT DOWN

05/09/2013- FINISH POH WITH PERMANENT BAKER PACKER, ROUND TRIP BIT AND SCRAPER TO 7087', LAND HANGER W/TWC,TEST WELL CONTROL EQUIPMENT-PASSED, PULL HANGER, FINISH POH, SECURE WELL

05/13/2013- PUMP 2% KCL TO RELEASE RETREIVABLE PACKER, POH PACKER ABOVE MV PERFORATIONS AND ALLOW TO RELAX, RIH AND TEST PACKER INTEGRITY, PACKER FAILED INTEGRITY TEST, POH, RIH WITH TENSION PACKER AND UNLOADER, PUMP 30 BBLS. 2% KCL DOWN THE TBG., SET TENSION PACKER, SHUT DOWN SECURE WELL

05/14/2013- RIH AND TEST TENSION PACKER INTEGRITY RIGHT ABOVE CIBP, GOOD TEST, FOUND HOLE HUNT HOLE, FOUND OUT HOLE IS ABOVE 6553', PULL PACKER ABOVE MV PERFORATIONS, SHUT DOWN SECURE WELL

05/15/2013- POH WITH TENSION PACKER, RIG E-LINE, TEST WELL CONTROL EQUIPMENT, LOST TOOLS IN THE HOLE, N/D ANNULAR, N/UP FRAC VALVE, LAND HANGER WITH TWC, TEST FRAC VALVE, PULL HANGER WITH TWC, SHUT DOWN

05/16/2013- RU WEATHERFORD WIRELINE LUBRICATOR AND EQUIPMENT, PRESSURE TEST LUBRICATOR-PASSED, RIH WITH SBL LOGS, LOG FROM 7026' - 5100', POOH RD WIRELINE, SEND LOG TO BLM & NMOCD, WAIT ON ORDERS FROM WIE & APPROVALS FROM BLM & NMOCD, RIH WITH OPEN ENDED TBG TO 7016', SHUT DOWN SECURE WELL

05/17/2013- RU BAKER HUGHES CEMENTERS, PUMP PLUG FROM 7016'-6272' W/12.3 BBLS G-CLASS YIELD 1.37 14.6 PPG CMT, POOH W/ TBG TO 5034', PUMP 20 BBL 2% KCL DOWN TBG, PUMP 20 BBL 2% KCL DOWN CSG, POOH TBG STRING, MU AND RIH W/ TENSION PACKER TO 4440', SHUT DOWN SECURE WELL AND EQUIPMENT

05/20/2013- RIH AND TAG CEMENT TOP @6272', SET TENSION PACKER @ 5168', TEST UNSUCCESSFUL, SET @ 5766', TEST UNSUCCESSFUL, SET PACKER @ 6018, TEST UNSUCCESSFUL, SET PACKER @ 6238', TEST UNSUCCESSFUL, POH WITH TENSION PACKER, SHUT DOWN SECURE WELL

05/21/2013- ROUND TRIP 4.5" BIT AND SCRAPER, ROUND TRIP TAPPERED MILL, IN-LINE MILLS, YO-YO THRU CASING BAD SPOTS, POH WITH MILLS, SHUT DOWN SECURE WELL

05/22/2013- RIH WITH HD COMPRESSION PACKER @6235', POH TO 4409', SET PACKER AND TEST CSG. ABOVE MV PERFORATION, GOOD MIT TEST, UNSET PACKER, SHUT DOWN SECURE WELL

05/23/2013- POH WITH PACKER, SET HANGER/TWC, TEST WELL CONTROL EQUIPMENT, PULL HANGER/TWC, FOUND CSG LEAK FROM 6238'-6272', RIH OPEN ENDED TO 6236', SHUT DOWN SECURE WELL, NOTIFY BLM STEPHEN MASON AND NMOCD BRANDON POWELL FOR PLAN FORWARD.

05/24/2013- WITH BLM & NMOCD APPROVALS, PUMP CEMENT BALANCE PLUG FROM 6238'-5526' W/62 SXS G-CLASS YIELD 1.37 14.60PPG CEMENT, POH, N/D FRAC VALVE, LOWER OPERATOR STAND, SHUT DOWN SECURE WELL

05/28/2013- RUN BIT AND SCRAPER, TAG CEMENT TOP @ 5526', POH, RIH WITH 3-7/8" BIT, FOUND CEMENT TAG CEMENT @ 4525', R/UP POWER SWIVEL, R/D, SHUT DOWN

05/29/2013- TEST AIR UNIT LINES, AIR MIST CLEAN OUT FROM 4525' TO 5223', SHUT DOWN SECURE WELL

05/30/2013- DRILL OUT CEMENT TO 4450', R/D SWIVEL, POH, RIH BIT AND SCRAPER TO CEMENT TOP, POH, SPOT ACID JOB, PUMP 3 BBLS OF 2% KCL, 800 GALLONS OF 15% ACID WITH CORROSION INHIBITOR, 3-BBLS OF FLUSH, R/D POH WITH 32 STANDS, SHUT DOWN SECURE WELL

05/31/2013- RIH WITH PACKER AND MIT TEST CASING, SUCCESSFUL TEST @5460" NMOCD ON SITE TO WITNESS MIT, POH WITH PACKER, SHUT DOWN SECURE WELL, MOVE OFF LOCATION

June 2013

06/03/2013- TRAINING

06/04/2013- TRAINING

06/05/2013- RIH, LAND 2 3/8" 4.7# J-55 TUBING @ 5000', N/D, N/UP, HOOK UP FLOWLINE, R/D, MOVE OFF LOCATION

06/06/2013- REVIEWED SAFETY INFORMATION AND HITRA WHILE WAITING, MOVE SWAB UNIT ONTO LOCATION, INSPECTED LOCATION IDENTIFIED NEED FOR FLOWBACK LINE AND TANK, RU SWAB UNIT, SHUT DOWN

06/07/2013- MADE 11 SWAB RUNS TOTAL, RECOVERED LITTLE GAS, SHUT DOWN SECURE WELL.

06/10/2013- INSPECT WELL AND EQUIPMENT, SWAB WELL, POOH, RD SWAB UNIT, MOVED SWAB UNIT TO THE YARD FOR REPAIRS

06/11/2013- MOVE PIT AND WSL TRAILER OFF LOCATION

September 2013

09/19/2013- MOVE ONTO LOCATION, RIG UP PUMP EQUIPMENT VALVE ALIGNMENT BAKER PSI TEST PUMP & LINE, VALVE ALIGNMENT, PUMP JOB PUMP 6 BBLS 15% HCL DOWN TUBING AND 6 BBLS 15% HCL DOWN CASING, FLUSH WITH 60BBLS 2% KCL DOWN TUBING AND CASING, R/D PUMP EQUIP, SHUT DOWN SECURE WEIL

09/26/2013- RU SWAB UNIT, PRESSURE TEST WELL CONTROL EQUIPMENT- PASSED, RIH AND MAKE 1 GAUGE RING RUN 2 SWAB RUNS, SECURE WELL AND EQUIPMENT

09/27/2013- MADE 10 SWAB RUNS, FLOWED WELL 30-60 MIN BETWEEN RUNS FOR FLUID ENTRY, SI WELL, LAYED DERRICK DOWN. SHUT DOWN SECURE WELL

09/30/2013- SWAB UNIT SHUT DOWN, CREW IN TRAINING

October 2013

10/01/2013- TRAINING

10/02/2013- TRAINING

10/03/2012- MIRU SWAB UNIT, RIH AND MAKE 6 SWAB RUNS, NO CHANGE IN THE TBG FLOWING RATE, SHUT DOWN MOVE OFF LOCATION